Original CR

Metro Phoenix Auto Auction
2475 S. 59th Avenue
Phoenix, AZ 85043
602-279-9500
remst@metroaa.com
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2002 INTERN 2000 SERIES 2574**
Bodystyle/Series:	**?CC? -**
Color:	**WHITE**
Mileage:	**1,035 (Exempt, 6 digits)**
Turn-in Mileage:	**-**
VIN:	**1HTGEATR22H525200**
Work Order/ Stock Number:	**000478370**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Room 3400 Washington, DC 20405 816-823-3358 linda.betlock@gsa.gov
Client Stock #:	**G820327H**
Vehicle Grade	**Grade 2.0**
Remarks:	**-**
Announcements:	• FRAME DAMAGE WELDED REAR RAILS • AS IS:NO ARB ON FRM
Certification :	**Not Certified**
Req. Prev. Repair Order:	**-**

Drivable: Yes	Tire Rating: null	Incremental Recon: No

UniBody/Frame Damage: NO

Equipment

Transmission:	**Six Speed Manual Transmission**	A/C:	**Yes**
Engine:	**6-Cylinder Diesel**	Cruise Control:	**Yes**
Engine Size:	**0 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**No**
Radio:	**AM/FM CD**	Pwr Windows	**No**
Interior - Type/Color:	**Leather Interior /Brown**	Rear Defroster:	**No**
Airbag:	**-**	Tilt Steering:	**No**
Seats:	**Bench**	Drive Type:	**Rear Wheel Drive**
Seat Count:	**0**	Brakes:	**-**

Additional Equipment:

Air Conditioning	LF Tires - 16/32 inch	RF Tires - 16/32 inch

LR Tires - 16/32 inch	RR Tires - 16/32 inch	Car Tire Size - LR SIDE TIRE SIZE 22.5
Car Tire Size - RR SIDE TIRE SIZE 22.5	Car Tire Size - LF SIDE TIRE SIZE 22.5	Car Tire Size - RF SIDE TIRE SIZE 22.5
Tire Brand - Front Left - LF SIDE TIRE MFG Bridgestone B	Tire Brand - Front Right - RF SIDE TIRE MFG Bridgestone B	Tire Brand - Rear Left - LR SIDE TIRE MFG BFGoodrich BF
Tire Brand - Rear Right - RR SIDE TIRE MFG Goodyear Good	Two-Wheel Drive	CD in Dash
Power Steering	Cruise Control	

Non Chargeable Damages

Photo	Item	Damage	Comments	Parts	Labor	Labor Hours	Paint Hours	Estimate	Action	Severity
	Photo - Rear	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Wheel	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Interior	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Right	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Rear	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Extra Photo 1	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Right	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown

[no photo]	Photo - Interior	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Left	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
				$0.00 (total)	**$0.00 (total)**	**0 (total)**	**0 (total)**	**$0.00 (total)**		

Chargeable Damages

Photo	Item	Damage	Comments	Parts	Labor	Labor Hours	Paint Hours	Estimate	Action	Severity
	Front Bumper	Unknown	IN CARGO	$0.00	$85.00	0	0	$85.00	Report	0
[no photo]	Hood	Chipped	TOUCHUP	$0.00	$55.00	0	0	$55.00	Report	0
	Cargo Box	Heavy Scratch	PAINT	$0.00	$600.00	0	0	$600.00	Report	0
				$0.00 (total)	**$740.00 (total)**	**0 (total)**	**0 (total)**	**$740.00 (total)**		

File Insurance Claim? No

Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.