

Recalls Results by VIN - Vehicle Identification Number

Print **VIN:** 2C3CA4CG6BH611390**Year:** 2011 **Make:** CHRYSLER **Model:** 300**Number of Open Recalls:** 2**NHTSA Recall Number:** [14V-634](#)**Recall Date:** December 1, 2014**Manufacturer Recall Number:** P60**SUMMARY:**

THE ALTERNATOR DIODES IN YOUR VEHICLE MAY EXPERIENCE A RAPID FAILURE. VARIABILITY IN THE FAILURE MODE RANGES FROM NO OUTPUT, REDUCED OUTPUT, AND/OR A FULLY SHORTED TO GROUND CONDITION. DEPENDING ON THE ALTERNATOR FAILURE MODE AND TIMING, VEHICLE ELECTRICAL SYSTEM VOLTAGE MAY DROP TO CRITICAL LEVELS, DISABLING SYSTEMS SUCH AS ANTILOCK BRAKE SYSTEM (ABS), ELECTRONIC STABILITY CONTROL (ESC), ELECTRONIC CONTROL MODULE (ECM), AND/OR THE CENTRAL BODY CONTROLLER (CBC).

SAFETY RISK:

THE DRIVER WILL HAVE LIMITED OR NO DETECTION OF THE ALTERNATOR FAILING, WHICH CAN RESULT IN VEHICLE SHUTDOWN WHILE DRIVING AND/OR AN UNDERHOOD ELECTRICAL FIRE.

REMEDY:

THE ALTERNATOR ASSEMBLY MUST BE REPLACED.

RECALL STATUS: Recall **INCOMPLETE****MANUFACTURER NOTES:**

For more information, visit recalls.mopar.com or call 1-800-853-1403. Please have your VIN ready when calling.

[Find a Dealer Near You](#)

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

*THIS RECALL DATA LAST REFRESHED: Oct 20, 2016***NHTSA Recall Number:** [16V-352](#)**Recall Date:** July 1, 2016**Manufacturer Recall Number:** S43**SUMMARY:**

THE FRONT PASSENGER AIRBAG INFLATOR HOUSING MAY RUPTURE WHILE DEPLOYING DURING A CRASH. THE POTENTIAL FOR SUCH RUPTURES MAY OCCUR IN SOME OF THE SUBJECT AIRBAG INFLATORS AFTER SEVERAL YEARS OF EXPOSURE TO PERSISTENT CONDITIONS OF HIGH ABSOLUTE HUMIDITY AND/OR HEAT AGING.

SAFETY RISK:

IN THE EVENT OF A FRONT PASSENGER AIRBAG INFLATOR RUPTURE, METAL FRAGMENT(S) COULD PASS THROUGH THE AIRBAG CUSHION MATERIAL, WHICH MAY RESULT IN ADDITIONAL INJURY OR DEATH TO VEHICLE OCCUPANTS.

REMEDY:

THE PASSENGER AIRBAG INFLATOR MUST BE REPLACED.

RECALL STATUS: Recall **INCOMPLETE. Remedy not yet available**

MANUFACTURER NOTES:

For more information, visit recalls.mopar.com or call 1-800-853-1403. Please have your VIN ready when calling.

[Find a Dealer Near You](#)



If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

THIS RECALL DATA LAST REFRESHED: Oct 20, 2016

Additional Safety Information

Besides the VIN search tool you just used, NHTSA offers additional safety information based on a vehicle's make, model, and model year and not tied to any particular VIN. A search by vehicle make, model, and model year gives you access to information about technical service bulletins, NHTSA investigations, and owner complaints, as well as safety recalls on aftermarket equipment that is often not linked to a particular VIN or even to your vehicle's manufacturer.

To search NHTSA's safety information based on your vehicle's make, model, and model year, please go to the [Safety Issues section](#) and follow the instructions there.

Recall information for this manufacturer is only available going back to January 01, 1990. If your vehicle was manufactured before this date, please contact the manufacturer for possible additional recall information.

 Enter another VIN here:

I'm not a robot reCAPTCHA
[Privacy](#) - [Terms](#)

Submit