

## Recalls Results by VIN - Vehicle Identification Number

[Print](#) **VIN:** 1YVHP81B795M50932**Year:** 2009 **Make:** MAZDA MOTOR CORP **Model:** MZ6 SSP A**Number of Open Recalls:** 2**NHTSA Recall Number:** [13V425000](#)**Recall Date:** September 24, 2013**Manufacturer Recall Number:** 70131**SUMMARY:**

Mazda6 Door Latch Mounting Screws. The door latch mounting screws may become loose. If all three door latch mounting screws become loose and fall out, the door latch mechanism will not engage when the door is closed, and the door ajar warning light will illuminate.

**SAFETY RISK:**

If the warning light goes unnoticed and the vehicle is driven, the door might open while the vehicle is in motion, increasing the risk of accident or injury.

**REMEDY:**

The dealer will remove the door latch mounting screws on all doors, replace any missing screws, apply a thread locking adhesive, and re-tighten the screws, free of charge.

**RECALL STATUS:** Recall **INCOMPLETE****MANUFACTURER NOTES:**

To locate your nearest Mazda dealer, visit our website and use our "Locate a Dealer" feature at [www.MazdaUSA.com](http://www.MazdaUSA.com).

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

*THIS RECALL DATA LAST REFRESHED: Oct 26, 2016***NHTSA Recall Number:** [16V-356](#)**Recall Date:** May 25, 2016**Manufacturer Recall Number:** 9516E**SUMMARY:**

Continued exposure to high levels of absolute humidity may cause the air bag inflator housing to rupture and deploy abnormally in the event of a crash necessitating deployment of the passenger side frontal air bag.

**SAFETY RISK:**

An inflator rupture may result in metal fragments striking the vehicle occupants, resulting in serious injury or death.

**REMEDY:**

Dealers will replace the passenger side frontal air bag inflator, free of charge.

**RECALL STATUS:** Recall **INCOMPLETE****MANUFACTURER NOTES:**

If you have any questions regarding this program, please contact our Customer Experience Center at (800) 222-5500, option #6.

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

*THIS RECALL DATA LAST REFRESHED: Oct 26, 2016*

### Additional Safety Information

Besides the VIN search tool you just used, NHTSA offers additional safety information based on a vehicle's make, model, and model year and not tied to any particular VIN. A search by vehicle make, model, and model year gives you access to information about technical service bulletins, NHTSA investigations, and owner complaints, as well as safety recalls on aftermarket equipment that is often not linked to a particular VIN or even to your vehicle's manufacturer.

To search NHTSA's safety information based on your vehicle's make, model, and model year, please go to the [Safety Issues section](#) and follow the instructions there.

Recall information for this manufacturer is only available going back to January 01, 1999. If your vehicle was manufactured before this date, please contact the manufacturer for possible additional recall information.

 Enter another VIN here:

I'm not a robot

reCAPTCHA  
[Privacy](#) - [Terms](#)

**Submit**