

# Excess Justification Report

## For Excess Lot

### FY15-035

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0001	061-326-0	N/A	TIRE, 17.5X6.25-6TT	1	4	Four new tires have a 8130 dated 1/25/08 from Michelin Aircraft Tire Co.
0002	650C06-3	N/A	TIRE, NOSE, 160MPH, 10 PLY	1	1	New tire Goodyear Flight Custom III 6.50-10. Purchased 11/12/08.
0003	1013-42-011 SERIES 23.1	880	Fms Control Head, Uns IM Nms	4	1	Has an 8130 Inspected by Mfg. Universal Avionics Systems Corp. dated 3/28/12. Removed from a King Air, CPU fail code, could not duplicate squawk. Work order report included.
0004	1U367-232-2	T9566B	Attitude Gyro	4	1	Has 8130 dated 7/11/06. Overhauled by Sigma Tek Inc. Service repair work order included.
0005	229-0324-020	2370	Accelerometer	4	1	Has an 8130 dated 12/11/13. Inspected by Avionic Specialist, Mfg. Columbia Research Labs
0006	270-0930-010	272856	Yaw Rate Sensor	4	1	Has 8130 dated 7/24/09. Inspected/tested by Mfg. Rockwell Collins. Tested ok - no defects.
0007	270-0930-010	3265082	Yaw Rate Sensor	4	1	Has 8130 dated 3/19/07. Overhauled by Rockwell Collins, service memo report included.
0008	501-1228-04	81897	Emergency Power Supply	4	1	Has an 8130 dated 5/14/14. Inspected by Masco, service report included.
0009	622-5027-001	2396	Actuator, Servo Elevator SV085B	4	1	Has an 8130 dated 9/2/11. Repaired by Aero Technology, work order report included. Mfg. Collins General Aviation
0010	622-5029-002	19HN	Mount, Servo SMT-65	1	1	New in Mfg. Rockwell Collins box. Has C of C dated 11/16/99.
0011	622-5734-002	6432	Primary Trim Servo	4	1	Has an 8130 dated 8/16/13. Overhauled by Avionic Specialist Inc. Tear down report included. Mfg. Collins
0012	622-5734-002	6433	Primary Trim Servo	4	1	Has serviceable tag dated 10/5/99. Recertified by IEC International Inc. Work order report included. Mfg. Collins
0013	622-5735-002	1436	Mount, Servo SMT-65	4	1	Has a 8130 dated 1/13/99. Repaired by Capital Avionics, replaced bearings, service report included. Mfg. Collins
0014	622-5735-002	5550	Mount, Servo Smt-65	4	1	Has a 8130 dated 11/12/98. Repaired by Mfg. Collins Commercial Avionics, service memo included.
0015	622-5735-002	5107	Mount, Servo Smt-65	4	1	Has a 8130 dated 7/13/99. Repaired by Capital Avionics Inc. Service report included. Mfg. Collins Avionics Div.
0016	622-5812-001	32179	Detector, Flux, Fdu-70	4	1	Has a 8130 dated 3/16/12. Repaired by Southwest Instruments. Mfg. Collins
0017	622-6019-001	1260	Slip/Skid Sensor	4	1	Has a 8130 dated 4/10/08. Inspected by Triumph Instruments, work order report included. Mfg. Collins General Aviation
0018	622-6019-001	26KVY	Slip/Skid Sensor	1	1	New part has a 8130 and C of C from Rockwell Collins dated 10/11/06.
0019	622-6135-014	3978	Control Compensation Unit	4	1	Has a 8130 dated 7/29/11. Repaired by Pacific Southwest Instruments, work order report included. Mfg. Collins
0020	622-6199-001	202	HSI Processor Unit, Hpu-74	4	1	Has a 8130 dated 1/3/12. Repaired by Duncan Aviation, work order report listed on 8130. Mfg. Collins
0021	622-6521-016	4403	Nav Control	4	1	Has a 8130 dated 8/17/11. Repaired by AV Group Inc., tear down report included. Mfg. Collins
0022	622-7876-011	2211	Multifunction Display	4	1	Has a 8130 dated 8/9/13. Tested by Millennium International. Mfg. Collins.

**Excess Justification Report**  
**For Excess Lot**  
**FY15-035**

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0023	622-8678-008	6960	Display Processor Unit, DPU-85N	4	1	Has a 8130 dated 2/8/12, Repaired by Mfg. Rockwell Collins, service memo included.
0024	MD41-1208	E04-11545	EGPWS Control/Indicator	4	1	Has a 8130 dated 7/28/11. Repaired by Mfg. Mld Continent Instrument Co. Work order report included.
0025	265F86-8		Tire, Nose, 160mph, 8 Ply	1	1	New tire has Goodyear label. Flight Custom III 22X6.75-10 Purchased 1/19/11.
0026	101450-11952	158931	Altimeter	4	1	Has a 8130 dated 6/25/12. Overhauled by AeroMach Labs, work order report included. Date of Mfg stamped on part 1/28/98. Mfg. AeroSonic Corp.
0027	130-380042-5	178U	Torque Indicator	4	1	Has a 8130 dated 8/7/13. Overhauled by Aero-Mach Labs Inc. Test data & work order report included. Mfg. Meggitt Avionics
0028	1U367-232-2	T10170D	Attitude Gyro	4	1	Has a 8130 dated 8/8/11. Overhauled by Aviation Plus Inc. Work order report included. Mfg. Beechcraft
0029	270-0930-010	3167-117	Yaw Rate Sensor	4	1	Has a 8130 dated 5/28/10. Overhauled by Mfg. Rockwell Collins, service memo & c of c with test report included.
0030	438	115	Audio Control Amplifier	4	1	Has a 8130 dated 9/9/11. Repaired by Chelton Avionics Inc. Mfg. DB Systems Inc.
0031	622-4565-001	2227	Gyro	4	1	Has a 8130 dated 12/2/11. Repaired by Aerospace Instruments Support Inc. Work order report included. Mfg. Collins
0032	622-4938-007	9615	RMI	4	1	Has a 8130 dated 4/10/08. Inspected by Aerospace Instrument Support. Work order report included. Mfg. Collins
0033	622-4938-007	G8CH	RMI	4	1	Has a 8130 dated 6/12/08. Repaired by Aerospace Instrument Support. Work order report included. Mfg. Collins
0034	622-4938-007	9772	RMI	4	1	Has ID tag dated 7/14/09, Removed from a King Air in serviceable condition. Mfg. Collins
0035	622-4938-007	9994	RMI	4	1	Has a ID tag dated 9/24/09. Removed from a King Air in serviceable condition. Mfg. Collins
0036	622-5735-002	592	Mount, Servo Smt-65	4	1	Has a 8130 dated 4/1/98. Bench checked by Capital Avionics Inc. Service work order report included. Mfg. Collins Aviation Div.
0037	622-5735-002	4352	Mount, Servo Smt-65	4	1	Has a 8130 dated 4/1/98. Bench checked by Capital Avionics Inc. Service report included. Mfg. Collins Avionics Div.
0038	622-5735-002	1435	Mount, Servo Smt-65	4	1	Has a 8130 dated 1/13/99. Repaired by Capital Avionics Inc. Service report included. Mfg. Collins Avionics Div.
0039	622-5798-008	2500	Flight Control Panel Fcp-65	4	1	Has a 8130 dated 7/22/13. Overhauled by Capital Avionics Inc. Tear down report included. Mfg. Collins General Aviation Div.
0040	622-5798-008	20T3	Flight Control Panel Fcp-65	4	1	Has a 8130 dated 7/24/13. Overhauled by Capital Avionics Inc. Tear down report included. Mfg. Collins General Aviation Div.
0041	622-6020-021	5664	Electronic Flight Display/ Pilots Side	4	1	Has a 8130 dated 3/18/13. Tested by Hawker Beechcraft. Mfg Collins
0042	622-6020-021	5668	Electronic Flight Display/ Pilots Side	4	1	Has a 8130 dated 3/18/13. Tested by Hawker Beechcraft. Mfg. Collins
0043	622-6020-021	2896	Electronic Flight Display/ Pilots Side	4	1	Has a 8130 dated 7/3/12. Overhauled by Mfg. Rockwell Collins.

**Excess Justification Report**  
**For Excess Lot**  
**FY15-035**

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0044	622-6020-021	5974	Electronic Flight Display/ Pilots Side	4	1	Has a 8130 dated 3/3/13. Tested by Hawker Beechcraft. Mfg. Collins
0045	622-6684-005	1782	Autopilot Control Panel	4	1	Has a 8130 dated 8/2/13. Overhauled by Pacific Southwest Instrument. Work order report included. Mfg. Collins
0046	622-6899-001	467	Course Heading Panel	4	1	Has a 8130 dated 6/4/12. Overhauled by L3 Communications Avionic System. Tear down report included. Mfg. Collins
0047	622-7876-011	2191	Multifunction Display, MFD-85B	4	1	Has a 8130 dated 12/28/12. Tested by Hawker Beechcraft. Mfg. Collins
0048	622-9785-032	2878	Auto Computer	4	1	Has a 8130 dated 8/23/13. Repaired by Capitol Avionics, tear down report included. Mfg. Collins
0049	PC-17A	9569A	Static Inverter-LH Reference Designator NO.: Ps111	4	1	Has a 8130 dated 12/13/11. Overhauled by Ametek B & S Aircraft. Mfg. Marathon Power Technologies
0050	101-8026-1	2372	NOSE WHEEL TIRE ASSY, KING AIR	4	1	Has Serviceable tag dated 7/29/14. Wheel balanced and repacked bearings . Mfg. Cleveland
					53	