

# Excess Justification Report

## For Excess Lot

### FY15-048

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0001	069-1025-27	48112	Transceiver, KX165, Cond. 7	7	1	Removed from a Cessna 206 on 5/29/15. #2 CDI inop. Mfg. Bendix King
0002	101-380025-17	7BB64	Controller-Bleed Air Valve, Cond. 7	7	1	Removed from a King Air on 5/7/15, weak. Mfg. Hawker Beechcraft
0003	066-3046-01	14816	KI-525A Pic Nav Indicator, Cond. 7	7	1	Removed from a Cessna 206 on 9/17/14. Internal lighting inop. Mfg. Bendix King
0004	066-3046-01	40893	KI-525A Pic Nav Indicator, Cond. 7	7	1	Removed from a Cessna 206 on 10/10/14. Glidescope indicator remains centered no matter where aircraft is in the approach. Mfg. Bendix King
0005	066-3046-01	32518	KI-525A Pic Nav Indicator, Cond. 7	7	1	Removed from an MD helicopter on 11/14/15. Processes correction card intermittent. Mfg. Bendix King
0006	23065104	BR52180	Fuel Control Assembly 250-C20b, Cond. 7	7	1	Removed from an MD500 on 4/13/06. Time since overhaul 1078.5. Inspect, repair and recalibrate, service accessory record included. Mfg. Rolls Royce
0007	23073533	1004-82	No: 1 Nozzle Shield Assy, Cond. 7	7	1	Removed from Rolls Royce engine on 8/7/13. Overhaul and certify. Total time 2300.9, Total cycles 2390. Mfg. Rolls Royce
0008	23073566	N/A	No: 1 Nozzle Shield Assy, Cond. 7	7	1	Removed from a Rolls Royce engine on 8/5/14. Overhaul & certify. Time since overhaul 1981.9, Total time 3342.0, Total cycles 3712. Mfg. Rolls Royce
0009	DC290D1-F/T37	120536	Governor Assembly, Propeller, Cond. 7	7	1	Removed from a Cessna 206 on 6/26/15, leaking oil. Mfg. McCauley
0010	23037403	KU92768	PT Inner Shaft, Cond. 7	7	1	Removed from a Rolls Royce Engine on 5/20/13. Overtemp to 1100 Deg C. Total time 2449.7, Total cycles 1706. Mfg. Rolls Royce
0011	23065104	332458	Fuel Control Assy, Cond. 7	7	1	Removed from a Rolls Royce engine on 1/31/04. Grease leaking from bearings. Rolls Royce T.S.O. 388.5. Inspect, repair and certify. Mfg. Rolls Royce
0012	23073533	AP018C	No: 1 Nozzle Shield Assy, Cond. 7	7	1	Removed from a Rolls Royce engine on 9/12/13. Overtemped to 1300 degrees C. Overhaul and certify. Total time 4075.8, Time since overhaul 649.3, Total cycles 5198. Mfg. Rolls Royce
0013	1214008-29	N/A	Cessna 206 Seat, Includes seat belt, Cond. 7	7	1	Removed from a Cessna 206 on 6/16/15. Broken weld at front of seat. Includes seat belt. Mfg. Cessna
0014	6879867	PF39795	Nozzle, 3rd Stage, Cond. 7	7	1	Removed from a Rolls Royce engine on 3/14/09. Severly eroded. Overhaul & recertify. Total time 4375.9, Total cycles 3673 Mfg. Rolls Royce
0015	6879867	RF38181	Nozzle, 3rd Stage, Cond. 7	7	1	Removed from a Rolls Royce engine to upgrade turbine. Total time 6486, Total cycles 9096 Mfg. Rolls Royce
0016	6879867	PF37653	Nozzle, 3rd Stage, Cond. 7	7	1	Removed for an upgrade from a Rolls Royce engine on 7/12/13, recertify. Time since overhaul 3012.2, Total time 7954.7, Total cycles 7413 Mfg. Rolls Royce
0017	23001967	X576904	Third Stage Turbine Wheel, Cond. 7	7	1	Removed from a Rolls Royce engine on 3/21/14, upgrading turbine, recertify. Total time 120.4, Total Cycles 87 Mfg. Rolls Royce
0018	23007189	PF49240	Third Stage Nozzle, Cond. 7	7	1	Removed from a Rolls Royce engine on 5/31/13, overtemped to 1300 Deg. C. Overhaul & recertify. Time since overhaul 649.3, Total Cycles 5198, Total Time 4075.8 Mfg. Rolls Royce
0019	066-1072-00	40508	KR 87 Receiver, Cond. 7	7	1	Removed from a Cessna Soloy on 7/28/15. Causes Erratic needle movement. Mfg. Bendix King
0020	100-384040	2059	Motor, Flap Drive, Cond. 7	7	1	On shelf since 12/1/13. Motor is intermittent and runs slow. Mfg. Hawker Beechcraft

# Excess Justification Report

## For Excess Lot

### FY15-048

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0021	101-384135-3	2435	Blower Assembly, Aft Evaporator And Heater Alternator, Cond. 7	7	1	Removed from a King Air on 2/26/15. Inop, has good ground, voltage to filter and out of filter, turns smoothly. Mfg. Hawker Beechcraft
0022	101-384135-3	1044	Blower Assembly, Aft Evaporator And Heater Alternator, Cond. 7	7	1	Removed from a King Air on 8/2/13. Does not turn on. Aircraft hours 7890.0 Mfg. Hawker Beechcraft
0023	101-950017-77	NSN	Exhaust Assy-Engine,LH, Cond. 7	7	1	Removed from a King Air on 6/24/09. Has grooves cut into the deice tube for the inlet lip. Mfg. Hawker Beechcraft
0024	LW-18861	BAN40200	Bypass Valve, Cond. 7	7	1	Removed from a Cessna Citation on 7/21/15. Requires overhaul. Mfg. Garrett
0025	48B22314	BDN44718	Controller, Cond. 7	7	1	Removed from a Cessna Citation on 1/28/15. Requires overhaul. Mfg. Garrett
0026	LW-14445-11	BBN04643	Valve, Cond. 7	7	1	Removed from a Lycoming engine on 1/28/15. Requires overhaul. Mfg. Garrett
0027	23057142	SET 42362	Case Halves, Cond. 7	7	1	Removed from a Rolls Royce engine on 6/18/15. Engine upgraded to Avid Air case half. Condition unknown. Mfg. Rolls Royce
0028	101-364715-1	02221105ICT	Module, Bus Tie Control Circuit Board, Cond. 7	7	1	Removed from a King Air on 7/14/15. Intermittent operation of LH generator coming online after start up. F6 fuse clear cover missing. Mfg. Hawker Beechcraft
0029	23053176	FF25097	Valve Assembly, Bleed Air, Cond. 7	7	1	Removed from a Rolls Royce engine on 7/29/15. Overhaul and certify. Mfg. Rolls Royce
0030	066-3046-05	80790	KI-525A Pictorial Navigation Indicator, Cond. 7	7	1	Removed from a Cessna 206 on 7/30/15, inop. Mfg. Bendix King
0031	81438-00-0242M	2186257	Trimble 2000 Approach, Cond. 7	7	1	Removed from a Cessna 206 on 7/30/15, Inop. Housing bent on right rear corner. Mfg. Trimble
0032	5035P-P-23	10376	Altimeter, Cond. 7	7	1	Removed from a Cessna 206 on 7/30/15, Inop. Mfg. Bendix King
0033	066-3038-00	5173	Indicator, Rmi, KI-229, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, Inop. Mfg. Bendix King
0034	066-3038-00	11485	Indicator, Rmi, KI-229, Cond. 7	7	1	Removed from a Bell 407 on 11/20/14. Bottom left screw broke off. Mfg. Bendix King
0035	066-3038-00	7357	Indicator, Rmi, KI-229, Cond. 7	7	1	Removed from a Cessna 210 on 12/17/14. Needle/ADF not pointing to station. Mfg. Hawker Beechcraft
0036	066-3038-00	6149	Indicator, Rmi, KI-229, Cond. 7	7	1	Removed from a Cessna on 4/20/15. VOR needle very erratic. Mfg. Bendix King
0037	066-3054-01	12005	Radar Altimeter Indicator, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, recertify. Mfg. Bendix King
0038	066-1068-01	25264	Dme, Kn62a, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, recertify. Mfg. King Radio
0039	066-1068-01	20646	Dme, Kn62a , Cond. 7	7	1	Removed from a MD Helicopter on 4/25/14. Recertify, plastic display cover hazy. Mfg. King Radio
0040	066-1068-01	21002	Dme, Kn62a, Cond. 7	7	1	Removed from a Cessna on 4/8/15. Display glitch - unit appears to only work intermittently. Mfg. King Radio
0041	066-01148-0102	8792	KLN-89B Receiver, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, recertify. Mfg. Bendix King
0042	70-2520	M100592213	Display/Controller-Bezel, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15. Overhaul and recertify. Mfg. Ryan International Corp.
0043	7000	283998	Vertical Speed Indicator, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, recertify. Mfg. United Instruments
0044	071-1242-01	16627	Accessory, Slaving, Hsi 206, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC. function tested. Requires recertification. Mfg. Bendix King
0045	066-01141-0101	10316	Transceiver, Transponder, KT 70, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC. function tested. Requires recertification. Mfg. Bendix King

**Excess Justification Report**  
**For Excess Lot**  
**FY15-048**

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0046	C668020-0207	0412	Tachometer, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC. function tested. Requires recertification. Mfg. Cessna
0047	C669561-0103	1284	Engine Temp Gauge, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC. function tested. Requires recertification. Mfg. Rochester Gauges
0048	C669562-0103	233	Fuel Qty. Gauge, Cond. 7	7	1	Removed from a Cessna 206, has an serviceable tag from JLC Avionics LLC. function tested. Requires recertification. Mfg. Rochester Gauges
0049	78-8051-9160-4	FXP01200039	Processor Assembly, Stormscope II, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. BF Goodrich
0050	78-8051-9160-4	UXP04003009	Processor Assembly, Stormscope II, Cond. 7	7	1	Removed from a Cessna 210 on 10/23/14 has a repair tag. Powers down intermittently. Internal components loose. Full function test due.
0051	066-1068-01	26683	Dme, Kn62a, Cond. 7	7	1	Removed from a Cessna 206, has a serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. Bendix King
0052	70-2500	001248	Display, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. Ryan International Corp.
0053	060-0015-00	44275	Gyro, Kg102a Directional, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., as removed. Erradic in flight, requires repair and recertification. Mfg. Bendix King
0054	071-1242-01	17204	Accessory, Slaving, Hsi 206, Cond. 7	7	1	Removed from a Cessna 206, has an serviceable tag from JLC Avionics LLC. Requires recertification.
0055	MD26-28	1827	DC/AC Inverter, Cond. 7	7	1	Removed from a Cessna 206 on 5/1/15, has an serviceable tag from JLC Avionics LLC., as removed. Requires recertification. Mfg. Mid Continent
0056	78-8051-9160-4	UXP10800489	Processor Assembly, Stormscope II, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC. as removed with rack. Requires recertification. Mfg. BF Goodrich
0057	066-3054-01	8038	Radar Indicator, Cond. 7	7	1	Removed from a Cessna 206, has an serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. Bendix King
0058	066-3034-05	19868	KI206 Indicator, Cond. 7	7	1	Removed from a Cessna 206, has a serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Bendix King
0059	066-3038-00	6683	Radio Magnetic Indicator, KI-229, Cond. 7	7	1	Removed from a Cessna 206, has a serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. Bendix King
0060	8025	156377	Airspeed Indicator, Cond. 7	7	1	Removed from a Cessna 206, has a serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. United Instruments
0061	MD41-1528	E22890	Gps Annunciation Control Unit, Cond. 7	7	1	Removed from a Cessna 206, has a serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. Mid-Continent Instruments
0062	060-0015-00	46165	Directional Gyro, Kg102a, Cond. 7	7	1	Removed from a MD Helicopter on 8/17/15, precesses 30 degrees in flight. Requires repair and recertification. Mfg. Bendix King
0063	060-0017-00	21378	Indicator, Flight Command, KI-256, Cond. 7	7	1	Removed from a Cessna 206, has an serviceable tag from JLC Avionics LLC., as removed. Requires recertification. Mfg. Bendix King
0064	071-4037-01	N/A	Cooling Fan, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Bendix King

# Excess Justification Report

## For Excess Lot

### FY15-048

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0065	060-0017-00	20367	Indicator, Flight Command, KI-256, Cond. 7	7	1	Removed from a Cessna 206, has an serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. Bendix King
0066	066-1055-71	80227	Audio/ Intercom Panel, KMA-24H-71, Cond. 7	7	1	Removed from a Cessna 206 on 4/30/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Bendix King
0067	70-2040	001275	Transponder Coupler, Cond. 7	7	1	Removed from a Cessna 206 on 4/30/15, has an serviceable tag from JLC Avionics LLC., as removed. Requires recertification. Mfg. Ryan International
0068	78-8051-9170-3	UXD04003006	Stormscope Display, Cond. 7	7	1	Removed from a Cessna 206, has an serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. Stormscope
0069	066-1061-03	13310	Radar Altimeter, Cond. 7	7	1	Removed from a Cessna 206 on 4/30/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Bendix King
0070	70-2400	010117	Processor, Cond. 7	7	1	Removed from a Cessna 206 on 4/30/15, has an serviceable tag from JLC Avionics LLC., as removed. Requires recertification. Mfg. Ryan International
0071	1394T100-7Z	7510-749	Turn Coordinator, Cond. 7	7	1	Removed from a Cessna 206, has an serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. Electric Gyro
0072	7000	25577	Verticle Speed Indicator, Cond. 7	7	1	Removed from a Cessna 206, has an serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. United Instruments
0073	066-3046-01	22542	KI-525A Pic Nav Indicator, Cond. 7	7	1	Removed from a Cessna 206, has an serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. King Radio
0074	071-1052-00	KMT112-79346	Transmitter, Flux Detector, Azimuth, Type Kmt, Cond. 7	7	1	Removed from a Cessna 206 on 5/6/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Honeywell
0075	066-01148-0101	7787	Receiver, GPS KLN-89B, Cond. 7	7	1	Removed from a Cessna 206, has an serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. Bendix King
0076	066-1072-00	45396	KR87 Receiver, Cond. 7	7	1	Removed from a Cessna 206, has an serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. Bendix King
0077	066-1053-00	3974	KT-79 Atc Transponder, Cond. 7	7	1	Removed from a Cessna 206, has an serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. King Radio
0078	VA-1A-300	058916	Voltmeter, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Electronics International
0079	46150	263924	EGT Indicator, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Alcor
0080	MD41-528	11243	GPS APU, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Mid Continent
0081	071-1052-00	60786	Flux Detector, Azimuth Transmitter, Type Kmt, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification.
0082	C668540-0101	W19915G	Suction Indicator, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has a serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Cessna
0083	1394T100-7Z	G12-10240	Turn Coordinator, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Electric Gyro

# Excess Justification Report

## For Excess Lot

### FY15-048

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0084	C662037-0103RX	187138AM	Fuel Flow Gage, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. United Instruments
0085	0669560-0105	578	Oil Pressure Gauge, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Rochester Gauges
0086	78-8051-9170-3	UXD02901086	Stormscope Display, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Stormscope
0087	066-1061-03	18589	Transceiver, Radar Altimeter, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC. Requires recertification. Mfg. Bendix King
0088	066-1055-71	85464, 84534, 85485	Audio/ Intercom Panel, KMA-24H-71 - King, Cond. 7	7	3	Removed from a Cessna 206 on 3/18/15, has a serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Bendix King
0089	70-2420-8TAS6051	990818	Processor, Cond. 7	7	1	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Avidyne
0090	069-1025-25	59390, 12404	Transceiver, Nav Comm, KX-165, Cond. 7	7	2	Removed from a Cessna 206 on 3/18/15, has an serviceable tag from JLC Avionics LLC., function tested. Requires recertification. Mfg. Bendix King
0091	23007189	PF45166	Third Stage Nozzle, Cond. 7	7	1	Removed from a Rolls Royce engine on 8/11/15, for turbine overhaul. Total time 4437.9, Time Since Overhaul 712.3, Total Cycles 4264.
0092	6890040	Unknown	First Stage Nozzle Shield, Cond. 7	7	1	Removed from a Rolls Royce engine on 8/10/15, overhaul and recertify. Total Time 4437.9, Time Since Overhaul 712.3, Total Cycles 4264.
0093	E23062753	ER187186	No: 1 Nozzle Shield, Cond. 7	7	1	Removed from a Rolls Royce engine on 8/11/15, overhaul and recertify. Total Time 4437.9, Time Since Overhaul 713.2, Total Cycles 4264.
0094	23037413	KU92051	P.T. Outer Shaft	7	1	Removed from a Rolls Royce engine on 8/11/15, overhaul and recertify. Total Time 4437.9, Time Since Overhaul 712.3, Total Cycles 4264.
0095	DC290D1-B/T25	990791	Prop Governor Assy, Cond. 7	7	1	Removed from a Cessna 206 on 7/8/14. Condition unknown.. Mfg. McCauley
0096	DC290D1-B/T25	980216	Prop Governor Assy, Cond. 7	7	1	Removed from a Cessna 206 on 10/25/12. Stops at 2400RPM. Mfg. McCauley
0097	C161031-0121	050563	Prop Governor Assy, Cond. 7	7	1	Removed from a Cessna 206 on 1/7/11. Condition unknown. Mfg. McCauley
0098	C161031-0121	060480	Prop Governor Assy, Cond. 7	7	1	Removed from a Cessna 206 on 10/3/13. Condition unknown. Mfg. McCauley
0099	C161031-0121	072128	Prop Governor Assy, Cond. 7	7	1	Removed from a Cessna 206 on 8/7/12, surging. Mfg. McCauley
0100	C20373-1	07169	Prop Governor Assy, Cond. 7	7	1	Removed from a Cessna on 2/15/11, weak. Mfg. McCauley
0101	C290D4J/T4	910088	Prop Governor Assy	7	1	Sitting on repair shelf since 3/29/07. Unit leaking, requires repair and overhaul. Mfg. McCauley
0102	C290D4-K/T2	781166	Prop Governor Assy, Cond. 7	7	1	On repair shelf since 1/14/09, overhaul required. Total time 1402.0 Mfg. McCauley
0103	C290D4-K/T2	920471	Prop Governor Assy, Cond. 7	7	1	On repair shelf since 12/8/11, due overhaul. Mfg. McCauley
0104	C290D4-K/T2	880525	Prop Governor Assy, Cond. 7	7	1	On repair shelf since 12/8/06, due overhaul. Mfg. McCauley
0105	C290D4-K/T2	792913	Prop Governor Assy, Cond. 7	7	1	On repair shelf since 12/8/12, due overhaul. Mfg. McCauley
0106	C290D4K/T4	820514	Prop Governor Assy, Cond. 7	7	1	On repair shelf since 12/16/11. Suspect oil seepage. Mfg. McCauley

**Excess Justification Report**  
**For Excess Lot**  
**FY15-048**

Item #	Part #	Serial #	Description	Cond	Qty	Remarks
0107	109-389002-9	199	Valve Assembly, Firewall Fuel Shutoff, Cond. 7	7	1	Removed from a King Air on 7/3/15, condition unknown. Mfg. Hawker Beechcraft
					110	