

A1QSCI-15-100 LOT 527

Crane, Rough Terrain, 40 Ton

Engine: Cummins 8.3L

Boom Length: 60'

Machine starts with a jump

Operating Condition unknown

Rear Wheel Steer was tested and did NOT function

Hydraulic Fluid is below site glass

Hydraulic Leak at front of operators station

Missing 1 Stabilizer Ram, exhaust pipe and LMI system

Drivelines Disconnected (unk if all parts to reconnect are present)

1 Tire is flat

Shipping Wt: 98,4000 lbs

Unit will require a 10' wide minimum RGN Trailer to safely transport.

Buyer is responsible for loading – There is No Loading Assistance available.