

A1QSCI-15-109 LOT 521

Crane, Rough Terrain, 40 Ton

Engine: Cummins 8.3L

Boom Length: 60'

Machine starts with a jump

Operating Condition unknown

Rear Wheel Steer was tested and did NOT function

Hydraulic Fluid is below site glass

Hydraulic Leak at front of operators station

Missing 1 Stabilizer Ram, exhaust pipe and LMI system

Drivelines Disconnected (unk if all parts to reconnect are present)

1 Tire is flat

Boom lift rams leaking

Safety guards/covers missing or loose

Note in cab states hydraulic tank empty and dirty inside

Top window on cab broken

2 "U" joints will need replaced

Antifreeze overflow tank empty and broken. Unable to check engine coolant level without rotating crane structure.

Shipping Wt: 98,400 lbs

Unit will require a 10' wide minimum RGN Trailer to safely transport.

Buyer is responsible for loading – There is No Loading Assistance available.

INSPECTION IS HIGHLY RECOMMENDED, OTHER UNKNOWN MECHANICAL ISSUES MAY BE PRESENT.

IT IS THE BUYERS RESPONSIBILITY TO VERIFY CONDITION!