

- Search Safety Problems
 - Vehicles
 - Car Seats
 - Tires
 - Equipment
 - Recalls by VIN
 - Recalls FAQ
- Report Safety Problems
 - Vehicle (Online)
 - Vehicle (via PDF)
 - Non-Vehicle
- Drive Safer
 - Technology
 - Driving Tips
 - Tires
 - Passenger Van Safety
 - Emergency Response Vehicles
 - Theft Prevention

Recalls Results by VIN - Vehicle Identification Number [Print](#)

VIN: 1D7KS28D57J577090
Year: 2007 **Make:** DODGE **Model:** RAM QUAD CAB 2500 4X4
Number of Open Recalls: 1

NHTSA Recall Number: 15V-313	Recall Date: May 29, 2015
Manufacturer Recall Number: R25	

SUMMARY:
THE DRIVER AIRBAG INFLATOR HOUSING MAY RUPTURE, DUE TO EXCESSIVE INTERNAL PRESSURE, DURING NORMAL AIRBAG DEPLOYMENT EVENTS. THIS CONDITION IS MORE LIKELY TO OCCUR IF THE VEHICLE HAS BEEN EXPOSED TO HIGH LEVELS OF ABSOLUTE HUMIDITY FOR EXTENDED PERIODS OF TIME.

SAFETY RISK:
AN INFLATOR RUPTURE, DURING AIRBAG DEPLOYMENT EVENTS, COULD RESULT IN METAL FRAGMENTS STRIKING AND POTENTIALLY SERIOUSLY INJURING THE VEHICLE OCCUPANT(S).

REMEDY:
THE DRIVER AIRBAG INFLATOR MUST BE REPLACED.

RECALL STATUS: **Recall INCOMPLETE**

MANUFACTURER NOTES:
For more information, visit recalls.mopar.com or call 1-800-853-1403. Please have your VIN ready when calling.

[Find a Dealer Near You](#) 

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in...