

VIN: 1FTYR15E65PA57997

Year: 2005 **Make:** FORD **Model:** Ranger

Number of Open Recalls: 2

NHTSA Recall Number: [15V322](#)

Recall Date: May 27, 2015

Manufacturer Recall Number: 15S22

SUMMARY:

IN THE SUBJECT VEHICLES, CONTINUED EXPOSURE TO HIGH LEVELS OF ABSOLUTE HUMIDITY MAY CAUSE THE PASSENGER AIRBAG INFLATOR HOUSING TO RUPTURE IF THE VEHICLE IS INVOLVED IN A CRASH WHERE THE SUPPLEMENTAL FRONT AIRBAGS ARE DESIGNED TO DEPLOY.

SAFETY RISK:

AN INFLATOR RUPTURE COULD RESULT IN METAL FRAGMENTS STRIKING AND POTENTIALLY INJURING VEHICLE OCCUPANTS.

REMEDY:

DEALERS WILL REPLACE THE PASSENGER AIRBAG INFLATOR WITH A NEW ONE, FREE OF CHARGE.

RECALL STATUS: **Recall INCOMPLETE. Remedy not yet available**

MANUFACTURER NOTES:

TO CHECK FOR NON-SAFETY-RELATED PROGRAMS APPLICABLE TO YOUR VEHICLE, SEE [HTTP://WWW.FORD.COM/](http://www.ford.com/) OR CALL YOUR FORD DEALER.

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

THIS RECALL DATA LAST REFRESHED: Nov 8, 2016

NHTSA Recall Number: [16V036](#)

Recall Date: January 22, 2016

Manufacturer Recall Number: 16S03

SUMMARY:

DRIVER AIRBAG INFLATOR REPLACEMENT

SAFETY RISK:

THE DRIVER SIDE AIRBAG INFLATOR COULD RUPTURE IF THE VEHICLE IS INVOLVED IN A CRASH WHERE THE SUPPLEMENTAL FRONTAL AIRBAGS ARE DESIGNED TO DEPLOY. IF THIS OCCURS, IT MAY INCREASE THE RISK OF INJURY OR DEATH TO THE OCCUPANTS.

REMEDY:

OWNERS WILL BE NOTIFIED BY MAIL AND INSTRUCTED TO TAKE THEIR VEHICLE TO A FORD OR LINCOLN DEALER TO HAVE THEIR DRIVER AIRBAG INFLATOR REPLACED. THERE WILL BE NO CHARGE FOR THIS SERVICE. FORD IS EXCLUDING REIMBURSEMENT FOR COSTS BECAUSE THE ORIGINAL WARRANTY PROGRAM

WOULD PROVIDE FOR A FREE REPAIR FOR THIS CONCERN. FORD WILL FORWARD A COPY OF THE NOTIFICATION LETTERS TO DEALERS TO THE AGENCY WHEN AVAILABLE.

RECALL STATUS: Recall INCOMPLETE. Remedy not yet available

MANUFACTURER NOTES:

TO CHECK FOR NON-SAFETY-RELATED PROGRAMS APPLICABLE TO YOUR VEHICLE, SEE [HTTP://WWW.FORD.COM/](http://www.ford.com/) OR CALL YOUR FORD DEALER.

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

THIS RECALL DATA LAST REFRESHED: Nov 8, 2016

Additional Safety Information

Besides the VIN search tool you just used, NHTSA offers additional safety information based on a vehicle's make, model, and model year and not tied to any particular VIN. A search by vehicle make, model, and model year gives you access to information about technical service bulletins, NHTSA investigations, and owner complaints, as well as safety recalls on aftermarket equipment that is often not linked to a particular VIN or even to your vehicle's manufacturer.

To search NHTSA's safety information based on your vehicle's make, model, and model year, please go to the [Safety Issues section](#) and follow the instructions there.

Recall information for this manufacturer is only available going back to January 01, 1999. If your vehicle was manufactured before this date, please contact the manufacturer for possible additional recall information.