

VIN: 1GCHK29K48E182720

Year: 2008 **Make:** Chevrolet **Model:** Silverado HD

Number of Open Recalls: 1

NHTSA Recall Number: [15V324](#)

Recall Date: May 28, 2015

Manufacturer Recall Number: N150817

SUMMARY:

Some front passenger airbag inflators may experience an alteration over time, which could lead to overaggressive combustion in the event of an air bag deployment. This condition could create excessive internal pressure when the air bag is deployed, which could result in the body of the inflator rupturing upon deployment.

SAFETY RISK:

In the event of an inflator rupture, metal fragments could pass through the air bag cushion material, which may result in injury or death to vehicle occupants.

REMEDY:

Dealers will replace the front passenger air bag inflator, free of charge.

RECALL STATUS: **Recall INCOMPLETE. Remedy not yet available**

MANUFACTURER NOTES:

Visit manufacturer website at <https://my.gm.com/recalls> for more information.

If the manufacturer has failed or is unable to remedy this safety recall for your vehicle in a timely manner, please contact the NHTSA Vehicle Safety Hotline at: 1-888-327-4236 or TTY: 1-800-424-9153 or file an [online complaint with NHTSA](#).

THIS RECALL DATA LAST REFRESHED: Nov 15, 2016

Additional Safety Information

Besides the VIN search tool you just used, NHTSA offers additional safety information based on a vehicle's make, model, and model year and not tied to any particular VIN. A search by vehicle make, model, and model year gives you access to information about technical service bulletins, NHTSA investigations, and owner complaints, as well as safety recalls on aftermarket equipment that is often not linked to a particular VIN or even to your vehicle's manufacturer.

To search NHTSA's safety information based on your vehicle's make, model, and model year, please go to the [Safety Issues section](#) and follow the instructions there.

Recall information for this manufacturer is only available going back to August 20, 1999. If your vehicle was manufactured before this date, please contact the manufacturer for possible additional recall information.