

FY15-26

Repairable Aircraft Parts

PART#	SERIAL#	DESCRIPTION	CONDITION	QUANTITY	Remarks
1	013500-1	MCU BOARD	7	1	REMOVED ON 9/15/10. WILL NOT RECEIVE RS-232 DATN TO TDFM-6148 BUT WILL RECEIVE & DISPLAY RS-232 DATA.
2	060-0015-00	KG102A DIRECTIONAL GYRO	7	1	REMOVED FROM A CESSNA 206 ON 7/29/13. DG PROCESS 30 TO 70 DEGREES OFF. WILL NOT HOLD SLAVE POSITION. INTERNAL CONDITION UNKNOWN.
3	060-0017-01	KI-256	7	1	REMOVED FROM A CESSNA 206 ON 6/20/12. CONDITION UNKNOWN.
4	064-1054-30	KY196A VHF TRANSCEIVER	7	1	REMOVED FROM AN MD369 HELICOPTER ON 6/18/13. UPON POWER UP FREQUENCY LIGHTS INTERMITTENT. INTERNAL CONDITION UNKNOWN.
5	065-0059-03	SERVO	7	1	REMOVED FROM A CESSNA 206 ON 10/11/10. LOOSE PARTS INSIDE.
6	065-0059-03	SERVO	7	1	REMOVED FROM A CESSNA 206 ON 12/6/12. NO UP PITCH TRIM OUTPUT. OUTSIDE CASE IS CRACKED.
7	065-0059-04	PITCH SERVO	7	1	REMOVED FROM A CESSNA 210 ON 2/16/12. NO DOWN AUTO TRIM.
8	065-0059-04	PITCH SERVO	7	1	REMOVED FROM A CESSNA 210 ON 10/3/11. CONDITION UNKNOWN.
9	065-0061-16	TRIM SERVO KS272A	7	1	REMOVED FROM A CESSNA 206 ON 10/20/14. CONDITION UNKNOWN.
10	066-01141-0101	KT70 TRANSPONDER TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 7/9/14. FAILED ON INSTALL.
11	066-01148-0101	KLN-89B GPS RECEIVER	7	1	REMOVED FROM A CESSNA 206 ON 7/19/13. UPGRADED TO KLN94.
12	066-01148-0101	KLN-89B GPS RECEIVER	7	1	REMOVED FROM A CESSNA 206 ON 3/29/13. INNER PULL SCAN KNOB BROKEN. INTERNAL CONDITION UNKNOWN.
13	066-01148-0101	KLN-89B GPS RECEIVER	7	1	REMOVED FROM A CESSNA 210 ON 11/15/11. CONDITION UNKNOWN.
14	066-01148-0102	KLN-89B GPS RECEIVER	7	1	REMOVED FROM A CESSNA 206 ON 4/18/11. NO DISPLAY.
15	066-01148-0102	KLN-89B GPS RECEIVER	7	1	REMOVED FROM A CESSNA 206 ON 1/21/14. UNKNOWN CONDITION.
16	066-01148-0102	KLN-89B GPS RECEIVER	7	1	REMOVED FROM A CESSNA 206 ON 4/2/12. BAD DISPLAY.
17	066-1055-65	AUDIO PANEL	7	1	REMOVED FROM A CESSNA 206 ON 6/24/14. CONDITION UNKNOWN.
18	066-1055-65	AUDIO PANEL	7	1	REMOVED FROM A CESSNA 206 ON 12/5/11. UNIT KEY BROKE AND LOCK MECHANISM STRIPPED. HAD TO DRILL OUT.
19	066-1055-71	KMA-24H-71 AUDIO/INTERCOM PANEL	7	1	REMOVED FROM A CESSNA 210 ON 7/25/14. CAN NOT HEAR ICS #2.
20	066-1055-71	KMA-24H-71 AUDIO/INTERCOM PANEL	7	1	REMOVED FROM A CESSNA 206 ON 2/14/14. BAD COM 4 AUDIO.
21	066-1055-71	KMA-24H-71 AUDIO/INTERCOM PANEL	7	1	REMOVED FROM A CESSNA 206 ON 11/12/14. VOX KNOB NOT WORKING PROPERLY. CAUSES STATIC IN AUDIO SYSTEM WHEN KNOB IS ROTATED.
22	066-1055-71	KMA-24H-71 AUDIO/INTERCOM PANEL	7	1	REMOVED FROM A CESSNA 210 ON 7/7/14. PRODUCES LOUD UNWANTED NOISE.
23	066-1055-71	KMA-24H-71 AUDIO/INTERCOM PANEL	7	1	REMOVED FROM A CESSNA 206 ON 5/28/14. CONDITION UNKNOWN.

24	066-1055-71	85945	KMA-24H-71 AUDIO/INTERCOM PANEL	7	1	REMOVED FROM A CESSNA 210 ON 3/31/14. UNIT IS INTERMITTENT AFTER 30 MINS. FLIGHT TIME.
25	066-1068-00	14564	KN62A DME	7	1	REMOVED FROM AN MD500 ON 7/2/13. DOES NOT DISPLAY .5 WHEN SMALL KNOB PULLED OUT.
26	066-1068-01	20523	KN62A DME	7	1	REMOVED FROM A CESSNA 206 ON 8/27/13. NO DME MILEAGE DISPLAYED IN FREQ. MODE.
27	066-3034-05	15285	KI206 VOR/LOC/G.S. INDICATOR	7	1	REMOVED FROM A CESSNA 206 ON 9/4/12. ALWAYS CENTERS DEV BAR 4 DEG OFF.
28	066-3034-05	17933	KI206 VOR/LOC/G.S. INDICATOR	7	1	REMOVED ON 12/15/08, CONDITION UNKNOWN.
29	066-3034-05	19896	KI206 VOR/LOC/G.S.INDICATOR	7	1	REMOVED FROM A CESSNA 210 ON 7/21/12. INTERMITTENT, INOP WITH FLAGS.
30	066-3046-05	80354	KI-525A HIS	7	1	REMOVED FROM A CESSNA 206 ON 12/6/12. LT/RT HANGING UP.
31	066-3046-05	80694	KI-525A-HIS	7	1	REMOVED FROM AN MD369 ON 9/18/13. BROKEN CONNECTOR.
32	069-1025-07	14728	KX-165 NAV COMM	7	1	REMOVED FROM A CESSNA CARAVAN 208 ON 3/22/11, INOP.
33	069-1025-07	45586	KX-165 NAV COM	7	1	REMOVED FROM A MD500 ON 7/30/11. #1 COMM VHF SCRATCHY AND ASSY FULL OF DEBRIS (SAND).
34	069-1025-23	5781	KX-165 NAV/COM	7	1	REMOVED FROM A CESSNA 210 ON 7/19/10. NOT POWERING UP.
35	069-1025-25	12520	KX-165 NAV COMM TRANSCEIVER	7	1	REMOVED FROM A CESSNA 210 ON 5/21/13. NO SIDE TONE WHEN TRANSMITTING.
36	069-1025-25	13974	KX-165 NAV COMM TRANSCEIVER	7	1	UP, NAV FREQUENCIES WILL NOT ADVANCE THROUGH FULL RANGE/INTERMITTENT. INTERNAL CONDITION UNKNOWN.
37	069-1025-25	13988	KX-165 NAV COMM TRANSCEIVER	7	1	REMOVED FROM A CESSNA 210 ON 7/25/14. NO AUDIO SIDETONES DURING TRANSMIT.
38	069-1025-25	13999	KX-165 NAV COMM TRANSCEIVER	7	1	REMOVED FROM A CESSNA 210 ON 6/13/13. NAV #2 BAD.
39	069-1025-25	14355	KX-165 NAV COMM TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 12/6/12. NAV MHZ DIAL BROKEN.
40	069-1025-25	14803	KX-165 NAV COMM TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 7/3/13. SQUELCH INOP. MOUNTING HARDWARE BROKEN.
41	069-1025-25	46204	KX-165 NAV COMM TRANSCEIVER	7	1	REMOVED FROM A CESSNA 210 ON 7/29/13. TRANSFER SWITCH INTERMITTENT.
42	069-1025-25	46405	KX-165 NAV COMM TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 9/4/12. TOO DIM IN SUNLIGHT.
43	069-1025-27	14828	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 9/3/13. UNIT STOPPED TRANSMIT/RECEIVE UPON OVERHEAT.
44	069-1025-27	2899	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 2/20/14. CONDITION UNKNOWN.
45	069-1025-27	45429	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 6/24/14. CONDITION UNKNOWN.
46	069-1025-27	47275	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA206 ON 6/24/14. CONDITION UNKNOWN.
47	069-1025-27	47706	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 3/17/14. CONDITION UNKNOWN.
48	069-1025-27	47818	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 5/23/14. CONDITION UNKNOWN.

49	069-1025-27	47933	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 1/16/14. WILL NOT POWER UP.
50	069-1025-27	48353	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 4/18/14. SQUELCH ON ALL THE TIME.
51	069-1025-27	48464	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 2/12/14. DISPLAY DIM.
52	069-1025-27	48516	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 210 ON 3/11/14. DISPLAY WINDOW FOGGY, DETERIORATED.
53	069-1025-27	48807	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 9/12/13. CONDITION UNKNOWN.
54	069-1025-27	48812	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 210 ON 12/23/13. SUBSTANTIAL AMOUNT OF STATIC PRESENT.
55	069-1025-27	48842	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 11/8/14. SQUELCH ON ALL THE TIME.
56	069-1025-27	48845	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 11/29/13. COM SQUELCH INTERMITTENT.
57	069-1025-27	48868	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 11/29/13. SQUELCH OUT OF ADJUSTMENT.
58	069-1025-27	49487	KX165 TRANSCEIVER	7	1	REMOVED FROM A CESSNA 206 ON 11/29/13. NO LEFT/RIGHT OUTPUT TO HSI.
59	10035-11424	1663464	ALTIMETER	7	1	REMOVED FROM A BELL 412 ON 2/1/13. ALTIMETER LAGS BEHIND TEST SET BY 500 FEET AND BARO KNOB IS VERY STIFF.
60	10035-11424	176533	ALTIMETER	7	1	REMOVED FROM A BELL 412 ON 3/26/10. 3 PIN CONN BENT WON'T TAKE CANNON PLUG. EXPIRED SHELF LIFE ON 9/19/11.
61	101-364582-15	828F96	LT TEST & HYD GEAR TIME DELAY PC BOARD	7	1	REMOVED FROM A KING AIR B300 ON 8/21/13. WORKS ONLY PART TIME FOR LOW PITCH SOLINOID RELEASE.
62	101-364674-1	880-G-91	FIRE EXTINGUISHER CIRCUIT CARD ASSEMBLY	7	1	REMOVED FROM A KING AIR B300 ON 12/21/10. DISCHARGE LIGHT INTERMITTENT.
63	117-384019-3	0923-5294	FUEL QUANTITY INDICATOR	7	1	REMOVED FROM A KING AIR B300 ON 4/29/14. DOES NOT INDICATE PROPERLY & ERRATIC IN OPERATION.
64	17960-0102-0001	M1118	GNS-XLS	7	1	REMOVED FROM A KING AIR B300 ON 8/13/12. UNIT INDICATES INCORRECT A/C POSITION. INTERMITTENT.
65	17960-0102-0003	3136	GNS-XLS	7	1	REMOVED FROM A KING AIR ON 6/14/11. ON POWER UP LOCATION SHOWS "Q" AND ONLY POWER BUTTON ON KEY PAD WORKS.
66	17960-0102-0014	3116	GNS-XLS	7	1	REMOVED FROM A KING AIR ON 5/26/09. LINE SELECT KEY #5 MISSING.
67	214-175-278-101	172502	ENCODING ALTIMETER	7	1	REMOVED FROM A BELL 412 ON 6/18/10. BAD, PARTICLE SCREEN IN STATIC PORT IS RIPPED.
68	229-0324-020-N	1829	LAT/LONG ACCELEROMETER	7	1	REMOVED FROM A KING AIR B300 ON 7/13/12. PROVIDING INACCURATE SIGNALS TO AUTOPILOT.
69	369H4233	2954	GENERATOR TACHOMETER	7	1	REMOVED FROM AN MD369 ON 4/30/14. CANON PLUG NEEDS REPLACEMENT.
70	412-075-010-111	01546	TACHOMETER INDICATOR	7	1	REMOVED FROM A BELL 412 ON 3/4/13. #1 ENGINE OUT OF SPEC.
71	5035P2-P44	32861	ENCODING ALTIMETER INDICATOR	7	1	REMOVED FROM AN AEROSTAR 350 ON 5/1/12. OUT OF CAL.
72	5035P2-P44	X20029	ENCODING ALTIMETER INDICATOR	7	1	REMOVED FROM A CESSNA 206 ON 3/17/12. FAILS ALT TOLERANCE CHECK.
73	504-0111-920	50401119202505	HORIZON REF. INDICATOR	7	1	REMOVED FROM AN AEROSTAR 350 ON 9/11/13. SLOW TO SPOOL UP. TENDS TO DRIFT-NEEDS TO BE CAGED.

74	5934PD-3	451433	BAROMETRIC MIDCONTINENT ALTIMETER	7	1	REMOVED FROM A CESSNA 206 ON 12/3/13. INDICATES 100' LOWER THAN REPORTED.
75	78-8060-5900-8	80555	STORMSCOPE DISPLAY UNIT	7	1	REMOVED FROM A BELL 407 ON 7/11/11. DISPLAY GOES OUT INTERMITTANTLY.
76	78-8060-5900-8	FSD06200494	STORMSCOPE DISPLAY UNIT	7	1	REMOVED FROM A CESSNA 210 ON 10/1/12. DISPLAY BECOMES DIM INTERMITTANTLY
77	78-8060-5900-8	FSD06200513	STORMSCOPE DISPLAY UNIT	7	1	REMOVED FROM A CESSNA 210 ON 7/19/13. DEAD.
78	78-8060-5900-8	FSD07301278	STORMSCOPE DISPLAY UNIT	7	1	REMOVED FROM A CESSNA 210 ON 7/27/14. AFTER UNIT HAS BEEN OPERATING 15 MINS. THE DISPLAY BECOMES DISTORTED.
79	805-10800-001	SKY07001802	SKYWATCH COMPUTER	7	1	REMOVED FROM A KING AIR ON 8/12/11. TCAS ERRONEOUS WARNING.
80	805-10800-001	SKY07800503	SKYWATCH COMPUTER	7	1	REMOVED FROM A KING AIR ON 4/26/12. OUTPUT VOLUME TO LOW FOR WARNINGS
81	DK120	DK4303	UNDERWATER BEACON	7	1	REMOVED FROM A KING AIR ON 10/10/14. BATTERY EXPIRES END OF OCT 2014.
82	H2946-1	155B	DIGITAL VOLTMETER/CYCLE COUNTER	7	1	REMOVED FROM AN AEROSTAR 350 ON 5/28/14. DEINSTALL- CONDITION UNKNOWN.
83	MD41-528	F09-10412	GPS ANNUNCIATION INDICATOR CONTROL UNIT	7	1	REMOVED FROM A CESSNA 206 ON 9/23/14. NAV LIGHT INOP.
84	MD41-528	G21188	GPS ANNUNCIATION INDICATOR CONTROL UNIT	7	1	REMOVED FROM A CESSNA 206 ON 9/23/14. NAV LIGHT INOP.
85	RT1168B/ARC164V	05969	UHF RCVR/XMITR	7	1	REMOVED FROM A KING AIR 350 ON 6/23/09. UHF INTERMITTENT. WILL WORK FOR ABOUT 5-10 MINS.
86	RT1505/ARC-164	E03341	UHF TRANSCEIVER	7	1	REMOVED FROM A BELL 412 ON 10/18/12. WILL NOT POWER UP.
87	S-100-001-P001	10495	SKYNODE CONTROLLER	7	1	REMOVED FROM A CESSNA 206 ON 2/12/14. WITH SYSTEM POWERED UP, STATIC IS PRODUCED IN BOT VHF RADIO SYSTEMS. PULLING BREAKER CLEARS PROBLEM UP.
88	S3350-1	410416	ALTIMETER	7	1	REMOVED FROM A CESSNA 206 ON 2/2/10. INDICATOR NEEDS TO BE RECERTIFIED AS SERVICEABLE TO MFG SPECS.
89	SN3308-00BL	2014	HIS - SANDEL AVIONICS INDICATOR	7	1	REMOVED FROM A CESSNA 206 ON 7/25/14. CONDITION UNKNOWN.
90	SN3308-00BL	3966	HIS - SANDEL AVIONICS INDICATOR	7	1	REMOVED FROM A CESSNA 206 ON 7/23/14. UNIT WILL NOT SWITCH GPS TO NAV.