

PW305A TURBO FAN ENGINE

31B4067-01; Engine Turbo Fan PW305A;

Repaired; Current hours/Cycles: 6216.5 hours/2845 Cycles;

Last HSI Completed: 09/18/2015 (6216.5 hours, 2854 Cycles);

Next HSI due: 9816.5 hours; next Overhaul due:

7200 hours; Hours until next HSI/Overhaul: 983.5 hours.

Part no: 31B4067-02, Engine, Turbofan PW305A,

Overhauled/Serviceable, Quantity: 1, Current Hours

Cycles: 7198.6 hours, 3246 Cycles;

Last HSI Completed: 09/30/2015 (7198.6 hours, 3246 Cycles);

Next HSI due: 10798.6 hours; Last Overhaul completed:

09/30/2015 (7198 hours, 3246 Cycles); next haul due:

14398.6 hours; Hours until next HSI/Overhaul: 3600 hours.

Part no: PRATT AND WHITNEY 31B4067-01