

7/26/11 N64057 CESSNA 182R S/N R18202024 ACTT 7123.1

TACH 1732.1
TSMO 1732.1
TSMO 199.0

ENGINE Lycoming O-540-J3C5D S/N L-19848-40A
PROPELLER McCauley B2D34C218 S/N 042589

100 Hour/Annual inspection completed as required by FAR 91.403 IAW Cessna Maintenance Manual 05-10-00. Performed ELT check IAW FAR 91.207 (d) requirements. Ops check OK. ELT battery replacement due 12/2011. C/W AD 2011-10-09 Seat slippage/seat roller housing. Found within limitations. Next due @ 1832.1 TACH. Inspected induction filter BA-2505. Replaced B3-5-1 Vacuum regulator filters. C/W SEB 99-16-R1 Vacuum system manifold check valve inspection/operation. No defects noted. Next due @ 2/2012. C/W AD 93-05-06 Ignition Switch Inspection/Lubrication. No defect noted. Next due @ 3134.3 TACH. Inspection panels opened. Pulleys, bell cranks, and hinges lubricated. Wheel bearings packed. No faults noted. Removed and replaced landing light GE4591. AD compliance currency check performed and updated.
I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH THE REQUIREMENTS FOR A 100 HR/ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. THIS AIRCRAFT RETURNED TO SERVICE.

George Hanzawa
George Hanzawa A&P/IA 3335928

10/14/11 N64057 CESSNA 182R S/N R18202024 ACTT 7224.0

TACH 1833.0
TSMO 1833.0
TSMO 299.9

ENGINE Lycoming O-540-J3C5D S/N L-19848-40A
PROPELLER McCauley B2D34C218 S/N 042589

100 Hour/Annual inspection completed as required by FAR 91.403 IAW Cessna Maintenance Manual 05-10-00. Performed ELT check IAW FAR 91.207 (d) requirements. Ops check OK. ELT battery replacement due 12/2011. C/W AD 2011-10-09 Seat slippage/seat roller housing. Found within limitations. Next due @ 1933.0 TACH. Inspected induction filter BA-2505. Replaced B3-5-1 Vacuum regulator filters. C/W SEB 99-16-R1 Vacuum system manifold check valve inspection/operation. No defects noted. Next due @ 6/2012. C/W AD 93-05-06 Ignition Switch Inspection/Lubrication. No defect noted. Next due @ 3134.3 TACH. Inspection panels opened. Pulleys, bell cranks, and hinges lubricated. Wheel bearings packed. No faults noted. Removed and replaced nose gear actuator hoses PN AE3663231E0096, AE3663231E0102. AD compliance currency check performed and updated.
I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH THE REQUIREMENTS FOR A 100 HR/ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. THIS AIRCRAFT RETURNED TO SERVICE.

George Hanzawa
George Hanzawa A&P/IA 3335928

2/2/12 N64057 CESSNA 182R S/N R18202024 ACTT 7324.2

TACH 1933.2
TSMO 1933.2
TSMO 400.1

ENGINE Lycoming O-540-J3C5D S/N L-19848-40A
PROPELLER McCauley B2D34C218 S/N 042589

100 Hour/Annual inspection completed as required by FAR 91.403 IAW Cessna Maintenance Manual 05-10-00. Removed and replaced ELT battery with new. Inspected and tested ELT IAW FAR 91.207 (d) requirements. Ops check OK. ELT battery replacement due 03/2014. C/W AD 2011-10-09 Seat slippage/seat roller housing. Found within limitations. Next due @ 2033.2 TACH. Inspected induction filter BA-2505. Replaced B3-5-1 Vacuum regulator filters. C/W SEB 99-16-R1 Vacuum system manifold check valve inspection/operation. No defects noted. Next due @ 2/2013. C/W AD 93-05-06 Ignition Switch Inspection/Lubrication. No defect noted. Next due @ 3134.3 TACH. Inspection panels opened. Pulleys, bell cranks, and hinges lubricated. Removed and replaced nose wheel tube. Wheel bearings packed. No faults noted. Removed and replaced landing & taxi light GE4591. Removed and replaced insight engine monitor that customer provided PN GEM2962 SN 5040. AD compliance currency check performed and updated.
I CERTIFY THAT THIS AIRFRAME HAS BEEN INSPECTED IN ACCORDANCE WITH THE REQUIREMENTS FOR A 100 HR/ANNUAL INSPECTION AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION. THIS AIRCRAFT RETURNED TO SERVICE.

George Hanzawa
George Hanzawa A&P/IA 3335928

THIS ELT EQUIPPED WITH ALKA-LINE BATTERY PACK P/N BP-1020
MAR 14
REPLACE BY
MERL, INC. 1777 N. Colony Rd. P.O. Box 188 Meriden, CT 06450
WARNING! DO NOT DISCARD BATTERY IN HEAT OR FIRE!

3/13/12 N64057 CESSNA 182R S/N R18202024 ACTT 7361.2

TACH 1970.2
TSMO 1970.2
TSMO 437.1

ENGINE Lycoming O-540-J3C5D S/N L-19848-40A
PROPELLER McCauley B2D34C218 S/N 042589

Repacked nose shimmy dampener. Removed and replaced nose wheel bearings. PN LM67048
George Hanzawa
George Hanzawa A&P/IA 3335928

SUB-TOTAL this page
TOTAL—Carry forward to next page