

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 1		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS ⊗	SYS A	DATE 15 Mar 17	NO 1	TIME 09:56	PID COLVARD, RON	DATE	TIME	ACFT HRS				
FAULTS/REMARKS USE OF PERSONAL RESTRAINT TETHER RESTRICTED PER H-60-17-ASAM-07						ROUNDS			ACTION CODE			WUC
						ACTION						
ACFT HRS 6577.1			WHEN DISC K	HOW REC G	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 02		TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 26 Mar 18	NO 3	TIME 08:57	PID HANSEN, TYREL	DATE	TIME	ACFT HRS				
FAULTS/REMARKS COMPLY WITH REQUIREMENTS OF THE ADDENDUM TO H-60-15-SOF-01 AT 8104.0 AIRCRAFT HOURS.						ROUNDS			ACTION CODE			WUC
						ACTION						
ACFT HRS 6739.1			WHEN DISC O	HOW REC G	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 04A08B		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 12 Jul 18	NO 2	TIME 12:09	PID TREMBLAY, PAU	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSTALLATION OF NO 1 ENGINE (2EA), NO 2 ENGINE (2EA), AND APU IR FLAME DETECTOR SENSOR, PN 70310-00800-101, REQUIRED PER H-60-18-AMAM-04 BY 10 JUL 20.						ROUNDS			ACTION CODE			WUC
						ACTION						
ACFT HRS 6797.8			WHEN DISC O	HOW REC G	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY Awaiting PMI				WUC 02		TIPIID ,			TI MANHOURS			

**DA FORM 2408-13-1-SG, OCT 1997**

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 2		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 04 Jan 19	NO 2	TIME 11:58	PID STLAURENT, JAI	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS INSTALL ANGLE BRACKETS FOR MR DE-ICE HARNESS PER H-60-19-AMAM-03, MR DE-ICE/CHIP DETECTOR HARNESS CHAFING AND RE-ROUTING, AT THE NEXT MAIN TRANSMISSION REMOVAL.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6849.8		WHEN DISC O	HOW REC G	MAL EFF 1								
DELAY ORDER PARTS UPON NEXT MAIN XMS						WUC 00		TIPIID ,		TI MANHOURS		
STATUS ⊗	SYS A	DATE 27 Mar 19	NO	TIME 11:01	PID GIORNO, NATAL	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS " RESCUE HOIST OPERATIONS RESTRICTED PER H-60-16-SOF-02" " SEE MSG"						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6870.6		WHEN DISC O	HOW REC O	MAL EFF 2								
DELAY						WUC 14A		TIPIID ,		TI MANHOURS		
STATUS /	SYS A	DATE 02 May 19	NO	TIME 15:11	PID THOMAS, STEPH	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS T/R DEICE STATOR BRUSH COVER IS CRACKED						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6884.6		WHEN DISC X	HOW REC G	MAL EFF 2								
DELAY Awaiting PMI						WUC 12E08		TIPIID ,		TI MANHOURS		

**DA FORM 2408-13-1-SG, OCT 1997**

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 3		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 08 May 19	NO	TIME 13:13	PID ALDRIDGE, SCO	DATE	TIME	ACFT HRS				
FAULTS/REMARKS R/H TRANSTION ACESS PANEL PIN HOLES ENLONGATED						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6896.8			WHEN DISC X	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY MAINTENANCE NOT BEING COMPLETED				WUC 00		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 08 May 19	NO	TIME 13:15	PID ALDRIDGE, SCO	DATE	TIME	ACFT HRS				
FAULTS/REMARKS AFT SOUNDPROOFING PANEL HAS MULTIPLE RIVITS NOT INSTALLED						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6896.8			WHEN DISC X	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY NEW PANEL IN SUPPLY				WUC 02B37		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 05 Jun 19	NO	TIME 16:54	PID GIORNO, NATAL	DATE	TIME	ACFT HRS				
FAULTS/REMARKS temporarily repair made on droop stop heater pin on red main rotor red blade using proseal . Droop stop heater pin was disbonding from housing. Will be replaced once parts come in.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 6918.3			WHEN DISC K	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY will not be repaired due to induction in				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 4		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 03 Sep 19	NO	TIME 21:21	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS MAINTENANCE FOR HOUSING ASSY MGB CAGE: 78286 PN: 70351-08110-045 NSN: 1615011101491 SN: A211-00956  INSTALLED ON MAIN TRANSMISSION MODULE CAGE: 78286 PN: 70351-08100-076 NSN: 1615015033115 SN: A265-00991.  IS DUE: 7066.0 AIRCRAFT HOURS ON HELICOPTER, UTILITY CAGE: 78286 PN:UH-60A NSN: 1520010350266 SN: 8123581						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 2901.3			WHEN DISC O	HOW REC O	MAL EFF 1							
DELAY			WUC 06A13			TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 03 Oct 19	NO	TIME 15:29	PID ALDRIDGE, SCO	DATE	TIME	ACFT HRS				
FAULTS/REMARKS 2ND 40 hour tq check due on left hand stab attachment fitting at 7016.5 acft hours						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6976.5			WHEN DISC O	HOW REC G	MAL EFF 2							
DELAY			WUC 02C15B			TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 17 Oct 19	NO	TIME 16:11	PID HARKER, CHRIS	DATE	TIME	ACFT HRS				
FAULTS/REMARKS #2 ENG LOWER INLET FAIRING HAS 1/2" CRACK AT FORWARD MOST BOLT HOLE						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6982.5			WHEN DISC K	HOW REC G	MAL EFF 1							
DELAY to be repaired at next 120 hour			WUC 04A11			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 5		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 24 Oct 19	NO	TIME 09:29	PID HARKER, CHRIS	DATE	TIME	ACFT HRS				
FAULTS/REMARKS #2 ENG AIR INLET LOWER FAIRING REAR UPPER SCREW MOUNT BROKEN OFF AIRFRAME.						ROUNDS	ACTION CODE	WUC				
						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6993.3		WHEN DISC K	HOW REC G	MAL EFF 1								
DELAY TO BE REPAIRED AT NEXT 120HR			WUC 04A11			TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 29 Oct 19	NO	TIME 15:52	PID DILLER, MATTHE	DATE	TIME	ACFT HRS				
FAULTS/REMARKS During the next PMI (Due @ 7097.8 ACFT HOURS) the Main Rotor Shaft Nut (PN 70103-08005-104) requires serial number be placed on Rotor Shaft Nut using a rubber stamp & then cover the number w/ a clear lacquer, a clear epoxy, or other suitable means (Due to their corrosive properties paint pens will not be used) Complete this all I/A/W H-60-19-ASAM-06 (Paragraph 8 -4th Note) Page 4 of 9  Serial # MSG192581 (2410 added on 29 OCT 19)						ROUNDS	ACTION CODE	WUC				
						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6993.3		WHEN DISC O	HOW REC G	MAL EFF 1								
DELAY			WUC 05A01G			TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 16 Nov 19	NO	TIME 15:40	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS MAINTENANCE FOR SERVO BEAM FITTING CAGE: 78286 PN: 70219-02134-046 NSN: 1560010957132 SN: A337-01182  INSTALLED ON HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581.  IS DUE: 7100.0 AIRCRAFT HOURS ON HELICOPTER, UTILITY CAGE: 78286 PN:UH-60A NSN: 1520010350266 SN: 8123581						ROUNDS	ACTION CODE	WUC				
						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 11D17			TIPIID ,			TI MANHOURS			

**DA FORM 2408-13-1-SG, OCT 1997**

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 6				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS —	SYS A	DATE 16 Nov 19	NO	TIME 15:40	PID Generated, Cor	DATE	TIME	ACFT HRS						
FAULTS/REMARKS MAINTENANCE FOR SERVO BEAM FITTING CAGE: 78286 PN: 70219-02134-046 NSN: 1560010957132 SN: F338-002277  INSTALLED ON HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581.  IS DUE: 7100.0 AIRCRAFT HOURS ON HELICOPTER, UTILITY CAGE: 78286 PN:UH-60A NSN: 1520010350266 SN: 8123581						ROUNDS			ACTION CODE			WUC		
						ACTION								
ACFT HRS 7014.6			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
DELAY				WUC 11D17		TIPIID ,			TI MANHOURS					
STATUS —	SYS A	DATE 16 Nov 19	NO	TIME 15:40	PID Generated, Com	DATE	TIME	ACFT HRS						
FAULTS/REMARKS MAINTENANCE FOR SERVO BEAM FITTING CAGE: 78286 PN: 70219-02134-046 NSN: 1560010957132 SN: A337-01182  INSTALLED ON HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581.  IS DUE: 7100.0 AIRCRAFT HOURS ON HELICOPTER, UTILITY CAGE: 78286 PN:UH-60A NSN: 1520010350266 SN: 8123581						ROUNDS			ACTION CODE			WUC		
						ACTION								
ACFT HRS 7014.6			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
DELAY				WUC 11D17		TIPIID ,			TI MANHOURS					
STATUS —	SYS A	DATE 16 Nov 19	NO	TIME 15:40	PID Generated, Com	DATE	TIME	ACFT HRS						
FAULTS/REMARKS MAINTENANCE FOR SERVO BEAM FITTING CAGE: 78286 PN: 70219-02134-046 NSN: 1560010957132 SN: F338-002277  INSTALLED ON HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581.  IS DUE: 7100.0 AIRCRAFT HOURS ON HELICOPTER, UTILITY CAGE: 78286 PN:UH-60A NSN: 1520010350266 SN: 8123581						ROUNDS			ACTION CODE			WUC		
						ACTION								
ACFT HRS 7014.6			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
DELAY				WUC 11D17		TIPIID ,			TI MANHOURS					
STATUS —	SYS A	DATE 16 Nov 19	NO	TIME 15:40	PID Generated, Com	DATE	TIME	ACFT HRS						
FAULTS/REMARKS MAINTENANCE FOR SERVO BEAM FITTING CAGE: 78286 PN: 70219-02134-046 NSN: 1560010957132 SN: F338-002277  INSTALLED ON HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581.  IS DUE: 7100.0 AIRCRAFT HOURS ON HELICOPTER, UTILITY CAGE: 78286 PN:UH-60A NSN: 1520010350266 SN: 8123581						ROUNDS			ACTION CODE			WUC		
						ACTION								
ACFT HRS 7014.6			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
DELAY				WUC 11D17		TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 7		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 16 Nov 19	NO	TIME 15:40	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS MAINTENANCE FOR SERVO BEAM FITTING CAGE: 78286 PN: 70219-02134-046 NSN: 1560010957132 SN: A337-01182  INSTALLED ON HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581.  IS DUE: 7100.0 AIRCRAFT HOURS ON HELICOPTER, UTILITY CAGE: 78286 PN:UH-60A NSN: 1520010350266 SN: 8123581						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 11D17	TIPID ,	TI MANHOURS				
STATUS —	SYS A	DATE 16 Nov 19	NO	TIME 15:40	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS MAINTENANCE FOR SERVO BEAM FITTING CAGE: 78286 PN: 70219-02134-046 NSN: 1560010957132 SN: F338-01471  INSTALLED ON HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581.  IS DUE: 7100.0 AIRCRAFT HOURS ON HELICOPTER, UTILITY CAGE: 78286 PN:UH-60A NSN: 1520010350266 SN: 8123581						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 11D17	TIPID ,	TI MANHOURS				
STATUS —	SYS A	DATE 16 Nov 19	NO	TIME 15:40	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS MAINTENANCE FOR SERVO BEAM FITTING CAGE: 78286 PN: 70219-02134-046 NSN: 1560010957132 SN: HN11874-2  INSTALLED ON HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581.  IS DUE: 7100.0 AIRCRAFT HOURS ON HELICOPTER, UTILITY CAGE: 78286 PN:UH-60A NSN: 1520010350266 SN: 8123581						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 11D17	TIPID ,	TI MANHOURS				

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 8				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS —	SYS A	DATE 16 Nov 19	NO	TIME 15:40	PID Generated, Cor	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS MAINTENANCE FOR SERVO BEAM FITTING CAGE: 78286 PN: 70219-02134-046 NSN: 1560010957132 SN: F338-01471  INSTALLED ON HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581.  IS DUE: 7100.0 AIRCRAFT HOURS ON HELICOPTER, UTILITY CAGE: 78286 PN:UH-60A NSN: 1520010350266 SN: 8123581						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY			WUC 11D17			TIPIID ,			TI MANHOURS					
STATUS —	SYS A	DATE 16 Nov 19	NO	TIME 15:40	PID Generated, Com	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS MAINTENANCE FOR SERVO BEAM FITTING CAGE: 78286 PN: 70219-02134-046 NSN: 1560010957132 SN: A337-01182  INSTALLED ON HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581.  IS DUE: 7100.0 AIRCRAFT HOURS ON HELICOPTER, UTILITY CAGE: 78286 PN:UH-60A NSN: 1520010350266 SN: 8123581						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY			WUC 11D17			TIPIID ,			TI MANHOURS					
STATUS —	SYS A	DATE 16 Nov 19	NO	TIME 15:40	PID Generated, Com	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS MAINTENANCE FOR SERVO BEAM FITTING CAGE: 78286 PN: 70219-02134-046 NSN: 1560010957132 SN: A337-01182  INSTALLED ON HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581.  IS DUE: 7100.0 AIRCRAFT HOURS ON HELICOPTER, UTILITY CAGE: 78286 PN:UH-60A NSN: 1520010350266 SN: 8123581						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY			WUC 11D17			TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00



1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 9		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 20 Nov 19	NO	TIME 15:38	PID GARLAND, JASC	DATE	TIME	ACFT HRS				
FAULTS/REMARKS MAIN MOD DRIP PAN SEAL DISBONDING						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7003.3			WHEN DISC K	HOW REC G	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 02B11A		TIPIID ,			TI MANHOURS			
STATUS —	SYS H	DATE 25 Nov 19	NO	TIME 08:18	PID GARLAND, JASC	DATE	TIME	ACFT HRS				
FAULTS/REMARKS OPERATIONAL CHECK DUE ON INTERNAL HOIST PRIOR TO USE						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7007.3			WHEN DISC X	HOW REC G	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 14A		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 26 Nov 19	NO	TIME 08:11	PID ALDRIDGE, SCO	DATE	TIME	ACFT HRS				
FAULTS/REMARKS 1ST HIT WITHIN 5 ON #2 ENGINE						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7011.3			WHEN DISC G	HOW REC D	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 04A		TIPIID ,			TI MANHOURS			

**DA FORM 2408-13-1-SG, OCT 1997**

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 10		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 05 Dec 19	NO	TIME 06:57	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS DAILY VISUAL INSPECTION DUE FOR INSTALLED EQUIPMENT IAW AWRs DATED AWR 1279 (WINDOWS/DOORS REMOVED) R8 15 MAY 18; AWR 1308 (INTERNAL RESCUE HOIST) R13 24 APR 19; AWR 1309 (OREGON SEAT COUSIONS) R11 11 APR 18; AWR 1346 (IVHMS) R25 21 NOV 17; AWR 1444 (SINGLE AHRS) R9 15 MAY 18; AWR 1516 (406 ELT) R12 07 FEB 19; AWR 1590 (147 MOUNTING BASE) R9 13 MAR 19; AWR 1607 (LED CDU/PDU) R10 28 MAR 18; AWR 1800 (BFT EDM) R8 28 MAR 19; AWR 1823 (BLOCK 5 IVHMS) R8 12 APR 19; AWR 1930 (PATIENT MOVEMENT ITEMS) R10 11 JAN 19.						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.1						WHEN DISC X	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TIPIID ,			TI MANHOURS
STATUS —	SYS A	DATE 05 Dec 19	NO	TIME 13:20	PID LIMOGES, MICH	DATE	TIME	ACFT HRS				
FAULTS/REMARKS MTF DUE FOR REPLACEMENT OF SDC						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.1						WHEN DISC M	HOW REC G	MAL EFF 2				
DELAY						WUC 02			TIPIID ,			TI MANHOURS
STATUS /	SYS A	DATE 06 Dec 19	NO	TIME 07:56	PID LIMOGES, MICH	DATE	TIME	ACFT HRS				
FAULTS/REMARKS XMSN DRIP PAN REMOVED FOR LEAK CHECK						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.1						WHEN DISC M	HOW REC G	MAL EFF 2				
DELAY						WUC 02			TIPIID ,			TI MANHOURS

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 11		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 10 Dec 19	NO	TIME 11:49	PID DEFREITAS, JESS	DATE	TIME	ACFT HRS				
FAULTS/REMARKS ENGINE SN GEE763247 CSM SN GEC003247 REQUIRES REPLACEMENT PER H-60-20-ASAM-02 BY 31 DEC 23.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.1			WHEN DISC O	HOW REC O	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 04A01		TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 10 Dec 19	NO	TIME 11:52	PID DEFREITAS, JESS	DATE	TIME	ACFT HRS				
FAULTS/REMARKS ENGINE SN GEE374965C CSM SN GEC003440 REQUIRES REPLACEMENT PER H-60-20-ASAM-02 BY 31 DEC 23.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.1			WHEN DISC O	HOW REC O	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 04A01		TIPIID ,			TI MANHOURS			
STATUS ×	SYS A	DATE 12 Dec 19	NO	TIME 15:34	PID RIEMER, JASON	DATE	TIME	ACFT HRS				
FAULTS/REMARKS main xmsn oil pressure fluctuates rapidly between 55 and 20 psi at steady hovering flight						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC M	HOW REC C	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 06A		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A				3. DATE				4. PAGE 12			
PART I - FAULT INFORMATION							PART II - CORRECTING INFORMATION								
STATUS X	SYS E	DATE 12 Dec 19	NO	TIME 15:37	PID RIEMER, JASON		DATE	TIME			ACFT HRS				
FAULTS/REMARKS UHF radio xmits but does not receive							ACTION								
ACFT HRS 7014.6				WHEN DISC M		HOW REC B		MAL EFF 2							
DELAY				WUC 19B				TIPIID ,				TI MANHOURS			
STATUS —	SYS A	DATE 14 Jan 20	NO	TIME 16:22	PID ALDRIDGE, SCO		DATE	TIME			ACFT HRS				
FAULTS/REMARKS 30 minute hover check due for replacement of pressure regulating valves per w/p 0834							ACTION								
ACFT HRS 7014.6				WHEN DISC K		HOW REC G		MAL EFF 1							
DELAY				WUC 00				TIPIID ,				TI MANHOURS			
STATUS /	SYS A	DATE 16 Jan 20	NO	TIME 15:33	PID MONTI, JOSEPH		DATE	TIME			ACFT HRS				
FAULTS/REMARKS proseal required on #1 and #2 accessory module upper and lower oil tubes after completion of 30/30 run up and leak check							ACTION								
ACFT HRS 7014.6				WHEN DISC B		HOW REC G		MAL EFF 1							
DELAY				WUC 00				TIPIID ,				TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 13		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 21 Jan 20	NO	TIME 11:03	PID MONTI, JOSEPH	DATE	TIME	ACFT HRS				
FAULTS/REMARKS cpc tail wheel fork wear pad due every 30 days (copy and paste write-up)						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC X	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 03B05B		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 21 Jan 20	NO	TIME 13:03	PID DILLER, MATTHE	DATE	TIME	ACFT HRS				
FAULTS/REMARKS Red M/R Damper Indicator has 1/4 gold band showing (Recommend Servicing prior to MTF)						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC B	HOW REC G	MAL EFF 3	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 05A01Z04		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 21 Jan 20	NO	TIME 14:55	PID RIEMER, JASON	DATE	TIME	ACFT HRS				
FAULTS/REMARKS xmsn oil pressure at 100% Nr reads 35 psi, needs to be 50-55 psi. Follow-on checks and adjustments to pressure regulating valves required IAW WP 852.						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC L	HOW REC G	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 06A		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 14		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 21 Jan 20	NO	TIME 15:02	PID RIEMER, JASON	DATE	TIME	ACFT HRS				
FAULTS/REMARKS during runup, xmsn oil bubbles out from bottom of housing along seam on aft half of housing, suspect housing failure						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6						WHEN DISC L	HOW REC G	MAL EFF 3				
DELAY						WUC 06A			TI MANHOURS			
STATUS —	SYS A	DATE 28 Jan 20	NO	TIME 08:33	PID DEFREITAS, JESS	DATE	TIME	ACFT HRS				
FAULTS/REMARKS PERFORM BORESCOPE INSPECTION OF THE ENGINE 1 ACCESSORY MODULE PER H-60-20-ASAM-03 AT OR BEFORE 7097.8 AIRCRAFT HOURS BUT NOT TO EXCEED 22 JAN 21.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 2				
DELAY						WUC 04A04			TI MANHOURS			
STATUS —	SYS A	DATE 28 Jan 20	NO	TIME 08:34	PID DEFREITAS, JESS	DATE	TIME	ACFT HRS				
FAULTS/REMARKS PERFORM BORESCOPE INSPECTION OF THE ENGINE 2 ACCESSORY MODULE PER H-60-20-ASAM-03 AT OR BEFORE 7097.8 AIRCRAFT HOURS BUT NOT TO EXCEED 22 JAN 21.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 2				
DELAY						WUC 04A04			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 15		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 29 Jan 20	NO	TIME 07:32	PID THOMAS, TRAC	DATE	TIME	ACFT HRS				
FAULTS/REMARKS removal of vor reciever in progress for troubleshooting						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC K	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 19E02A		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 04 Feb 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A103 AIRCRAFT WASH DUE FOR HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 03 FEB 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1500-344-23						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 04 Feb 20	NO	TIME 12:46	PID TREMBLAY, PAU	DATE	TIME	ACFT HRS				
FAULTS/REMARKS PERFORM OPERATIONAL CHECK OF FLIGHT CONTROLS IAW TM 1-1520-237-MTF.FOR REMOVAL OF LONG CONTROL ROD WP1322						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC L	HOW REC K	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 11		TIPIID ,			TI MANHOURS			

**DA FORM 2408-13-1-SG, OCT 1997**

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 16									
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION													
STATUS X		SYS E	DATE 05 Feb 20		NO	TIME 00:01		PID Generated, Cor			DATE		TIME		ACFT HRS				
											ROUNDS		ACTION CODE		WUC				
FAULTS/REMARKS INSP E801 PERFORM 10HR / 14 DAY VISUAL INSPECTION OF FM IMMUNE VOR / ILS FOR HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 7024.6 AIRCRAFT HOURS OR 04 FEB 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: AWR 1787 / AWR 1788						ACTION													
											PID		CAT		HRS				
ACFT HRS 7014.6		WHEN DISC O		HOW REC O		MAL EFF 1													
DELAY				WUC 00				TIPIID ,				TI MANHOURS							
STATUS X		SYS A	DATE 06 Feb 20		NO	TIME 00:00		PID Generated, Com			DATE		TIME		ACFT HRS				
											ROUNDS		ACTION CODE		WUC				
FAULTS/REMARKS INSP A022 14 DAY FLYABLE STORAGE ENGINE RUN UP FOR HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 05 FEB 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1520-237-23&P						ACTION													
											PID		CAT		HRS				
ACFT HRS 7014.6		WHEN DISC O		HOW REC O		MAL EFF 1													
DELAY				WUC 00				TIPIID ,				TI MANHOURS							
STATUS X		SYS A	DATE 07 Feb 20		NO	TIME 14:44		PID SAMSON, MATT			DATE		TIME		ACFT HRS				
											ROUNDS		ACTION CODE		WUC				
FAULTS/REMARKS REMOVAL OF TAIL ROTOR QUADRANT FOR CONTROL EXCHANGE						ACTION													
											PID		CAT		HRS				
ACFT HRS 7014.6		WHEN DISC K		HOW REC G		MAL EFF 1													
DELAY				WUC 11C08				TIPIID ,				TI MANHOURS							

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00



1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 17		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS E	DATE 08 Feb 20	NO	TIME 12:41	PID HOLLIS, JOHN	DATE 08 Feb 20	TIME 13:35	ACFT HRS 7014.6				
FAULTS/REMARKS Removal Of APR-39 System						ACTION Removal of APR-39 system completed						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6						WHEN DISC G	HOW REC G	MAL EFF 2				
DELAY						WUC 76A			TI MANHOURS			
STATUS X	SYS A	DATE 08 Feb 20	NO	TIME 19:49	PID SPEARS, RONAL	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE		WUC			
FAULTS/REMARKS Aircraft fold in process for ground transportation						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6						WHEN DISC K	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS X	SYS A	DATE 09 Feb 20	NO	TIME 10:53	PID Generated, Com	DATE	TIME	ACFT HRS				
						ROUNDS	ACTION CODE		WUC			
FAULTS/REMARKS STABILATOR REMOVED						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6						WHEN DISC O	HOW REC G	MAL EFF 2				
DELAY						WUC 00			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 18		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 09 Feb 20	NO	TIME 15:11	PID THIBEDAU, BRI	DATE	TIME	ACFT HRS				
FAULTS/REMARKS tail rotor blade fold for transport						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.6						WHEN DISC B	HOW REC G	MAL EFF 2				
DELAY						WUC 02			TIPIID ,			TI MANHOURS
STATUS X	SYS A	DATE 15 Feb 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A851 30 DAY LOG BOOK RECON FOR HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 14 FEB 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: FACILITY SOP						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPIID ,			TI MANHOURS
STATUS X	SYS A	DATE 17 Feb 20	NO	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A115 LUBE REQUIRMENTS FOR HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 16 FEB 2020 OR 7058.6 AIRCRAFT HOURS  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPIID ,			TI MANHOURS

**DA FORM 2408-13-1-SG, OCT 1997**

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 19		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS E	DATE 19 Feb 20	NO	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E040 APR-39 RADAR/LASER WARNING OPNL CHECK, 5841-01-236-8951 FOR HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 18 FEB 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 11-5841-294-12						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPIID ,			TI MANHOURS
STATUS X	SYS E	DATE 19 Feb 20	NO	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E125 KY-58 PMCS/OPNL CHECK FOR HELICOPTER, UTILITY CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 18 FEB 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 11-5810-262-23						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPIID ,			TI MANHOURS
STATUS —	SYS A	DATE 21 Feb 20	NO	TIME 13:05	PID HARKER, CHRIS	DATE	TIME	ACFT HRS				
FAULTS/REMARKS ENGINE GE-E-374965C AI/SBV LINK ASSEMBLY AND THE AI/SBV SHAFT QDP REQUIRES REPLACEMENT PER H-60-20-AMAM-03 BY 31DEC21						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.6						WHEN DISC O	HOW REC G	MAL EFF 1				
DELAY						WUC 04A09A			TIPIID ,			TI MANHOURS

**DA FORM 2408-13-1-SG, OCT 1997**

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 20		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 21 Feb 20	NO	TIME 13:06	PID HARKER, CHRIS	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS ENGINE GE-E-763247 AI/SBV LINK ASSEMBLY AND THE AI/SBV SHAFT QDP REQUIRES REPLACEMENT PER H-60-20-AMAM-03 BY 31DEC21						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC G	MAL EFF 1								
DELAY				WUC 04A09A		TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 21 Feb 20	NO	TIME 13:14	PID HARKER, CHRIS	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS ENGINE GE-E-374965C HMU CONTROL LINK AND THE VARIABLE GUIDE VANE ACTUATING SHAFT QDP REQUIRES REPLACEMENT PER H-60-20-AMAM-03 BY 31DEC21						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC G	MAL EFF 1								
DELAY				WUC 04A05A		TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 21 Feb 20	NO	TIME 13:15	PID HARKER, CHRIS	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS ENGINE GE-E-763247 HMU CONTROL LINK AND THE VARIABLE GUIDE VANE ACTUATING SHAFT QDP REQUIRES REPLACEMENT PER H-60-20-AMAM-03 BY 31DEC21						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC G	MAL EFF 1								
DELAY				WUC 04A05A		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 21				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS X	SYS E	DATE 02 Mar 20	NO	TIME 00:01	PID Generated, Cor	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS INSP E823 KY-100 FILL BATTERY REPLACEMENT DUE FOR HCPTU UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 01 MAR 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 11-5821-357-12						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY				WUC 00		TIPIID ,			TI MANHOURS					
STATUS X	SYS E	DATE 02 Mar 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS INSP E854 SINGARS C-CELL BATTERY REPLACEMENT FOR HCPTU UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 01 MAR 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 11-5841-33-12						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY				WUC 00		TIPIID ,			TI MANHOURS					
STATUS X	SYS A	DATE 10 Mar 20	NO	TIME 11:17	PID THOMAS, TRAC	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS Removal of avionics components for transfer in process						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC K	HOW REC G	MAL EFF 2										
DELAY				WUC 19		TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 22				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS X	SYS A	DATE 13 Mar 20	NO	TIME 00:01	PID Generated, Cor	DATE	TIME	ACFT HRS						
						ROUNDS	ACTION CODE	WUC						
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-20-AMAM-03 DESCRIPTION: COMPLY WITH H-60-20-AMAM-03, T700 HYDRO-MECHANICAL CONTROL UNIT AND ANTI-ICING START AND BLEED VALVE LINKAGE QUICK DISCONNECT PINS, BY 12 MAR 20. FOR T700-GE-701C ENGINE ASSY CAGE: 99207 PN: 6071T24G01 NSN: 2840012844011 SN: GEE763247 WAS DUE: 12 MAR 2020 CALENDAR						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 4195		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY			WUC 04A			TIPIID ,			TI MANHOURS					
STATUS X	SYS A	DATE 13 Mar 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS						
						ROUNDS	ACTION CODE	WUC						
FAULTS/REMARKS INSP A177 90 DAY REVIEW/UPDATE OF 365-4 ENTRIES FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 12 MAR 2020  REFERENCE: AR 95-1						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY			WUC 00			TIPIID ,			TI MANHOURS					
STATUS X	SYS A	DATE 13 Mar 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS						
						ROUNDS	ACTION CODE	WUC						
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-20-AMAM-03 DESCRIPTION: COMPLY WITH H-60-20-AMAM-03, T700 HYDRO-MECHANICAL CONTROL UNIT AND ANTI-ICING START AND BLEED VALVE LINKAGE QUICK DISCONNECT PINS, BY 12 MAR 20. FOR T700-GE-701C ENGINE ASSY CAGE: 99207 PN: 6071T24G01 NSN: 2840012844011 SN: GEE374965C WAS DUE: 12 MAR 2020 CALENDAR						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6804		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY			WUC 04A			TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 23		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 16 Mar 20	NO	TIME 00:01	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A108 AIRCRAFT BATTERY PMCS FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 15 MAR 2020 OR 7069.6 AIRCRAFT HOURS  ADDENDUM: EXTENSION AUTHORIZED IAW REGULATION  REFERENCE: TM 11-6140-203-23						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 18 Mar 20	NO	TIME 07:48	PID ALDRIDGE, SCO	DATE	TIME	ACFT HRS				
FAULTS/REMARKS BLADES REMOVED FOR TRANSPORT						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC S	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 30 Mar 20	NO	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A534 FIRST AID KIT INSPECTION FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 29 MAR 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1500-204-23-1						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 24		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS E	DATE 02 Apr 20	NO	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E015 ASN 128D DOPPLER GPS BATTERY REPLACEMENT FOR HCPT UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 01 APR 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: MWO 1-1520-237-50-92						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 05 Apr 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A092 30 DAY SLAB BATTERY INSPECTION (D8565/11-1) FOR HCPT UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 04 APR 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 11-6140-203-23 P						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS E	DATE 05 Apr 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E050 ARC-220 RADIO SET BATTERY INSPECTION OR REPLACE FOR HCPT UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 04 APR 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 11-5821-357-12P						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00



1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 25				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS X	SYS A	DATE 13 Apr 20	NO	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS						
						ROUNDS	ACTION CODE	WUC						
FAULTS/REMARKS INSP A502 INSPECT AND TEST GROUND RECEPTACLE IAW TM 1-1500-204-23 FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 12 APR 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1520-237-23&P						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY				WUC 00		TIPIID ,			TI MANHOURS					
STATUS —	SYS A	DATE 22 Apr 20	NO	TIME 10:33	PID LIMOGES, MICH	DATE	TIME	ACFT HRS						
						ROUNDS	ACTION CODE	WUC						
FAULTS/REMARKS COMPLY WITH REQUIREMENT OF H-60-20-ASAM-04 MAIN ROTOR BLADE TAP TEST INSPECTION @ 7097.8 ACFT HRS BUT NLT 20 APR 22						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC H	HOW REC G	MAL EFF 2										
DELAY				WUC 02		TIPIID ,			TI MANHOURS					
STATUS X	SYS A	DATE 23 Apr 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS						
						ROUNDS	ACTION CODE	WUC						
FAULTS/REMARKS INSP A230 INSPECT BATTERY COMPARTMENT FOR CORROSION (SLAB) FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 22 APR 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: MWO 1-1520-237-50-77						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY				WUC 00		TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 26		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 23 Apr 20	NO	TIME 00:01	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A160 90 DAY CORROSION INSPECTION FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 22 APR 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS E	DATE 25 Apr 20	NO	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E155 KY-58 BATTERY REPLACEMENT FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 24 APR 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 11-5810-262-23						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS E	DATE 30 Apr 20	NO	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E350 REPLACE APX-123 TRANSPONDER BATTERY FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 29 APR 2020  REFERENCE: TM 11-5895-1841-13 P						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 27		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS E	DATE 06 May 20	NO	TIME 00:01	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E145 AN/ARC-201A(V) SINGGARS HUB BATT REPL FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 05 MAY 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 11-5821-333-12						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPID ,	TI MANHOURS		
STATUS X	SYS A	DATE 12 May 20	NO	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A495 LUBRICATE WINDSHIELD WIPER CONVERTER (P/N 70209-01012-104) FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 11 MAY 2020  REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPID ,	TI MANHOURS		
STATUS ⊗	SYS A	DATE 19 May 20	NO	TIME 12:09	PID DEFREITAS, JESS	DATE	TIME	ACFT HRS				
FAULTS/REMARKS OPERATE WITHIN LIMITATIONS PRESCRIBED IN ENCLOSED AWRs DATED AWR 980 (FP SKED RESCUE SYS) R23 21 JUN 19; AWR 1279 (WINDOWS/ DOORS REMOVED) R8 15 MAY 18; AWR 1308 (INTERNAL RESCUE HOIST) R13 24 APR 19; AWR 1309 (OREGON SEAT COUSIONS) R11 11 APR 18; AWR 1346 (IVHMS) R25 21 NOV 17; AWR 1444 (SINGLE AHRS) R9 15 MAY 18; AWR 1452 (LC6 CLOCK) R7 22 APR 19; AWR 1455 (BATTELLE C/A PANEL) R8 31 OCT 19; AWR 1516 (406 ELT) R12 07 FEB 19; AWR 1566 (CABLE GUARD) R7 05 FEB 19; AWR 1590 (147 MOUNTING BASE) R10 25 MAR 20; AWR 1594 (H-60L W/ 701D) R7 22 NOV 19; AWR 1607 (LED CDU/PDU) R11 13 MAR 20;						ROUNDS	ACTION CODE	WUC				
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPID ,	TI MANHOURS		

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 28		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 28 May 20	NO	TIME 10:33	PID THIBEDAU, BRI	DATE	TIME	ACFT HRS				
FAULTS/REMARKS ENGINE #1 ELECTRICAL CHIP DETECTOR CANNON PLUG CONNETOR BROKEN						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC K	HOW REC G	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 02		TI MANHOURS						
STATUS X	SYS A	DATE 29 May 20	NO	TIME 14:17	PID SAMSON, MATT	DATE	TIME	ACFT HRS				
FAULTS/REMARKS removed #1 engine PCL handle						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC K	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY removed light spring to use in ACFT 013				WUC 11C08		TI MANHOURS						
STATUS X	SYS A	DATE 30 May 20	NO	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A538 FAT/OAT GAUGE INSPECTION/TEST FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 29 MAY 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 7014.6			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TI MANHOURS						

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 29		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 01 Jun 20	NO	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A532 COMPASS SWING / RMI FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 31 MAY 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1500-204-23-4						ROUNDS	ACTION CODE		WUC			
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 11 Jun 20	NO	TIME 08:50	PID MADJOUCOFF, T	DATE 11 Jun 20	TIME 09:04	ACFT HRS 7014.6				
FAULTS/REMARKS MAIN ROTOR PITCH LINKS 4EA. REMOVED TO FACILITATE OTHER MAINTRNANCE.						ROUNDS	ACTION CODE R		WUC 05A03C			
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC S	HOW REC A	MAL EFF 2								
DELAY			WUC 05A03C			TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 11 Jun 20	NO	TIME 09:22	PID LIMOGES, MICH	DATE	TIME	ACFT HRS				
FAULTS/REMARKS ELT REMOVED FOR ACFT TRANSFER						ROUNDS	ACTION CODE		WUC			
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC K	HOW REC G	MAL EFF 2								
DELAY			WUC 02			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 30				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS X	SYS A	DATE 11 Jun 20	NO	TIME 10:19	PID LIMOGES, MIC-	DATE	TIME	ACFT HRS						
FAULTS/REMARKS SAMPLES DUE FOR XMSN, TAIL ROTOR GEARBOX, INTERMEDIATE GEAR BOX, APU AND BOTH ENGINES AS AIRCRAFT HAS NOT BEEN RUN FOR OVER 90 DAYS						ROUNDS	ACTION CODE	WUC						
						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC K	HOW REC G	MAL EFF 2										
DELAY				WUC 02		TIPIID ,			TI MANHOURS					
STATUS X	SYS A	DATE 12 Jun 20	NO	TIME 07:18	PID GONZALEZ, RAF	DATE	TIME	ACFT HRS						
FAULTS/REMARKS removal of bft antenna for acft trasfer in progress						ROUNDS	ACTION CODE	WUC						
						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC K	HOW REC G	MAL EFF 2										
DELAY				WUC 19X		TIPIID ,			TI MANHOURS					
STATUS X	SYS A	DATE 12 Jun 20	NO	TIME 07:33	PID GONZALEZ, RAF	DATE	TIME	ACFT HRS						
FAULTS/REMARKS removal of cargo hook squib for acft transfer in progress						ROUNDS	ACTION CODE	WUC						
						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC K	HOW REC G	MAL EFF 2										
DELAY				WUC 16A01A		TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 31		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 16 Jun 20	NO	TIME 08:03	PID THOMAS, TRAC	DATE	TIME	ACFT HRS				
FAULTS/REMARKS ASN-128D gps/doppler set does not hold fills						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6						WHEN DISC G	HOW REC G	MAL EFF 2				
DELAY						WUC 19E04			TIPIID ,			TI MANHOURS
STATUS X	SYS E	DATE 23 Jun 20	NO	TIME 12:28	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E331 UNDER WATER ACOUSTIC BEACON TEST AND CLEAN FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 19 JUN 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1520-237-23_P						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPIID ,			TI MANHOURS
STATUS X	SYS A	DATE 26 Jun 20	NO	TIME 08:39	PID CRABB, ARLANA	DATE	TIME	ACFT HRS				
FAULTS/REMARKS DEPANELED FOR INDUCTION INTO BEST PROGRAM PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P, BEST SOW AND SES GOP AS A REFERENCE						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TIPIID ,			TI MANHOURS

**DA FORM 2408-13-1-SG, OCT 1997**

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 32		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 26 Jun 20	NO	TIME 08:40	PID CRABB, ARLAN/	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED APX TRANSPONDER TRANSMITTER CONTROL (SN 2235) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4361 AS A REFERENCE.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 26 Jun 20	NO	TIME 08:43	PID CRABB, ARLANA/	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED APX-118 TRANSPONDER RECIEVER-TRANSMITTER (SN 2716) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4362 AS A REFERENCE.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY				WUC 00		TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 26 Jun 20	NO	TIME 08:44	PID CRABB, ARLANA/	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED DOPPLER SDC ASN-128 (SN 3035) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4095 AS A REFERENCE.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00



1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 33		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 26 Jun 20	NO	TIME 08:48	PID CRABB, ARLAN/	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED DOPPLER CDU ASN-128 (SN 1777) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4097 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
ACTION												
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6		WHEN DISC E	HOW REC G	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS A	DATE 26 Jun 20	NO	TIME 08:49	PID CRABB, ARLANA/	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED DOPPLER RT/ANTENNA ASN-128 (SN 2596B) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4100						ROUNDS	ACTION CODE	WUC				
ACTION												
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6		WHEN DISC E	HOW REC G	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 26 Jun 20	NO	TIME 12:47	PID BRIDGES, ROBEF	DATE	TIME	ACFT HRS				
FAULTS/REMARKS AIRCRAFT INDUCTED INTO BEST PROGRAM ON 26 JUNE 2020, NO SCHEDULED MAINTENANCE PERFORMED AFTER THIS DATE.						ROUNDS	ACTION CODE	WUC				
ACTION												
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 7014.6		WHEN DISC E	HOW REC G	MAL EFF 2								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 34			
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION							
STATUS ⊗		SYS A	DATE 26 Jun 20		NO	TIME 12:49		PID Generated, Cor			ACFT HRS		
ROUNDS		ACTION CODE		WUC		DATE		TIME		ACFT HRS			
FAULTS/REMARKS REMARK/NOTICE TO BUYER: PRIOR TO DELIVERY OF THE AIRCRAFT TO THE BUYER THE FOLLOWING ITEMS WILL BE REMOVED FROM THE AIRCRAFT AT THE DIRECTION OF THE US GOVERNMENT; TO INCLUDE BUT NOT LIMITED TO: CMWS JUNCTION BOX; SA-26669/ALE-47 (V) CMWS SEQUENCER; SENSOR ELECTRO-OPTIC MISSILE CM-SU-202/AAR-57 (V); DIGITAL COCKPIT DISPLAY UNIT (CMWS); SAFE/ARM CONTROL PANEL (CMWS); CMWS RELAY BOX; MEMORY CARD PMCIA (UDM) MU-1126/AAR-57(V) (CMWS); RECEIVER/TRANSMITTER, RT-1477/ARC-201; CONTROL, C-11466A/ARC-201; KY-58(3EA); KY-58 CONTROL HEAD (3EA); KY-100 AIRTERM; ARC-220/						ACTION							
ACFT HRS 7014.6		WHEN DISC W		HOW REC G		MAL EFF 1		PID		CAT		HRS	
DELAY		WUC 00		TIPIID ,		TI MANHOURS		DATE		TIME		ACFT HRS	
STATUS —		SYS A	DATE 01 Jul 20		NO	TIME 08:24		PID BRIDGES, ROBEF			ACFT HRS		
ROUNDS		ACTION CODE		WUC		DATE		TIME		ACFT HRS			
FAULTS/REMARKS DURING THE BEST PROGRAM INDUCTION PROCEDURE, THE FOLLOWING COMPONENTS WERE UNABLE TO HAVE THE S/N'S VERIFIED. ALL OF THESE COMPONENTS HAVE BEEN S/N MATCHED AGAINST MCDS AND THE RECORDS MATCH BETWEEN ACN AND MCDS. THESE COMPONENTS REQUIRE S/N VERIFICATION AT THE NEXT MAJOR MAINT EVENT. ENGINE OIL COOLER, S/N: UDC03716; NUT ASSY, MAIN ROTOR, S/N: MSG192581; T/ R PITCH CHANGE SHAFT, S/N: B233-01303; AFT WALKING BEAM, S/N: 346-00093.						ACTION							
ACFT HRS 7014.6		WHEN DISC E		HOW REC G		MAL EFF 2		PID		CAT		HRS	
DELAY		WUC 00		TIPIID ,		TI MANHOURS		DATE		TIME		ACFT HRS	
STATUS —		SYS A	DATE 02 Jul 20		NO	TIME 00:01		PID Generated, Com			ACFT HRS		
ROUNDS		ACTION CODE		WUC		DATE		TIME		ACFT HRS			
FAULTS/REMARKS INSP A553 AIRCRAFT WEIGHING INVENTORY (365-1) FOR HCPTU UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 IS DUE. STATUS WILL UPGRADE TO X ON: 31 AUG 2020  REFERENCE: AR 95-1						ACTION							
ACFT HRS 7014.6		WHEN DISC O		HOW REC O		MAL EFF 1		PID		CAT		HRS	
DELAY		WUC 00		TIPIID ,		TI MANHOURS		DATE		TIME		ACFT HRS	

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 35		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 05 Jul 20	NO	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A302 LUBRICATE MAIN LANDING GEAR WHEEL BEARINGS FOR HCPT UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 IS DUE. STATUS WILL UPGRADE TO X ON: 7443.3 AIRCRAFT HOURS OR 03 SEP 2020  ADDENDUM: EXTENSION AUTHORIZED IAW REGULATION  REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TI MANHOURS						
STATUS X	SYS A	DATE 08 Jul 20	NO	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A299 LUBRICATE SWASHPLATE FOR HCPT UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 07 JUL 2020 OR 7403.3 AIRCRAFT HOURS  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TI MANHOURS						
STATUS X	SYS A	DATE 08 Jul 20	NO	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A533 PITOT STATIC SYSTEM INSPECTION FOR HCPT UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 07 JUL 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TI MANHOURS						

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 36				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS X	SYS E	DATE 15 Jul 20	NO	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS INSP E220 EMERGENCY LOCATOR TRANSMITTER SELF-TEST (AS REQUIRED) FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 14 JUL 2020 OR 7139.6 AIRCRAFT HOURS  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: AWR 1516 R12						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY				WUC 00		TIPIID ,			TI MANHOURS					
STATUS X	SYS A	DATE 15 Jul 20	NO	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS INSP A100 LH/RH ENGINE HISTORY RECORDER READINGS DUE FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 14 JUL 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: DA PAM 738-751						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY				WUC 00		TIPIID ,			TI MANHOURS					
STATUS X	SYS A	DATE 17 Jul 20	NO	TIME 00:04	PID Generated, Com	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-20-SOF-03 DESCRIPTION: T700 SERIES ENGINE POWER TURBINE MODULE NOZZLE SEAL RE-INSPECTION FOR POWER TURBINE MODULE CAGE: 99207 PN: 6071T26G02 NSN: 2840015031700 SN: GEL803090C WAS DUE: 16 JUL 2020 CALENDAR						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 5927		WHEN DISC O	HOW REC O	MAL EFF 1										
DELAY				WUC 04A03		TIPIID ,			TI MANHOURS					

**DA FORM 2408-13-1-SG, OCT 1997**

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 37		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 18 Jul 20	NO	TIME 00:00	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A496 CF3BR FIRE EXTINGUISHER WEIGHT TEST INSPECTION FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 IS DUE. STATUS WILL UPGRADE TO X ON: 23 AUG 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1520-237-23&P						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS X	SYS E	DATE 26 Jul 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E357 REPLACE APX-123 TRANSPONDER SAFT BATTERY FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 25 JUL 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 11-5895-1841-13P						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS —	SYS E	DATE 28 Jul 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E320 EMERGENCY LOCATOR TRANSMITTER G-SWITCH (EBC-406HM) FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 IS DUE. STATUS WILL UPGRADE TO X ON: 26 SEP 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: AWR 1516 R12						ROUNDS	ACTION CODE	WUC				
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 7014.6		WHEN DISC O	HOW REC O	MAL EFF 1								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 38		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 28 Jul 20	NO	TIME 00:01	PID Generated, Cor	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS INSP A501 MAIN ROTOR BLADE SPAR PRESSURE CHECK FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 8123581 WAS DUE. STATUS UPGRADED TO X ON: 27 JUL 2020  ADDENDUM: EXTENSION AUTHORIZED I/A/W REGULATION  REFERENCE: TM 1-1520-237-23&P						ACTION						
ACFT HRS 7014.6						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TIPIID ,			TI MANHOURS
STATUS X	SYS A	DATE 28 Jul 20	NO	TIME 13:27	PID BRIDGES, ROBEF	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS 2 EA TAIL ROTOR BLADES (A009-05657, A009-05972) WERE HISTORICALLY INSTALLED UNSERVICEABLE FOR INDUCTION INTO THE BEST PROGRAM.						ACTION						
ACFT HRS 7014.6						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 05B02			TIPIID ,			TI MANHOURS
STATUS X	SYS A	DATE 28 Jul 20	NO	TIME 13:30	PID BRIDGES, ROBEF	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS DURING BEST PROGRAM INDUCTION, TAIL ROTOR BLADE, S/N: A009-05657, WAS FOUND TO BE MISSING 2 EA TIP CAPS, 2 EA BOOTS, 1 EA FAIRING, 1 EA WEIGHT BRACKET, 2 E DE-ICE BRACKETS, AND 1 EA LEADING EDGE ABRASION STRIP.						ACTION						
ACFT HRS 7014.6						WHEN DISC E	HOW REC G	MAL EFF 2				
DELAY						WUC 05B02			TIPIID ,			TI MANHOURS

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 8123581				2. MODEL UH-60A			3. DATE			4. PAGE 39			
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION							
STATUS X		SYS A	DATE 28 Jul 20		NO	TIME 13:51		PID BRIDGES, ROBEI			ACFT HRS		
ROUNDS		ACTION CODE			WUC								
FAULTS/REMARKS 4 EA MAIN ROTOR BLADES, A007-03811, A007-04615, A007-05202, A007-08743, WERE HISTORICALLY INSTALLED UNSERVICEABLE FOR TRANSFER TO THE BEST PROGRAM.						ACTION							
ACFT HRS 7014.6		WHEN DISC E		HOW REC G		MAL EFF 2		PID		CAT		HRS	
DELAY			WUC 05A02			TIPIID ,			TI MANHOURS				
STATUS		SYS	DATE		NO	TIME		PID			ACFT HRS		
ROUNDS		ACTION CODE			WUC								
FAULTS/REMARKS						ACTION							
ACFT HRS		WHEN DISC		HOW REC		MAL EFF		PID		CAT		HRS	
DELAY			WUC			TIPIID			TI MANHOURS				
STATUS		SYS	DATE		NO	TIME		PID			ACFT HRS		
ROUNDS		ACTION CODE			WUC								
FAULTS/REMARKS						ACTION							
ACFT HRS		WHEN DISC		HOW REC		MAL EFF		PID		CAT		HRS	
DELAY			WUC			TIPIID			TI MANHOURS				
STATUS		SYS	DATE		NO	TIME		PID			ACFT HRS		
ROUNDS		ACTION CODE			WUC								
FAULTS/REMARKS						ACTION							
ACFT HRS		WHEN DISC		HOW REC		MAL EFF		PID		CAT		HRS	
DELAY			WUC			TIPIID			TI MANHOURS				

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

**AIRCRAFT INSPECTION AND MAINTENANCE RECORD**

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG













APD PE v3.00

1. STATUS —	2. SERIAL NUMBER 8123581	3. SYSTEM CODE A	4. TIME 06:57		
5. FAULT DATE 05 Dec 19		6. FAULT NUMBER			
7. FAULT DAILY VISUAL INSPECTION DUE FOR INSTALLED EQUIPMENT IAW AWRs DATED AWR 1279 (WINDOWS/DOORS REMOVED) R8 15 MAY 18; AWR 1308 (INTERNAL RESCUE HOIST) R13 24 APR 19; AWR 1309 (OREGON SEAT COUSIONS) R11 11 APR 18; AWR 1346 (IVHMS) R25 21 NOV 17; AWR 1444 (SINGLE AHRS) R8 15 MAY 18; AWR 1516 (406 ELT) R13 07 FEB 19; AWR 1590 (147 MOUNTING BASE) R8 13 MAR 19; AWR 1607 (LED CDU/PDU) R8 28 MAR 18; AWR 1800 (BFT EDM) R8 28 MAR 19; AWR 1823 (BLOCK 5 IVHMS) R8 12 APR 19; AWR 1930 (Patient Movement Items) R8 28 MAR 18.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
—	Perform visual inspection as required by AWR 1279 (WINDOWS/DOORS REMOVED), dated 15 MAY 18. A				
—	Perform visual inspection as required by AWR 1308 (INTERNAL RESCUE HOIST), dated 24 APR 19. A				
—	Perform visual inspection as required by AWR 1309 (OREGON SEAT COUSIONS), dated 11 APR 18. A				
—	Perform visual inspection as required by AWR 1346 (IVHMS), dated 21 NOV 17. A visual inspection, prior				
—	Perform visual inspection as required by AWR 1444 (SINGLE AHRS), dated 15 MAY 18. A visual inspection, prior				
—	Perform visual inspection as required by AWR 1516 (406 ELT), dated 07 FEB 19. A visual inspection, prior				
—	Perform visual inspection as required by AWR 1590 (147 MOUNTING BASE), dated 13 MAR 19. A visual				
—	Perform visual inspection as required by AWR 1607 (LED CDU/PDU), dated 28 MAR 18. A visual				
—	Perform visual inspection as required by AWR 1800 (BFT EDM), dated 28 MAR 19. A visual inspection,				
—	Perform visual inspection as required by AWR 1823 (BLOCK 5 IVHMS), dated 12 APR 19. A visual				
—	Perform visual inspection as required by AWR 1930 (Patient Movement Items), dated 28 MAR 18. A visual				

**DA FORM 2408-13-2-SG, OCT 97**  
 DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**  
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG









1. STATUS ×	2. SERIAL NUMBER 8123581	3. SYSTEM CODE A	4. TIME 15:34		
	5. FAULT DATE 12 Dec 19	6. FAULT NUMBER			
7. FAULT main xmsn oil pressure fluctuates rapidly between 55 and 20 psi at steady hovering flight					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	 REMOVED MAIN TRANSMISSION DRAIN PLUG	reinstalled tq to 60 inch pnds per w/p 0215	ROMANO, D	F	0.3
×	 REMOVED SAFETY FROM MAIN TRANSMISSION DRAIN PLUG	replaced safety	ROMANO, D	F	0.2
×	 Drained main transmission	serviced main transmission	MONTI, J.	F	0.8
×	 removed pump pressure regulating valves (2e/a)	replaced pump pressure regulating valves until seated per w/p 0852	ROMANO, D	F	0.3
×	 removed packings (4e/a) from pump pressure regulating valves	replaced packings	ALDRIDGE, S	F	0.4
—	 cci,fod check and toolbox inventory due	completed, hyd deck vacuuumed, box inventory completed for m8	MONTI, J.	F	0.6
—	Perform a functional check and check for leaks per w/p 0834				
×	 removed #1 and #2 UPPER accessory module drain screens (witches hats) from tube assemblies.	cleaned/inspected and reinstalled	MONTI, J.	F	0.5
×	 removes #1 and #2 UPPER accessory module drain tube retaining clips	replaced retaining rings	MONTI, J.	F	1.0
×	 removed #1 and #2 accessory module UPPER drain back tube o-rings	replaced orings	MONTI, J.	F	0.6
×	 removed #1 and #2 accessory mod LOWER drainback tube spring clips	replaced clips	MONTI, J.	F	0.4
×	 removed #1 and #2 accessory mod LOWER drain back tube o-rings	replaced orings	MONTI, J.	F	0.3
×	 removed #1 and #2 LOWER accessory module drain screens (witches hats) from tube assemblies.	cleaned and reinstalled	MONTI, J.	F	0.3

DA FORM 2408-13-2-SG, OCT 97

DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**

For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 8123581	3. SYSTEM CODE A	4. TIME 15:34		
5. FAULT DATE 12 Dec 19		6. FAULT NUMBER			
7. FAULT main xmsn oil pressure fluctuates rapidly between 55 and 20 psi at steady hovering flight					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	 moved #1 and #2 upper and lower accessory mod drain back tubes to aft position for inspection of fluid	installed in forward position with new orings an spring clips, awaiting	MONTI, J.	F	0.9
×	 removed clamp assemblies from #1 and #2 accessory mod lower drain tubes	reinstalled clamp assemblies	MONTI, J.	F	0.6
×	 removed sensor adapters from clamps on #1 and #2 accessory mod lower drainback tubes	reinstalled sensor adapters 2ea	MONTI, J.	F	0.2
—	 toolbox inventory due	completed	ROMANO, D	F	0.2
×	 remove drain plug oring	replaced	ROMANO, D	F	0.2
×	 removed safeties from pump pressure regulating valves (2e/a)	Replaced 2ea	ROMANO, D	F	0.2

DA FORM 2408-13-2-SG, OCT 97  
 DA FORM 2408-13-2, NOV 91, MAY BE USED









**RELATED MAINTENANCE ACTIONS RECORD**  
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG



1. STATUS ×	2. SERIAL NUMBER 8123581	3. SYSTEM CODE A	4. TIME 14:44		
5. FAULT DATE 07 Feb 20		6. FAULT NUMBER			
7. FAULT REMOVAL OF TAIL ROTOR QUADRANT FOR CONTROL EXCHANGE					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	Disconnected tail rotor quadrant spring cylinders hardware				
×	Removed l/ and r/h access panels on tail cone				
×	disconnected cables at quick-disconnects in tail cone				
×	Removed bolts, washers, and nuts securing pushrod to between tail rotor quadrant and tail rotor servo				
×	Removed screws, washers, and nuts securing cable guards to quadrant.				
×	Removed adjusting nuts and washers from right and left micro-switches				
×	Removed safety bolt (right-hand thread) and washer from nut at top of quadrant				
×	Removed large nut (left-hand thread) bushing, washer, and large washer.				
×	Removed quadrant with spring cylinders from tail gear box				
/	cci,fod check and toolbox inventory due				
/	QUADRANT ASSEMBLY NOT TORQUED TO FINAL SPEC. QUADRANT WAS NOT CONTROLLED				

**DA FORM 2408-13-2-SG, OCT 97**  
 DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**  
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG












1. STATUS ×	2. SERIAL NUMBER 8123581	3. SYSTEM CODE E	4. TIME 12:41		
	5. FAULT DATE 08 Feb 20	6. FAULT NUMBER			
7. FAULT Removal Of APR-39 System					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	 removed 4 screws from front left APR-39 Antenna	Screws removed due to component being removed	HOLLIS, J.	F	0.2
×	 removed p634R from left front APR-39 antenna	Stowed P634R	HOLLIS, J.	F	0.2
×	removed antenna serial number 2330AA		HOLLIS, J.	F	0.2
×	removed 4 screws from front right antenna	screws removed due to component being removed	HOLLIS, J.	F	0.2
×	disconnected P632R from antenna	stowed P632R	HOLLIS, J.	F	0.2
×	removed antenna sn:9184				
×	Disconnected P634R from antenna	Stowed P634R	HOLLIS, J.	F	0.2
×	 disconnected P706R and electrical connector AVR2B-P11	Stowed P706R and AVR2B-P11	HOLLIS, J.	F	0.2
×	 removed 4 screws and washers from APR-39 Processor	4 Screws and washers removed due to component being removed	HOLLIS, J.	F	0.2
×	 Removed apr-39 Processor NSN: 5898-01-395-7447, SN:1326 from Aircraft	Stowed Cannon Plugs and tied them back to prevent damage to	HOLLIS, J.	F	0.2
×	 remove hardware from APR-39 Display Unit	hardware removed due to component being removed	HOLLIS, J.	F	0.2
×	 remove P690R from APR-39 display unit	stowed P690R	HOLLIS, J.	F	0.2
×	 removed Display unit NSN: 5841-01-205-0658, PN:A3084060, SN:A0054CC From Aircraft	stowed cannon plug and tied back to prevent damage to cannon plug	HOLLIS, J.	F	0.2

DA FORM 2408-13-2-SG, OCT 97

DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**

For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 8123581	3. SYSTEM CODE E	4. TIME 12:41		
5. FAULT DATE 08 Feb 20		6. FAULT NUMBER			
7. FAULT Removal Of APR-39 System					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	 Disconnected P633R, P631R, P636R, P637R, and P635R from APR-39 FWD Receiver	Stowed P633R, P631R, P636R,P637R, and P635R	HOLLIS, J.	F	0.2
×	 Removed Hardware from APR-39 Receiver	Hardware removed due to component being removed	HOLLIS, J.	F	0.2
×	 Removed APR-39 FWD receiver NSN: 5841-01-204-8266 PN: A3084297, SN: 2188AA,	Stowed Cannon plugs and tied them back to prevent damage to	HOLLIS, J.	F	0.2
×	 removed 4 Screws from right AFT Antenna	screws removed due to component being removed	HOLLIS, J.	F	0.2
×	 removed 4 screws from left AFT APR-39 antenna	screws removed due to component being removed	HOLLIS, J.	F	0.2
×	 removed 3 screws from AFT APR-39 Receiver	removed screws due to component being removed	HOLLIS, J.	F	0.2
×	 disconnected P703R from Left Aft APR-39 Antenna	Stowed P703R	HOLLIS, J.	F	0.2
×	 Disconnected P705R from Right AFt APR-39 Antenna	Stowed P705R	HOLLIS, J.	F	0.2
×	removed right AFT APR-39 Antenna SN: 317				
×	remeved Left AFT APR-39 antenna SN:7783				
×	 Removed AFT APR-39 Receiver SN:0435	Stowed Cannon plugs and tied them back to prevent damage to	HOLLIS, J.	F	0.2
—	 FOD check required	Fod check complete	HOLLIS, J.	F	0.1
—	 CCI required	CCI complete	HOLLIS, J.	F	0.1

DA FORM 2408-13-2-SG, OCT 97  
DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**  
For use of this form see DA PAM 738-751, the proponent agency is DCSLOG



1. STATUS X	2. SERIAL NUMBER 8123581	3. SYSTEM CODE A	4. TIME 19:49		
	5. FAULT DATE 08 Feb 20	6. FAULT NUMBER			
7. FAULT Aircraft fold in process for ground transportation					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
X	Removed screws securing LH pilot step fairing to fuselage				
X	Removed screws securing RH pilot step fairing to fuselage				
X	Removed LH pilot step fairing from fuselage				
X	Removed RH pilot step fairing from fuselage				
X	Removed 4 screws securing LH pilot step to fairing				
X	Removed 4 screws securing RH pilot step to fairing				
X	Removed allen bolt securing LH pilot step to airframe				
X	Removed allen bolt securing RH pilot step to airframe				
X	Removed LH pilot step from airframe				
X	Removed RH pilot step from airframe				
X	Disconnected two electrical connectors for position light on LH pilot step fairing				
X	Disconnected two electrical connectors for position light on RH pilot step fairing				
X	REMOVED INTERMEDIATE GEARBOX COVER				

**DA FORM 2408-13-2-SG, OCT 97**  
 DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**  
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG



1. STATUS X	2. SERIAL NUMBER 8123581	3. SYSTEM CODE A	4. TIME 19:49		
5. FAULT DATE 08 Feb 20		6. FAULT NUMBER			
7. FAULT Aircraft fold in process for ground transportation					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
X	REMOVED LEFT SIDE TAIL STRUT ACCESS PANEL				
X	REMOVED ILOCKNUTS 2EA FROM FLIGHT CONTROL CABLE QUICK DISCONNECTS FORWARD OF STA 642.0				
X	SEPERATED FLIGHT CONTROL CABLES HALVES 2EA FORWARD OF STA 642				
X	DISCONNECTED ELECTRICAL CONNECTORS NEAR INTERMEDIATE GEARBOX AT STA 635.0				
X	REMOVED BOLTS (3EA), WASHERS, AND NUTS (3EA) CONNECTING TAIL DRIVE SHAFT TO INTERMEDIATE				
X	REMOVED BOLTS (4EA) AND WASHERS (4EA) ATTACHING PYLON TO TAIL CONE BULKHEAD				
X	INSTALLED PYLON FOLD STRUT ON PYLON AND TAILCONE				
X	FOLDED PYLON				
X	REMOVED TAIL PYLON JACKING POINT LOWER FAIRING				
X	REMOVED LH MLG UPPER/LOWER STRUT FAIRINGS FOR KNEELING OF AIRCRAFT				
X	REMOVED RH MLG UPPER/LOWER STRUT FAIRINGS FOR KNEELING OF AIRCRAFT				
X	REMOVED LH TAIL STRUT ACCESS PANEL FOR KNEELING OF AIRCRAFT				
—	CPC TREATMENT DUE FOR ALL SURFRACES/ HARDWARE EXPOSED FROM PANESL REMOVED FOR	TREATED WITH TYPE 2, COMPLETED	LIMOGES, M	F	1.0

DA FORM 2408-13-2-SG, OCT 97

DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**

For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS X		2. SERIAL NUMBER 8123581		3. SYSTEM CODE A		4. TIME 10:53	
		5. FAULT DATE 09 Feb 20		6. FAULT NUMBER			
7. FAULT STABILATOR REMOVED							
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH		
X	REMOVED LEFT STABILATOR -PYLON FAIRING.						
X	REMOVED RIGHT STABILATOR -PYLON FAIRING						
X	REMOVED LOWER PYLON FAIRING						
X	DISCONNECTED APR-39 LEADS (3EA).						
X	DISCONNECTED APR-39 GROUNDING STRAP						
X	DISCONNECTED BOTH FORMATION LIGHT CANNON PLUGS						
X	DISCONNECTED LIMIT SWITCH FROM STABILATOR.						
X	REMOVED STABILATOR ACTUATOR HDWR FROM STABILATOR.						
X	REMOVED RIGHT BONDING JUMPER.						
X	REMOVED LEFT BONDING JUMPER.						
X	REMOVED RIGHT STABILATOR BOLT.						
X	REMOVED LEFT STABILATOR BOLT						
X	REMOVED STABILATOR						

**DA FORM 2408-13-2-SG, OCT 97**  
 DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**  
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG



1. STATUS ×	2. SERIAL NUMBER 8123581	3. SYSTEM CODE A	4. TIME 15:11		
5. FAULT DATE 09 Feb 20		6. FAULT NUMBER			
7. FAULT tail rotor blade fold for transport					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	disconnect deice electrical connectors (4ea)				
×	removed hardware from pitch control rods at pitch beam				
×	removed pitch control rods and bonding jumpers from pitch beam				
×	removed outboard retention plate hardware				
—	tool box, fod check, and cci due				
×	REMOVED PITCHBEAM NUT SCREWS AND SAFETY				
×	REMOVED PITCHBEAM NUT				
×	REMOVED PITCH BEAM				

DA FORM 2408-13-2-SG, OCT 97  
 DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**  
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 8123581	3. SYSTEM CODE A	4. TIME 11:17		
	5. FAULT DATE 10 Mar 20	6. FAULT NUMBER			
7. FAULT Removal of avionics compenents for transfer in process					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	Removed 2 FM RCU's	Secured wire harnesses	THOMAS, T.	F	2.0
×	Removed UHF r/t	secured wire harness	THOMAS, T.	F	2.0
×	Removed KY-100 amp	secured wire harness	THOMAS, T.	F	2.0
×	Removed 2 KY58 RCUs	secured wire harnesses	THOMAS, T.	F	2.0
×	removed 2 ky58 amps	secured wire harnesses	THOMAS, T.	F	2.0
×	Removed HUD SDC	secured wire harness	THOMAS, T.	F	2.0
×	removed hud ccu	secured wire harness	THOMAS, T.	F	2.0
×	Removed HF RCU, R/t and coupler	secured wire harnesses	THOMAS, T.	F	2.0
×	Removed apr-39 processor	secured wire harness	THOMAS, T.	F	2.0
×	Removed IVHMU	secured wire harness	THOMAS, T.	F	2.0
×	Removed BFT pallet	did not reinstall	GONZALEZ,	F	2.0
×	removed ivhmu rdc	did not reinstall	GONZALEZ,	F	2.0
×	removed IVHMU display and DTU	did not reinstall	THOMAS, T.	F	2.0

**DA FORM 2408-13-2-SG, OCT 97**

DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**

For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 8123581	3. SYSTEM CODE A	4. TIME 11:17		
	5. FAULT DATE 10 Mar 20	6. FAULT NUMBER			
7. FAULT Removal of avionics compenents for transfer in process					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	Removed apr-39 receivers and antennas	did not reinstall	HOLLIS, J.	F	6.0
—	fod check, toolbox inventory and cci due	complete	THOMAS, T.	F	2.0
×	Removed ELT	Did not reinstalled	THOMAS, T.	F	0.5
×	Removed 2 flare dispenser mounts	Did not reinstall	THOMAS, T.	F	0.5
×	removed IVHMU RDC	did not reinstall	GONZALEZ,	F	0.5
×	removed APR-39 display unit	did not reinstall	GONZALEZ,	F	0.5
×	removed APR-39 control head	did not reinstall	GONZALEZ,	F	0.2
×	removed arc-201 control head	did not reinstall	GONZALEZ,	F	0.5
×	removed arc-201 RT	did not reinstall	GONZALEZ,	F	0.5
×	removed arc-201 power amp	did not reinstall	GONZALEZ,	F	0.5
×	removed ELT mounting bracket	did not reinstall	GONZALEZ,	F	0.2
×	removed arc 220 power amp	did not reinstall	GONZALEZ,	F	0.5
×	removed cmws safe arm switch	did not reinstall	GONZALEZ,	F	0.2

DA FORM 2408-13-2-SG, OCT 97

DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD

For use of this form see DA PAM 738-751, the proponent agency is DCSLOG



1. STATUS ×	2. SERIAL NUMBER 8123581	3. SYSTEM CODE A	4. TIME 07:48		
5. FAULT DATE 18 Mar 20		6. FAULT NUMBER			
7. FAULT BLADES REMOVED FOR TRANSPORT					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	DISCONNECTED 4 EA M/R BLADE DEICE CANNON PLUGS				
×	DISCONNECTED 4 EA M/R BLADE ANTI-FLAP CAM SPRINGS				
×	REMOVED ALL M/R BLADE PINS				
×	REMOVED ALL M/R BLADES				
—	TOOL INVENTORY DUE				
—	FOD CHECK DUE				

**DA FORM 2408-13-2-SG, OCT 97**  
 DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**  
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG



1. STATUS ×	2. SERIAL NUMBER 8123581	3. SYSTEM CODE A		4. TIME 14:17	
	5. FAULT DATE 29 May 20	6. FAULT NUMBER			
7. FAULT removed #1 engine PCL handle					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	removed screws 3ea from PCL handle	reinstalled 3ea	SAMSON, M	F	0.3
×	removed spring, bolt, nut, washers (2ea), and spacers (2ea) from PCL handle	reinstalled	SAMSON, M	F	0.3
×	removed PCL handle	reinstalled	SAMSON, M	F	0.2
×	removed heavy spring from handle	reinstalled	SAMSON, M	F	0.1
×	removed light spring from handle	reinstalled	SAMSON, M	F	0.1
×	removed cotter pin				

**DA FORM 2408-13-2-SG, OCT 97**  
 DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**  
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 8123581	3. SYSTEM CODE A	4. TIME 08:50		
5. FAULT DATE 11 Jun 20		6. FAULT NUMBER			
7. FAULT MAIN ROTOR PITCH LINKS 4EA. REMOVED TO FACILITATE OTHER MAINTRNANCE.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
×	REMOVED. SAFETY WIRE FROM PCR'S 8EA.				
×	BROKE TORQUE ON MAIN ROTOR PCR'S 8EA.				
×	REMOVED. COTTER PINS FROM MAIN ROTOR PCR ATTACHMENT HDWR. 8EA.				
×	REMOVED. MAIN ROTOR PCR ATTACHMENT HDWR. 8EA.	REINSTALLED. 8EA. (NOT TORQUED)	MADJOUCO	F	0.5
×	REMOVED. MAIN ROTOR PCR ASSEMBLIES 4EA.	REPLACED 4EA.	MADJOUCO	F	3.1
—	CCI, FOD CHECK, TOOL INVENTORY DUE.	COMPLETED.	MADJOUCO	F	0.2
×	MAIN ROTOR PCR ATTACHMENT HDWR. NOT TORQUED!! 8EA.				

DA FORM 2408-13-2-SG, OCT 97  
 DA FORM 2408-13-2, NOV 91, MAY BE USED

**RELATED MAINTENANCE ACTIONS RECORD**  
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG



