

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 1		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 22 Feb 18	NO 6	TIME 09:12	PID Conversion, Ulls	DATE	TIME	ACFT HRS				
FAULTS/REMARKS #2 UPPER CARGO DOOR TRACK FAIRING CRACKED BY ENGINE COWLING FWD HINGE (100% QA)						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 5614.9			WHEN DISC B	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY WILL REPAIR AT 40HR PMS @6045.9				WUC 02B		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 12 Jun 18	NO 6	TIME 06:53	PID Conversion, Ulls	DATE	TIME	ACFT HRS				
FAULTS/REMARKS L AFT LOWER APU PANEL SCREW NUT PLATE NOT INSTALLED						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 5635.6			WHEN DISC K	HOW REC G	MAL EFF 3	PID	CAT	HRS	PID	CAT	HRS	
DELAY WILL REPAIR AT 40HR PMS @6045.9				WUC 15A		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 02 Jan 19	NO 4	TIME 12:04	PID FERNANDEZ, JO	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSTALL ANGLE BRACKETS FOR MR DE-ICE HARNESS PER H-60-19- AMAM-03, MR DE-ICE/CHIP DETECTOR HARNESS CHAFING AND RE- ROUTING, AT THE NEXT MAIN TRANSMISSION REMOVAL						ROUNDS	ACTION CODE	WUC				
						ACTION						
ACFT HRS 5768.1			WHEN DISC K	HOW REC G	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY DUE AT NEXT TRANSMISSION REMOVAL				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 2						
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION										
STATUS —		SYS A	DATE 17 Jul 19		NO	TIME 13:12	PID MCINTIRE, MAR			DATE		TIME	ACFT HRS			
FAULTS/REMARKS TAIL ROTOR GEARBOX ASSY, S/N A006-00858 WITH INBOARD RETENTION PLATE S/N C25900997, REQUIRES REPLACEMENT PER H-60-19-AMAM-09 AT 6085.9 ACFT FLIGHT HOURS BUT NOT TO EXCEED 30 JUL 23. (UPON REMOVAL, QC CONTACT POC GEORGE PROSNIK DSN: 746-4706 FOR FURTHER GUIDANCE)						ACTION						ROUNDS		ACTION CODE	WUC	
ACFT HRS 5918.9		WHEN DISC O		HOW REC G		MAL EFF 2		PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
DELAY				WUC 06G				TIPIID ,			TI MANHOURS					
STATUS /		SYS A	DATE 16 Aug 19		NO	TIME 11:49	PID DARNELL, DAVI			DATE		TIME	ACFT HRS			
FAULTS/REMARKS LOWER FASTENER NUT PLATE ON FORWARD END OF R/H BROOM CLOSET DAMAGED WILL NOT LATCH						ACTION						ROUNDS		ACTION CODE	WUC	
ACFT HRS 5923.2		WHEN DISC X		HOW REC G		MAL EFF 1		PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
DELAY WILL REPAIR AT 40HR PMS @6045.9				WUC 02				TIPIID ,			TI MANHOURS					
STATUS /		SYS A	DATE 30 Oct 19		NO	TIME 08:57	PID MCINTIRE, MAR			DATE		TIME	ACFT HRS			
FAULTS/REMARKS S/N/P/N VERIFICATION REQUIRED FOR MAIN ROTOR SHAFT NUT AT NEXT PMI(6085.9 ACFT FLIGHT HOURS) IAW H-60-19-ASAM-06.						ACTION						ROUNDS		ACTION CODE	WUC	
ACFT HRS 5956.8		WHEN DISC O		HOW REC G		MAL EFF 2		PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
DELAY TO BE COMPLETED AT NEXT PMI 6085.9				WUC 05A01G				TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 3		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 25 Mar 20	NO	TIME 09:58	PID KEMP, KYLE	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS SEALING COMPOUND DETERIORATED AROUND T/R MAG PICKUP BRACKET TO GEARBOX HOUSING						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6011.4		WHEN DISC O	HOW REC G	MAL EFF 1								
DELAY			WUC 12E08			TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 25 Mar 20	NO	TIME 11:33	PID LAKE, BRANDON	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS FWD SECTION2 T/R DRIVESHAFT COVER CRACKED APPROXIMATELY 6 INCHES BACK FROM FWD EDGE ON L/H SIDE						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6011.4		WHEN DISC O	HOW REC G	MAL EFF 2								
DELAY AWAITING SHEETMETAL			WUC 02C12H			TIPIID ,			TI MANHOURS			
STATUS ⊗	SYS E	DATE 24 Apr 20	NO	TIME 09:32	PID BOUDREAUX, PA	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS Aircraft restricted from ILS use in IMC, roll command bar, course deviation bar, deviating 30* left then right.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	PID
ACFT HRS 6016.1		WHEN DISC G	HOW REC G	MAL EFF 4								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 4		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 07 May 20	NO	TIME 23:32	PID WILDE, BRENN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS Pilot windshield anti ice was inop. It was clear that it never warmed up or evaporated the rain as the middle and co pilot windshields.						ROUNDS		ACTION CODE		WUC		
						ACTION						
ACFT HRS 6024.6			WHEN DISC G	HOW REC K	MAL EFF 4	PID	CAT	HRS	PID	CAT	HRS	
DELAY TROUBLESHOT REQUIRES REPLACEMENT						WUC 00		TIPIID ,		TI MANHOURS		
STATUS ⊗	SYS A	DATE 27 May 20	NO	TIME 09:10	PID VAUGHN, JUSTII	DATE	TIME	ACFT HRS				
FAULTS/REMARKS OPERATE WITHIN LIMITATIONS AND RESTRICTIONS SPECIFIED IN; (AWR 2122 R5, DATED 09AUG19) (AWR 2120 R3, DATED 27 SEP 19) (AWR 2064 R1, DATED 20 NOV 19) (AWR 2000 R10, DATED 09 SEP 19) (AWR 1965 R9, DATED 18 MAY 20) (AWR 1956 R3, DATED 31 OCT 18) (AWR 1939 R3, DATED 10 MAR 20) (AWR 1913 R3, DATED 26 JAN 18) (AWR 1833 R8, DATED 08 JUL 18) (AWR 1823 R8, DATED 12 APR 19) (AWR 1805 R1, DATED 20 MAR 19) (AWR 1801 R20, DATED 30 AUG 18) (AWR 1800 R9, DATED 18 JUL 19) (AWR 1788 R7, DATED 04 JAN 18) (AWR 1776 R10, DATED 17 MAY 17) ((AWR 1753 R9, DATED 17 APR 20) (AWR 1750 R6, DATED 31 MAR 20) (AWR 1708 R7, DATED						ROUNDS		ACTION CODE		WUC		
						ACTION						
ACFT HRS 6032.2			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY						WUC 00		TIPIID ,		TI MANHOURS		
STATUS —	SYS A	DATE 03 Jun 20	NO	TIME 00:36	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A400 PMI-1.						ROUNDS		ACTION CODE		WUC		
						ACTION						
ACFT HRS 6038.8			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY						WUC 00		TIPIID ,		TI MANHOURS		

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 5				
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION								
STATUS —	SYS A	DATE 15 Jul 20	NO	TIME 10:56	PID MAZE, ROBERT	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS 3-13 HOUR TQ CHECK REQ ON NO.1 ENG HIGHSPEED SHAFT, DUE AT ACFT HOURS 6063.4-6073.4						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6060.4		WHEN DISC K	HOW REC G	MAL EFF 1										
DELAY			WUC 04			TIPIID ,			TI MANHOURS					
STATUS —	SYS A	DATE 15 Jul 20	NO	TIME 11:00	PID MAZE, ROBERT	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS 3-13 HOUR TQ CHECK REQ ON NO.2 ENG HIGHSPEED SHAFT, DUE AT ACFT HOURS 6063.4-6073.4						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6060.4		WHEN DISC K	HOW REC G	MAL EFF 1										
DELAY			WUC 04			TIPIID ,			TI MANHOURS					
STATUS /	SYS A	DATE 21 Jul 20	NO	TIME 12:54	PID TYLER, CASEY	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC			
FAULTS/REMARKS IVHMU CDU BRIGHT/DIM ADJUST WOULD ONLY ADJUST THE LETTERING, NOT THE BACKGROUND						ACTION								
						PID	CAT	HRS	PID	CAT	HRS	PID	CAT	HRS
ACFT HRS 6060.4		WHEN DISC L	HOW REC G	MAL EFF 4										
DELAY Awaiting AVN			WUC 08F01			TIPIID ,			TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 6		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS /	SYS A	DATE 24 Jul 20	NO	TIME 08:45	PID HICKS, JACOB	DATE	TIME	ACFT HRS				
FAULTS/REMARKS PRO SEAL NOT INSTALLED AROUND YAW TRIM SERVO						ROUNDS		ACTION CODE		WUC		
						ACTION						
ACFT HRS 6060.4			WHEN DISC K	HOW REC G	MAL EFF 2	PID	CAT	HRS	PID	CAT	HRS	
DELAY PRO SEAL ON ORDER				WUC 11C06		TIPIID ,			TI MANHOURS			
STATUS /	SYS A	DATE 07 Aug 20	NO	TIME 14:27	PID BOWMAN, BRAI	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVAL OF PROPERTY BOOK ITEMS REQUIRED FOR ACFT TRANSFER TO BEST PROGRAM.						ROUNDS		ACTION CODE		WUC		
						ACTION						
ACFT HRS 6062.9			WHEN DISC B	HOW REC G	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 02		TIPIID ,			TI MANHOURS			
STATUS —	SYS A	DATE 22 Aug 20	NO	TIME 00:00	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A802 TDFM-9000 NV CIVIL COMMUNICATIONS SYSTEM FOR HCPT UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923282 IS DUE. STATUS WILL UPGRADE TO X ON: 01 SEP 2020 REFERENCE: AWR 2122						ROUNDS		ACTION CODE		WUC		
						ACTION						
ACFT HRS 6065.5			WHEN DISC O	HOW REC O	MAL EFF 1	PID	CAT	HRS	PID	CAT	HRS	
DELAY				WUC 00		TIPIID ,			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 7		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS E	DATE 23 Aug 20	NO	TIME 00:01	PID Generated, Cor	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP E800 PERFORM 10 HOUR 14 DAY VISUAL INSPECTION IAW AWR 1788 (AN ARN-147 VOR/ILS RECIEVER) FOR HCPTTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923282 IS DUE. STATUS WILL UPGRADE TO X ON: 6075.9 AIRCRAFT HOURS OR 29 AUG 2020 REFERENCE: AWR 1788						ROUNDS	ACTION CODE	WUC				
ACFT HRS 6065.5						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS —	SYS A	DATE 25 Aug 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A230 INSPECT BATTERY COMPARTMENT FOR CORROSION (SLAB) FOR HCPTTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923282 IS DUE. STATUS WILL UPGRADE TO X ON: 18 SEP 2020 REFERENCE: MWO 1-1520-237-50-77						ROUNDS	ACTION CODE	WUC				
ACFT HRS 6065.5						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS —	SYS A	DATE 29 Aug 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A108 AIRCRAFT BATTERY PMCS FOR HCPTTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923282 IS DUE. STATUS WILL UPGRADE TO X ON: 6116.4 AIRCRAFT HOURS OR 04 SEP 2020 REFERENCE: TM 11-6140-203-23						ROUNDS	ACTION CODE	WUC				
ACFT HRS 6065.5						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 8							
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION											
STATUS X		SYS A	DATE 29 Aug 20		NO	TIME 00:01		PID Generated, Cor			DATE		TIME		ACFT HRS		
											ROUNDS		ACTION CODE		WUC		
FAULTS/REMARKS INSP A115 LUBE REQUIRMENTS FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923282 WAS DUE. STATUS UPGRADED TO X ON: 6105.4 AIRCRAFT HOURS OR 28 AUG 2020 REFERENCE: TM 1-1520-237-23&P						ACTION											
											PID		CAT		HRS		
ACFT HRS 6065.5		WHEN DISC O		HOW REC O		MAL EFF 1											
DELAY				WUC 00				TIPIID ,				TI MANHOURS					
STATUS X		SYS A	DATE 29 Aug 20		NO	TIME 00:01		PID Generated, Com			DATE		TIME		ACFT HRS		
											ROUNDS		ACTION CODE		WUC		
FAULTS/REMARKS INSP A103 AIRCRAFT WASH DUE FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923282 WAS DUE. STATUS UPGRADED TO X ON: 28 AUG 2020 REFERENCE: TM 1-1500-344-23						ACTION											
											PID		CAT		HRS		
ACFT HRS 6065.5		WHEN DISC O		HOW REC O		MAL EFF 1											
DELAY				WUC 00				TIPIID ,				TI MANHOURS					
STATUS X		SYS A	DATE 31 Aug 20		NO	TIME 00:01		PID Generated, Com			DATE		TIME		ACFT HRS		
											ROUNDS		ACTION CODE		WUC		
FAULTS/REMARKS INSP A501 MAIN ROTOR BLADE SPAR PRESSURE CHECK FOR HCPTX UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923282 WAS DUE. STATUS UPGRADED TO X ON: 30 AUG 2020 REFERENCE: TM 1-1520-237-23&P						ACTION											
											PID		CAT		HRS		
ACFT HRS 6065.5		WHEN DISC O		HOW REC O		MAL EFF 1											
DELAY				WUC 00				TIPIID ,				TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 9							
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION											
STATUS —		SYS A	DATE 01 Sep 20		NO	TIME 08:28		PID Generated, Cor			DATE		TIME		ACFT HRS		
											ROUNDS		ACTION CODE		WUC		
FAULTS/REMARKS SAFETY MESSAGE NUMBER: H-60-20-ASAM-09 DESCRIPTION: H-60-20-ASAM-09, NON-CONFORMING TAIL ROTOR PUSHROD CLEVIS ROD END. IS DUE: 06 SEP 2020 CALENDAR						ACTION											
											PID		CAT		HRS		
ACFT HRS 6065.5		WHEN DISC O		HOW REC O		MAL EFF 1											
DELAY				WUC 00				TIPIID ,				TI MANHOURS					
STATUS —		SYS A	DATE 02 Sep 20		NO	TIME 13:12		PID BRIDGES, ROBEF			DATE		TIME		ACFT HRS		
											ROUNDS		ACTION CODE		WUC		
FAULTS/REMARKS AIRCRAFT INDUCTED INTO BEST PROGRAM ON 02 SEPTEMBER AUGUST 2020, NO SCHEDULED MAINTENANCE PERFORMED AFTER THIS DATE.						ACTION											
											PID		CAT		HRS		
ACFT HRS 6065.5		WHEN DISC E		HOW REC G		MAL EFF 2											
DELAY				WUC 00				TIPIID ,				TI MANHOURS					
STATUS ⊗		SYS A	DATE 02 Sep 20		NO	TIME 13:15		PID Generated, Com			DATE		TIME		ACFT HRS		
											ROUNDS		ACTION CODE		WUC		
FAULTS/REMARKS REMARK/NOTICE TO BUYER: PRIOR TO DELIVERY OF THE AIRCRAFT TO THE BUYER THE FOLLOWING ITEMS WILL BE REMOVED FROM THE AIRCRAFT AT THE DIRECTION OF THE US GOVERNMENT; TO INCLUDE BUT NOT LIMITED TO: CMWS JUNCTION BOX; SA-26669/ALE-47 (V) CMWS SEQUENCER; SENSOR ELECTRO-OPTIC MISSILE CM-SU-202/AAR-57 (V); DIGITAL COCKPIT DISPLAY UNIT (CMWS); SAFE/ARM CONTROL PANEL (CMWS); CMWS RELAY BOX; MEMORY CARD PMCIA (UDM) MU-1126/AAR-57(V) (CMWS); RECEIVER/TRANSMITTER, RT-1477/ARC-201; CONTROL, C-11466A/ARC-201; KY-58(3EA); KY-58 CONTROL HEAD (3EA); KY-100 AIRTERM; ARC-220/						ACTION											
											PID		CAT		HRS		
ACFT HRS 6065.5		WHEN DISC W		HOW REC G		MAL EFF 1											
DELAY				WUC 00				TIPIID ,				TI MANHOURS					

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 10		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 02 Sep 20	NO	TIME 13:15	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS AIRCRAFT DEPANELED FOR INDUCTION INTO BEST PROGRAM. USED TM 1-1520-237-23&P, BEST SOW AND SES GOP AS A REFERENCE.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6065.5						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS X	SYS A	DATE 02 Sep 20	NO	TIME 13:16	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS MAIN ROTOR BLADES (4 EA) REMOVED FOR INDUCTION INTO BEST STORAGE PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 0790 AS A REFERENCE.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6065.5						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS X	SYS A	DATE 02 Sep 20	NO	TIME 14:09	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED STABILATOR FOR INDUCTION INTO BEST PROGRAM PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 0539.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6065.5						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 11		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 02 Sep 20	NO	TIME 14:20	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED TAIL ROTOR BLADES FOR INDUCTION INTO BEST STORAGE PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 0815, BEST SOW AND SES GOP AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
ACTION												
ACFT HRS 6065.5						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS X	SYS A	DATE 02 Sep 20	NO	TIME 14:39	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED COMMON MISSILE WARNING SYSTEM JUNCTION BOX (SN 01013) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 1915 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
ACTION												
ACFT HRS 6065.5						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS X	SYS A	DATE 02 Sep 20	NO	TIME 14:40	PID CRABB, ARLAN	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED COMMON MISSILE WARNING SYSTEM SAFETY SWITCH (SN 1003) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 1917 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
ACTION												
ACFT HRS 6065.5						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 12		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 02 Sep 20	NO	TIME 14:43	PID CRABB, ARLAN/	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED COMMON MISSILE WARNING SYSTEM RELAY BOX (SN 01013) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 1913 AS A REFERENCE.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6065.5						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS X	SYS A	DATE 02 Sep 20	NO	TIME 14:47	PID CRABB, ARLANA/	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED CARGO HOOK SQUIB (SN 0318) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 1504 AS A REFERENCE.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6065.5						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			
STATUS X	SYS A	DATE 02 Sep 20	NO	TIME 14:49	PID CRABB, ARLANA/	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED DOPPLER SDC ASN-128 (SN 3321) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4079.						ACTION						
						PID	CAT	HRS	PID	CAT	HRS	
ACFT HRS 6065.5						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 13		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS X	SYS A	DATE 02 Sep 20	NO	TIME 14:50	PID CRABB, ARLAN/	DATE	TIME	ACFT HRS				
FAULTS/REMARKS REMOVED DOPPLER RT/ANTENNA ASN-128 (SN 1711B) PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 4076 AS A REFERENCE.						ROUNDS	ACTION CODE	WUC				
ACTION												
ACFT HRS 6065.5						WHEN DISC E	HOW REC G	MAL EFF 1				
DELAY						WUC 00		TI MANHOURS				
STATUS X	SYS A	DATE 03 Sep 20	NO	TIME 00:01	PID Generated, Com	DATE	TIME	ACFT HRS				
FAULTS/REMARKS INSP A092 30 DAY SLAB BATTERY INSPECTION (D8565/11-1) FOR HCPTR UTILITY UH-60A CAGE: 78286 PN: UH-60A NSN: 1520010350266 SN: 7923282 WAS DUE. STATUS UPGRADED TO X ON: 02 SEP 2020 REFERENCE: TM 11-6140-203-23 P						ROUNDS	ACTION CODE	WUC				
ACTION												
ACFT HRS 6065.5						WHEN DISC O	HOW REC O	MAL EFF 1				
DELAY						WUC 00		TI MANHOURS				
STATUS —	SYS A	DATE 03 Sep 20	NO	TIME 15:22	PID BRIDGES, ROBEF	DATE	TIME	ACFT HRS				
FAULTS/REMARKS DURING THE BEST PROGRAM INDUCTION PROCEDURE, THE FOLLOWING COMPONENTS WERE UNABLE TO HAVE THE S/N'S VERIFIED. ALL OF THESE COMPONENTS HAVE BEEN S/N MATCHED AGAINST MCDS AND THE RECORDS MATCH BETWEEN ACN AND MCDS. THESE COMPONENTS REQUIRE S/N VERIFICATION AT THE NEXT MAJOR MAINT EVENT. R/H MLG LOWER PISTON, S/N: P00315; MAIN ROTOR NUT ASSY, S/N: MSG192591; MAIN ROTOR SPINDLE ASSY, S/N: 338963987; MAIN ROTOR BIFILAR ASSY, S/N: A345-034003; STATIONARY SWASHPLATE, S/N: FM00038; TAIL ROTOR PITCH CHANGE SHAFT, S/N: 233-04269.						ROUNDS	ACTION CODE	WUC				
ACTION												
ACFT HRS 6065.5						WHEN DISC E	HOW REC G	MAL EFF 2				
DELAY						WUC 00		TI MANHOURS				

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. AIRCRAFT SERIAL NUMBER 7923282				2. MODEL UH-60A			3. DATE			4. PAGE 14		
PART I - FAULT INFORMATION						PART II - CORRECTING INFORMATION						
STATUS —	SYS A	DATE 04 Sep 20	NO	TIME 11:03	PID BRIDGES, ROBEI	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS DUE TO INCONSISTENCIES BETWEEN ACN AND MCDS RECORDS, THE L/H OUTBOARD SERVO BEAM FITTING REQUIRES SERIAL NUMBER VERIFICATION AT NEXT MAJOR MAINTENANCE. SERIAL NUMBER IS CURRENTLY UNKNOWN.						ACTION						
												PID
ACFT HRS 6065.5		WHEN DISC E	HOW REC G	MAL EFF 2								
DELAY			WUC 00			TIPIID ,			TI MANHOURS			
STATUS	SYS	DATE	NO	TIME	PID	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS						ACTION						
												PID
ACFT HRS		WHEN DISC	HOW REC	MAL EFF								
DELAY			WUC			TIPIID			TI MANHOURS			
STATUS	SYS	DATE	NO	TIME	PID	DATE	TIME	ACFT HRS	ROUNDS	ACTION CODE	WUC	
FAULTS/REMARKS						ACTION						
												PID
ACFT HRS		WHEN DISC	HOW REC	MAL EFF								
DELAY			WUC			TIPIID			TI MANHOURS			

DA FORM 2408-13-1-SG, OCT 1997

DA FORM 2408-13-1, OCT 91, MAY BE USED

AIRCRAFT INSPECTION AND MAINTENANCE RECORD

For use of this form, see DA PAM 738-751; the proponent agency is DCSLOG

APD PE v3.00

1. STATUS /	2. SERIAL NUMBER 7923282	3. SYSTEM CODE A	4. TIME 14:27		
5. FAULT DATE 07 Aug 20		6. FAULT NUMBER			
7. FAULT REMOVAL OF PROPERTY BOOK ITEMS REQUIRED FOR ACFT TRANSFER TO BEST PROGRAM.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
/	RMVD HUD SDC				
/	RMVD HUD CONTROL PANEL.				
/	RMVD ALL COMPONENTS OF THE APR-39 RADAR DETECTING SET SUCH AS, RMVD DIGITAL				
/	RMVD DAGR.				
/	RMVD BOTH. ARC-201 RT'S, RMVD CONTROL HEAD, RMVD IFM AMPLIFIER				
/	RMVD KY-58 CONTROL HEADS (2EA), RMVD KY-58 RECEIVERS (2EA)				
/	RMVD LH CREW CHIEF ICS BOX, RMVD TROOP COMMAND ICS BOX AS WELL AS THE HAND HELD				
/	RMVD CMWS SAFE/ARM CONTROL PANEL.				
/	RMVD BFT SYSTEM SUCH AS, RMVD TRANSCEIVER, RMVD MICROROUTER, RMVD L-BAND ANTENNA,				
/	RMVD TDFM-9000 RADIO.				
/	RMVD THE FOLLOWING IVHMS COMPONENTS, RMVD IVHMU, RMVD REMOTE DATA				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 7923282	3. SYSTEM CODE A	4. TIME 13:16		
5. FAULT DATE 02 Sep 20		6. FAULT NUMBER			
7. FAULT MAIN ROTOR BLADES (4 EA) REMOVED FOR INDUCTION INTO BEST STORAGE PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 0790 AS A REFERENCE.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
—	ALL MAINT TO BE COMPLETED USING TM 1-1520-237-23&P WP 0790, SES GOP AND BEST				
×	REMOVED COTTER PINS (8 EA) FROM BLADE PINS PER CUSTOMER REQUEST. USED TM				
×	DISCONNECTED DE-ICE ELECTRICAL CONNECTORS (4 EA)				
×	DISCONNECTED ANTI-FLAP SPRINGS (4 EA)				
×	REMOVED BLADE PINS (8 EA)				
×	REMOVED MAIN ROTOR BLADES (4 EA) SN A007-13001, SN A007-13477, SN A007-02329, AND				
—	FOD CHECK REQUIRED				
—	TOOLBOX INVENTORY REQUIRED.				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 7923282	3. SYSTEM CODE A	4. TIME 14:09		
5. FAULT DATE 02 Sep 20		6. FAULT NUMBER			
7. FAULT REMOVED STABILATOR FOR INDUCTION INTO BEST PROGRAM PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 0539.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
—	ALL MAINT TO BE COMPLETED USING TM 1-1520-237-23&P WP 0539, BEST SOW AND SES GOP				
×	REMOVED COTTER PINS FROM STABILATOR ATTACHING HARDWARE (4 EA).				
×	REMOVED HARDWARE FROM STABILATOR GROUNDING STRAP.				
×	DISCONNECTED STABILATOR GROUNDING STRAP (2 EA).				
×	DISCONNECTED ELECTRICAL CONNECTOR FROM TAIL PYLON (2 EA)				
×	REMOVED HARDWARE FROM STAB LIMIT SWITCH.				
×	REMOVED HARDWARE FROM STAB ACTUATOR				
×	REMOVED HARDWARE FROM STAB HING FITTINGS (2 EA)				
×	REMOVED STABILATOR.				
—	FOD CHECK REQUIRED.				
—	TOOLBOX INVENTORY REQUIRED.				

DA FORM 2408-13-2-SG, OCT 97
 DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD
 For use of this form see DA PAM 738-751, the proponent agency is DCSLOG

1. STATUS ×	2. SERIAL NUMBER 7923282	3. SYSTEM CODE A	4. TIME 14:20		
	5. FAULT DATE 02 Sep 20	6. FAULT NUMBER			
7. FAULT REMOVED TAIL ROTOR BLADES FOR INDUCTION INTO BEST STORAGE PER CUSTOMER REQUEST. USED TM 1-1520-237-23&P WP 0815, BEST SOW AND SES GOP AS A REFERENCE.					
8. STA	9. RELATED MAINTENANCE ACTIONS	10. ACTION	11. PID	12. CAT	13. MMH
—	ALL WORK TO BE COMPLETED USING TM 1-1520-237-23&P WP 0815, BEST SOW AND SES				
×	REMOVED SAFETY FROM TAIL ROTOR PITCH BEAM RETAINING NUT				
×	REMOVED HARDWARE FROM TAIL ROTOR PITCH BEAM RETAINING NUT (2 EA)				
×	REMOVED TAIL ROTOR PITCH BEAM RETAINING NUT.				
×	REMOVED COTTER PINS FROM TAIL ROTOR PITCH CONTROL LINKS BLADE SIDE. (4 EA)				
×	REMOVED TAIL ROTOR PITCH BEAM				
×	REMOVED HARDWARE FROM PITCH BEAM LINKS ON BLADE SIDE (4 EA)				
×	DISCONNECTED DE-ICE ELECTRICAL CONNECTORS FROM TAIL ROTOR PADDLES (4 EA)				
×	REMOVED HARDWARE FROM OUTBOARD RETENTION PLATE (12 EA)				
×	REMOVED OUTBOARD RETENTION PLATE				
×	REMOVED TAIL ROTOR BLADE (2 EA) SN A009-04972 AND SN A009-09833.				
—	FOD CHECK REQUIRED.				
—	TOOLBOX INVENTORY REQUIRED.				

DA FORM 2408-13-2-SG, OCT 97

DA FORM 2408-13-2, NOV 91, MAY BE USED

RELATED MAINTENANCE ACTIONS RECORD

For use of this form see DA PAM 738-751, the proponent agency is DCSLOG