NK 2R2

(P)

MIDLANT BSVE MOTOR VEHICLE DESCRIPTION AND VEHICLE CHECKLIST

NOTE: Please fill in requested information as completely as possible. Place an (X) in the correct feature/description. MANDANTORY fields are indicated by (*) asterisks.

Vehicle Tag * 94-74196 (2R) Location/Site * SP233 NORFOLK NAVY BASE

IO# * _____ EC * 0345 Leased/Owned/Non Owned * NAVFAC

Odometer Reading * 64264 Hours _____ Acquisition Cost * _____

Manufacturer * Ford Model * utility VAN Ford

Year Mfg. * 2005 VIN * 1FCJE39L96HA19712

Pass Cap 2 Trans (Man/Auto) Auto # Doors 2FT/2BACK(4)

Color (Ext */Int) Green / _____ Fuel Type * GAS Fuel Cap _____ Cylinders _____

#Axles 2 Pickup Bed (narrow/wide) N/A Bed Length N/A GVWR * 9600LBS/4354KG

Body Style/Description BOX/good no damage

Installation Date _____ Acquisition Date * _____ In-Service Date * _____

Purchase Price: _____ Warranty Expiration Date/Miles: _____/_____

Warranty Expiration Date/Miles: _____/_____ MSA ☐ Yes ☐ No

Owning Activity * NAVFAC midlant (Little Creek) UIC _____

Activity POC (757) 636-4371 POC Work Phone ONLY _____

Secondary POC (757) 636-7164 POC Purchase Price: _____

☑ GSA ☐ Agency Owned ☐ Long Term Commercial Lease ☐ Short Term Rental

Operational Status: ☑ Oper ☐ Decom ☐ Pend ☐ Other : _____

Exemption ID * _____ Location Code * _____ Location Zip * _____ WC _____

Vehicle Specifications:

Purchase Contract Number:	RPN:
Engine Type:	Engine Serial Number:
Number of Cylinders:	Engine Size:
Battery Size (amp): 2	Transmission Type:
Auxiliary Engine Type:	Aux. Eng. Serial Number:
Aux. Eng. Power:	Aux. Eng. Cylinders:
Tire Size, Front: LT245/75R16	Tire Size, Rear: LT245/75R16
Ignition Code:	Lease Contract Number:

Please check/list any special features and accessories:

☐ 4x4	☐ AWD	☐ Dual Wheels	☐ Power Locks
☐ 4x6	☐ Extended Cab	☐ Towing Package	☐ Power Windows
☐ 6x6	☐ Crew Cab	☑ Utility Body	☐ Tire Chains

Please check/describe vehicle condition:

☐ A/C Inoperable	☐ Electrical Problems	☐ Headlights Inoperable	☐ Starter Bad-Won't Start
☑ Battery(s) Dead/Missing	☐ Exhaust System Problem	☐ Keys Missing	☐ Speedometer Inoperable
☑ Body Damage, Rust	☐ Fire Damage	☐ Parking Lights Inoperable	☐ Suspension Problems
☐ Brakes Worn	☐ Flood Damage	☐ Mechanical Problems	☐ Transmission Leak
☐ Dents, Minor	☐ Fuel Gauge Inoperable	☐ Minor Scratches	☐ Trans. Repairs Req.
☐ Engine Part(s) Required	☐ Interior Damaged	☐ Odometer Inoperable	☐ Visual Blemishes
☐ Engine Repairs Req.	☐ Hazard Lights Inoperable	☐ Oil Leaks	☐ Windshield Cracked
☐ Engine Smoke	☐ Horn Inoperable	☐ Radiator Leak	☐ Wipers Inoperable
☐ Axel Damage	☐ Frame Damage	☑ Tires(condition) good	

Jump Battery

Damage vent on pass side

FUSE BOX LID MISSING

Please Check Appropriate Condition Code:

☐ Code 1 = Excellent ☐ Code S = Scrap (Major mechanical or accidents repairs required.)

☑ Code 4 = Usable ☐ Code X = Salvage (Not to be "Titled" for highway use.)

☐ Code 7 = Repairable (Mechanical and/or accident repairs required)

Data Recorded By: [signature] Date: 12 FEB 11