NOTE: Please fill in requested information as completely as possible. Place an (X) in the correct feature/description. MANDANTORY fields are indicated by (*) asterisks.

MIDLANT BSVE MOTOR VEHICLE DESCRIPTION AND VEHICLE CHECKLIST

Vehicle Tag * N9471185 **Location/Site** * PWD CRANE

IO# * _____ **EC** * 0327-01 Leased/Owned/Non Owned * OWNED

Odometer Reading * 44035 Hours _____ Acquisition Cost * _____

Manufacturer * CHEVROLET Model * C2500 SILVERADO

Year Mfg. * 2003 VIN * 1GCHC23U63F225481

Pass Cap 5 Trans (Man/Auto) AUTO # Doors 4

Color (Ext */Int) WHITE / BROWN Fuel Type * GAS Fuel Cap _____ Cylinders 8

#Axles 2 Pickup Bed (narrow/wide) WIDE Bed Length 8' GVWR * 9200LB

Body Style/Description TRUCK CARGO PICKUP 8501 AND UP GVWR CREW CAB

Installation Date _____ Acquisition Date * _____ In-Service Date * _____

Purchase Price: _____ Warranty Expiration Date/Miles: _____/_____

Warranty Expiration Date/Miles: _____/_____ MSA ☐ Yes ☐ No

Owning Activity * PWD CRANE UIC N40085

Activity POC KEVIN FUHRMAN POC Work Phone ONLY 812-854-5557

Secondary POC HAROLD MCINTOSH POC Purchase Price: 812-854-3115

☐ GSA ☐ Agency Owned ☐ Long Term Commercial Lease ☐ Short Term Rental

Operational Status: ☐ Oper ☐ Decom ☐ Pend ☐ Other : _____

Exemption ID * _____ Location Code * _____ Location Zip * 47522 WC _____

Vehicle Specifications:

Purchase Contract Number:	RPN:
Engine Type:	Engine Serial Number:
Number of Cylinders:	Engine Size: 6.0L
Battery Size (amp):	Transmission Type:
Auxiliary Engine Type:	Aux. Eng. Serial Number:
Aux. Eng. Power:	Aux. Eng. Cylinders:
Tire Size, Front:	Tire Size, Rear:
Ignition Code:	Lease Contract Number:

Please check/list any special features and accessories:

☐ 4x4	☐ AWD	☐ Dual Wheels	☐ Power Locks
☐ 4x6	☐ Extended Cab	■ Towing Package	☐ Power Windows
☐ 6x6	■ Crew Cab	☐ Utility Body	☐ Tire Chains

Please check/describe vehicle condition:

☐ A/C Inoperable	☐ Electrical Problems	☐ Headlights Inoperable	☐ Starter Bad-Won't Start
☐ Battery(s) Dead/Missing	☐ Exhaust System Problem	☐ Keys Missing	☐ Speedometer Inoperable
■ Body Damage, Rust	☐ Fire Damage	☐ Parking Lights Inoperable	☐ Suspension Problems
☐ Brakes Worn	☐ Flood Damage	☐ Mechanical Problems	☐ Transmission Leak
■ Dents, Minor	☐ Fuel Gauge Inoperable	■ Minor Scratches	☐ Trans. Repairs Req.
☐ Engine Part(s) Required	☐ Interior Damaged	☐ Odometer Inoperable	☐ Visual Blemishes
☐ Engine Repairs Req.	☐ Hazard Lights Inoperable	☐ Oil Leaks	☐ Windshield Cracked
☐ Engine Smoke	☐ Horn Inoperable	☐ Radiator Leak	☐ Wipers Inoperable
☐ Axel Damage	☐ Frame Damage	☐ Tires(condition)	

Please Check Appropriate Condition Code:

☐ Code 1 = Excellent ☐ Code S = Scrap (Major mechanical or accidents repairs required.)

✓ Code 4 = Usable ☐ Code X = Salvage (Not to be "Titled" for highway use.)

☐ Code 7 = Repairable (Mechanical and/or accident repairs required)

Data Recorded By: _____ Date: _____

MIDLANT BSVE MOTOR VEHICLE DESCRIPTION AND VEHICLE CHECKLIST

(con't)

Add Additional Detailed Description/Condition Information:

VINYL SEATS AND FLOOR
4X2
TIRES 60%
STEP BARS RUSTED
2 LARGE DENTS IN DRIVERS SIDE BED
TAILGATE NOT ATTACHED
NO SPARE TIRE

MECHANICALLY SOUND

Data Recorded By: _____ Date: _____