

**Boat Inspection Photos - 85TR654 (Part 01)**




Photo 1: WRB-102 Bow Profile



Photo 2: WRB-102 Port Aft Profile



Photo 3: Port Deck



Photo 4: Stbd Deck



Photo 5: Transom




Photo 6: Antennas, Aft Control Station



Photo 7: Aft Control Station



Photo 8: Bow with Anchor Windlass




Photo 9: Anchor Windlass – Viewed Aft



Photo 10: Pilothouse



Photo 11: Pilothouse – Port



Photo 12: Bunk Room



Photo 13: Sink & Mirror



Photo 14: Head



Photo 15: Mess



Photo 16: Galley



Photo 17: Engineering Compartment – Viewed Forward



Photo 18: Engineering Compartment – Viewed Aft



Photo 19: Engine Room Compartment – Viewed aft



Photo 20: Port Main Engine



Photo 21: STBD Main Engine




Photo 22: STBD Generator




Photo 23: Port Generator



Photo 24: Boat Identification Information – 85TR654