

Stock: 30003280  
 Unit: G05-01228  
 Customer:  
 Lot:



Date: 07/08/2016 1:17 PM  
 Seller: GENERAL SERVICES  
 ADMINISTRATION/OFA #G93791  
 Phone/Fax: (0 ) -(0 ) -  
 Sale Date:

<b>Year</b> 2009	<b>Make</b> LINCOLN		<b>Model</b> NAVIGATOR L		<b>Body Type</b> SPORT UTILITY VEHI	<b>VIN</b> 5LMFL285X9EJ01228
<b>Drive</b> 4WD	<b>Ext Color</b> Black	<b>Int Color</b> Black	<b>Int Material</b> Leather		<b>Sound</b> Satellite	<b>Roof</b> Hardtop
<b>Fuel</b> E85	<b>Mileage</b> 105204	<b>Odo. Type</b> Digital	<b>Engine</b> 8-Cyl. 5.4Liters		<b>Transmission</b> Automatic	<b>Airbags</b> Dual
<b>Doors</b> 4	<b>License Plate</b> G05-01228		<b>License St</b>	<b>Plates</b>	<b>Plate Expires</b>	<b>End of Term</b>

- **Accessories:** Remote key, (1) Keyless entry, Homelink
- **Interior:** Seats, (8) Heated mirrors, Power mirrors, Child seat anchors, Adjustable pedals, Steering wheel controls, 3rd seat, (BENCH) Compass, Seat type 60/40, Heated seats, (DRIVER & PASSENGER) Rear air, Rear defroster, Memory seats, Equalizer, Power locks, Power roof, Power seats, Power windows, Cruise control, Tilt wheel, Rear entertainment system, (1) Owners manual, Odometer scale, (Miles) Steering wheel audio controls, Parking distance control, Woodgrain interior package, A/c seats, Safety restraint system, Dual air
- **Exterior:** Fog lights, Luggage rack, Chrome wheels, Spare tire, Sunroof, (Power Glass) Trailer hitch, Rear tail/lift gate, Power liftgate, Tinted windows (aftermarket)
- **Equipment:** Trip counter, Air conditioner, Antilock brake system, Power steering, Power brakes, Side air bags
- **Electronics:** Back up camera & screen, Dvd, Navigation system, Cd player, Tachometer, Voltmeter, Radio-satellite, Tv rear, Mp3 player, Trip computer, Traction control

**Notification:**

**Arrival:** 07/06/2016

**Visual:** 07/06/2016

**Body:** 07/06/2016

**Mechanical:** 07/06/2016

**Writer:** TT

**Complete:** 07/08/2016

**Revised:** 07/08/2016

**Driveable:** Yes

**Visual Frame**

**Damage:**

**Condition:** 2.5

<b>Tires</b>	<i>Left</i>	<i>Right</i>
<i>Front</i>	07/32in Goodyear 20	07/32in Goodyear 20
<i>Rear</i>	07/32in Goodyear 20	05/32in Goodyear 20
<i>Spare</i>		



**Announcements:**

**Notes:**

- L
- REVISED 7-8-16 AG

<b>Inspection Date</b>	<b>Description</b>	<b>Approved</b>	<b>Repaired</b>	<b>Material Estimate</b>	<b>Labor Hours</b>	<b>Labor Estimate</b>	<b>Paint Hours</b>	<b>Paint Estimate</b>	<b>Sublet Estimate</b>
<i>Chargeable</i>									
07/06/2016	Front bumper mult			50.00	0.00	0.00	0.00	0.00	0.00

	scratches/heavy - 1 - 3in. Touch Up.						
07/06/2016	Hood multiple chips - SCRATCH. Touch Up.	50.00	0.00	0.00	0.00	0.00	0.00
07/06/2016	Lf door scratch heavy - CHIPS\DENTS. 1 - 3in. Touch Up.	100.00	0.00	0.00	0.00	0.00	0.00
07/06/2016	Lf fender scratch heavy - CHIPS. 1 - 3in. Touch Up.	50.00	0.00	0.00	0.00	0.00	0.00
07/06/2016	Lr door dent/no paint dmg - SCRATCHES. 1 - 3in. Repair.	100.00	0.00	0.00	0.00	0.00	0.00
07/06/2016	L qtr panel scratch heavy - DENT. 1 - 3in. Touch Up.	100.00	0.00	0.00	0.00	0.00	0.00
07/06/2016	Rear bumper mult scratches/heavy - MISALIGNED. 9 - 12in. Refinish.	150.00	0.00	0.00	0.00	0.00	0.00
07/06/2016	Lift gate chipped - Touch Up.	50.00	0.00	0.00	0.00	0.00	0.00
07/06/2016	Rf door dent/no paint dmg - SCRATCHES. 1/2 To 1 Inch. Repair.	100.00	0.00	0.00	0.00	0.00	0.00
07/06/2016	Rf fender chipped - SCRATCHES. Touch Up.	50.00	0.00	0.00	0.00	0.00	0.00
07/06/2016	Rr door scratch heavy - 1 - 3in. Touch Up.	50.00	0.00	0.00	0.00	0.00	0.00
07/06/2016	R qtr panel mult scratches/heavy - CHIP/DENT. 1 - 3in. Touch Up.	100.00	0.00	0.00	0.00	0.00	0.00
	<i>Subtotal:</i>	\$950.00	0.00	\$0.00	0.00	\$0.00	\$0.00
<b>Deductible</b>							
	<i>Subtotal:</i>	\$0.00	0.00	\$0.00	0.00	\$0.00	\$0.00
<b>Nonchargeable</b>							
	<i>Subtotal:</i>	\$0.00	0.00	\$0.00	0.00	\$0.00	\$0.00
	Total Estimate:	\$950.00	0.00	\$0.00	0.00	\$0.00	\$0.00
<b>Grand Total:</b>							<b>\$950.00</b>

Charge Date	Description	Amount
-------------	-------------	--------

07/06/2016	Auto ims fee	
------------	--------------	--

07/06/2016	Pick-up charge	
------------	----------------	--



Odometer



Front right



Dash



Engine



Extra-photo



Interior front



Extra-photo



Wheel



Rear left



Rear bumper mult scratches/hea



Rear right



Extra-photo