

Aircraft Component Removal Report

Id Number	Serial Number	Model Type	Fuel Type	Location
4614N	550-0659	C550	JP	

Control Number	Nomenclature	Part Number	Serial Number	Install Date
' 040REG000	AIRCRAFT REGISTRATION	'N NUMBER	'	11/30/2017
' 050001-4	INSPECTION	'PHASE 1-4	'	2/15/2019
'		'	'	2/15/2019
' 050001CS	INSPECTION	'PHASE 1 SUPPLEMENT	'	2/15/2019
'		'	'	2/15/2019
' 050005	INSPECTION	'PHASE 5	'	9/27/2017
'		'	'	9/27/2017
' 050005S	INSPECTION	'PHASE 5 SUPPLEMENT	'	9/27/2017
'		'	'	9/27/2017
' 05000B	INSPECTION	'PHASE B	'	2/15/2019
' 054012	INSPECTION	'PHASE 12	'	12/2/2016
' 054014A	INSPECTION	'PHASE 14	'SUBSEQUENT	6/22/2006
' 054015A	INSPECTION	'PHASE 15	'	6/15/1991
' 054015B	INSPECTION	'PHASE 15	'	12/20/1994
' 054016A	INSPECTION	'PHASE 16	'	6/15/1991
' 054016B	INSPECTION	'PHASE 16	'	12/20/1994
' 054017	INSPECTION	'PHASE 17	'	6/15/1991
' 054018	INSPECTION	'PHASE 18	'	10/11/2018
' 054018A	RE-CERTIFY	'FIRST AID KIT	'	12/15/2017
' 054019A	INSPECTION	'PHASE 19	'	6/12/2006
' 054020H	OVERSPEED WARNING	'PHASE 20	'142	11/8/2018
'		'	'	11/8/2018
' 054020I	ESIS	'CERT/FAR 91.411	'2949	11/8/2018
' 054020J	VOR CHECK	'FAR 91.171	'MONTHLY	8/2/2019
' 054020K	RVSM REQUIREMENTS	'	'	3/28/2018
'		'	'	3/28/2018
' 054020X	C5000 ANNUAL TEST	'IN-SERVICE FUNCTION	'	9/26/2018
' 054022A	INSPECTION	'EMR BOT HYDRO TEST	'9262	12/1/2016
' 054025L	#1 ENGINE	'HOT SECTION	'PCE-JF0028	6/11/2007
' 054025R	#2 ENGINE	'HOT SECTION	'PCE-71517	1/13/2016
' 054030	ELT XMTR TEST	'FAR 91.207	'08134	10/9/2018
' 054034A	INSPECTION	'PORT FIRE EXT	'E93772475	6/12/2019
' 054034B	INSPECTION	'PORT FIRE EXT	'E-92812986	6/12/2019
' 054037	INSPECTION	'PHASE 37	'	3/3/2001
'			'WING SKIN	
' 054049A	INSPECTION	'PHASE 49	NDT	9/27/2017

'					9/27/2017
' 054060A	INSPECTION	'PHASE 60	'WING SPAR		9/27/2017
' 054H5100	INSPECTION	'UC5100	'2627		1/7/2019
' 0550030	INSPECTION	'CORROSION	'PART 1		8/23/2019
' 056I210	HEAT EXCHANGER	'CLEANING	'		9/27/2017
'		'	'		9/27/2017
' 056I270	INSPECTION	'TRIM ACTUATORS	'		9/27/2017
'		'	'		9/27/2017
' 059IC18A	ICA INSPECTION	'RADAR&MMS SYSTEM	'		8/26/2019
' 059IC18B	ICA INSPECTION	'RADAR&MMS SYSTEM	'		8/6/2019
' 059IC18E	ICA INSPECTION	'FLIR MOUNT	'		9/27/2017
'		'	'		9/27/2017
' 059IC18F	ICA INSPECTION	'NOSE RADOME	'		2/15/2019
'		'	'		2/15/2019
' 059IC34H	ICA INSPECTION	'EMERGENCY PWR SUPPLY	'84120		5/21/2019
' 059IC34I	ICA INSPECTION	'EMERGENCY PWR SUPPLY	'84120		5/21/2019
' 059ICA01	ICA INSPECTION	'TCAS BENDIX	'		9/26/2018
' 059ICA03	ICA INSPECTION	'DEFOG C/B REPLACEMNT	'		9/27/2017
'		'	'		9/27/2017
' 059ICA05	ICA INSPECTION	'BOOKCASE	'		9/7/2018
' 059ICA34	ICA INSPECTION	'NAVIGATION EQUIPMENT	'		2/17/2018
'		'	'		2/17/2018
' 059SD01	FRONT INNER BYPASS BONDED SKIN	'MAINT ADVISORY	'11-16-01		12/19/2018
' 059SD02	INSPECTION	'TASK 55-10-01-270	'		8/23/2019
' 059SDVS	VERT STAB NDT	'INSPECTION	'		2/15/2019
'		'	'		2/15/2019
' 122010	SERVICING	'COMP RINSE	'		8/18/2019
' 122014	SERVICING	'AIRCRAFT WASH	'		8/23/2019
' 122041A	INSPECTION	'#1 ENG OIL FILTER	'		2/15/2019
' 122042A	INSPECTION	'#2 ENG OIL FILTER	'		2/15/2019
' 215001	#1 ACM (UPPER)	'738384-26	'9706128		9/18/2012
' 215002	#2 ACM (LOWER)	'738384-26	'900880		10/7/2003
' 215041	FAN CABIN OVERHEAD	'BC61A-901-2	'1982A		5/14/2016
' 215042	FAN DEFOG	'5703-3	'1296		12/5/2003
' 243006	A/C BATTERY	'RG380E/44	'40942755		8/4/2019
'		'	'		8/4/2019
' 256008	ELT RE-REGISTER 406MHZ	'453-5060	'		6/20/2018
' 256009	RAFT ELT RE-REG 406MHZ	'2744NH	'7916		
' 256010	LIFE RAFT	'69FA-AV	'		

' 256021A	LIFE PRESERVER	'P0723E105P	'758302	
' 256022A	LIFE PRESERVER	'P0723E105P	'0920150	
' 256023A	LIFE PRESERVER	'P0723E105P	'541621	
' 256024A	LIFE PRESERVER	'P0723E105P	'41121	
' 256030	SURVIVAL KIT	'MILS43302	'C-10	3/28/2019
' 262001	#1 F/B SQUIB	'13083-5	'#1 FWD	9/1/2016
' 262001A	#1 F/B SQUIB	'13083-5	'#1 AFT	9/1/2016
' 262002	#2 F/B SQUIB	'13083-5	'#2 FWD	9/1/2016
' 262002A	#2 F/B SQUIB	'13083-5	'#2 AFT	9/1/2016
' 275011	#1 FLAP G/B	'5565175-38	'8-26-1	6/6/2013
' 275012	#2 FLAP G/B	'5565175-38	'T1	6/6/2013
' 312002	CLOCK BATT PILOT	'PC9100	'	9/26/2018
' 312002A	CLOCK BATT C-PILOT	'PC9100	'	12/29/2018
' 312002B	CLOCK BATT SENSOR	'PC9100	'	9/26/2018
' 324005A	ANTI-SKID HYD PMP MTR	'MP50B-1	'4005	8/7/2019
'		'	'	8/7/2019
' 34001DB	NAVIGATION	'DATABASE	'	8/12/2019
' 351106	OXY MASK INSP	'MF10-03-12	'	12/26/2018
' 351112	OXY HOOD SENSOR	'MR-10010N	'R1005642	
' 351112A	OXY HOOD SENSOR	'MR-10010N	'R1005642	
' 351113	OXY HOOD PASSENGER	'MR-10010N	'R1812100	
' 351113A	OXY HOOD PASSENGER	'MR-10010N	'R1812100	
' 712101	#1 ENG MOUNTS	'L-4200 SYSTEM	'N/A	6/11/2007
' 712102	#2 ENG MOUNTS	'L-4200 SYSTEM	'N/A	5/3/2005
'A720B01	#1 ENGINE	'JT15D-4	'PCE-JF0028	6/11/2007
'B720B02	#2 ENGINE	'JT15D-4	'PCE-71517	5/3/2005
'A801001B	L/H ST/GEN	'23080-025	'4984	6/17/2018
'B801002B	R/H ST/GEN	'23080-025	'7742	9/30/2018
' 99HCMD0110	CMD-C550-01-10	'TAILCONE STRUCTURE	'C/W	2/15/2019
'		'	'	2/15/2019
' 99HCMD0112	CMD-C550-01-12	'WING STRINGER CRACKS	'C/W	9/27/2017
'		'	'	9/27/2017
' 99HCMD0216	CMD-C550-02-16	'ENGINE INLET CRACK	'C/W	2/15/2019
'		'	'	2/15/2019
' 99HCMD0217	CMD-C550-02-17	'PRESSURIZATION PLUM	'C/W	9/1/2000
'		'	'	9/1/2000
' 99HCMD0318R1	CMD-C550-03-18R1	'THROTTLE CABLE LUBE	'C/W	9/27/2017
'		'	'	9/27/2017
' 99HCMD0421	CMD-C550-04-21	'INSP TEMP CONTROL	'C/W	9/27/2017
'		'	'	9/27/2017
' 99HCMD0423	CMD-C550-04-23	'NOSE GEAR DOOR RIG-	'C/W	2/15/2019
'		'	'	2/15/2019

' 99HCMD0624	CMD-C550-06-24	'EMERGENCY DOOR EXIT	'C/W	8/18/2019
' 99HCMD1826	CMD-C550-18-26	'ENG BYPASS DUCT INSP	'	2/15/2019

Life		
Hours	Life Landings	Life Cycles
9419.3	6540	1909

TY	INT	TBO	RMNG	Due
DY	120	1095	325	11/29/2020
HR	25	300	164.7	9584
DY	30		402	2/14/2021
HR	25	300	164.7	9584
DY	30		402	2/14/2021
HR	100	1200	742.7	10162
DY	30		261	9/26/2020
HR	25	1200	742.7	10162
DY	30		261	9/26/2020
HR	25	150	14.7	9434
HR	25	600	89.7	9509
HR	100	3000	1050.7	10470
HR	100	11250	1830.7	11250
HR	50	1000	2830.7	12250
HR	100	11250	1830.7	11250
HR	100	3000	4830.7	14250
HR	150	10000	580.7	10000
DY	14	365	-90	10/11/2019
DY	30	1095	340	12/14/2020
HR	100	2500	550.7	9970
DY	30	730	303	11/7/2020
HR	30		136.7	9556
DY	30	730	303	11/7/2020
DY	5	30	-130	9/1/2019
HR	100	1000	635.7	10055
DY	30		78	3/27/2020
DY	30	365	-105	9/26/2019
DY	30	1095	-39	12/1/2019
HR	100	1750	72.7	9492
HR	100	1750	1026.7	10446
DY	15	365	-92	10/9/2019
DY	7	180	-31	12/9/2019
DY	7	180	-31	12/9/2019
HR	100	5000	549.7	9969
HR	100	1200	742.7	10162

DY	30		261	9/26/2020
HR	100	1200	742.7	10162
DY	30	365	-2	1/7/2020
DY	10	30	-109	9/22/2019
HR	100	1200	742.7	10162
DY	30		261	9/26/2020
HR	100	1200	742.7	10162
DY	30		261	9/26/2020
DY	3	7	-129	9/2/2019
DY	7	30	-126	9/5/2019
HR	100	1200	742.7	10162
DY	30		261	9/26/2020
HR	25	300	164.7	9584
DY	30		402	2/14/2021
DY	15	180	-53	11/17/2019
DY	30	365	132	5/20/2020
DY	30	365	-105	9/26/2019
HR	100	1200	742.7	10162
DY	30		261	9/26/2020
DY	30	365	-124	9/7/2019
HR	100	1200	811.7	10231
DY	30		404	2/16/2021
HR	30	300	143.7	9563
DY	10	30	-109	9/22/2019
HR	25	300	164.7	9584
DY	30		217	8/13/2020
DY	7	30	-114	9/17/2019
DY	10	30	-109	9/22/2019
HR	30	200	64.7	9484
HR	30	200	64.7	9484
HR	100	5000	3831.7	13251
HR	100	5000	723.7	10143
HR	50	1000	397.7	9817
HR	50	3500	266.7	9686
HR	25	150	136.7	9556
DY	30		207	8/3/2020
DY	30	730	162	6/19/2020
DY	30	730	0	
DY	30	365	0	

DY	30	730	0	
DY	30	730	0	
DY	30	730	0	
DY	30	730	0	
DY	30	365	-107	9/24/2019
DY	30	1460	235	8/31/2020
DY	30	1460	235	8/31/2020
DY	30	1460	235	8/31/2020
DY	30	1460	235	8/31/2020
HR	100	3000	1935.7	11355
HR	100	3000	1935.7	11355
DY	30	365	-105	9/26/2019
DY	30	365	-11	12/29/2019
DY	30	365	-105	9/26/2019
HR	25	1500	1486.7	10906
LD	50		1693	8233
DY	5	28	-122	9/9/2019
DY	30	365	-14	12/26/2019
DY	30	3650	0	
DY	10	90	0	
DY	30	3650	0	
DY	10	90	0	
HR	100	3500	1822.7	11242
HR	100	3500	1048.7	10468
HR	100	3500	1823.3	3500
HR	100	3500	1052.8	3504
HR	100	1000	687.3	2364
HR	100	1000	756.8	3208
HR	25	300	164.7	9584
DY	30		402	2/14/2021
HR	25	1200	742.7	10162
DY	30		261	9/26/2020
HR	25	300	164.7	9584
DY	30		402	2/14/2021
HR	100	8400	748.7	10168
DY	30		231	8/27/2020
HR	25	1200	742.7	10162
DY	30		261	9/26/2020
HR	100	1200	742.7	10162
DY	30		261	9/26/2020
HR	25	300	164.7	9584
DY	30		402	2/14/2021

DY	30	180	36	2/14/2020
HR	25	150	14.7	9434