

N540DB
Eurocopter AS350-B2

Serial Number: 3218
Year: 1999
Airframe Total Time: 4558.1
Total Landings: 3405
Engine Total Time: 4558.1
Engine Total Cycles: 5184
Engine Total Time Since O/H: 1557.2, Total Time Since New: 4558.1
Gas Generator Module Time Since O/H: 1557.2, Total Time Since New: 4558.1
Free Turbine Assembly Module Total Time Since O/H: 1557.2, Total Time Since New: 4558.1
Axial Compressor Module Total Time Since O/H: 1557.2, Total Time Since New: 4558.1
Engine Accessory Gear Box Module Total Time Since O/H: 1557.2, Total Time Since New: 4558.1

#1 Main Rotor Blade Total Time Since New: 4558.1
#2 Main Rotor Blade Total Time Since New: 4558.1
#3 Main Rotor Blade Total Time Since New: 3633.8
Tail Rotor Blade Total Time Since New: 1557.6
Main Rotor Transmission Total Time Since New: 4558.1
Main Rotor Mast Total Time Since New: 4558.1
Tail Rotor Gearbox Total Time Since O/H: 1557.6

Avionics:

EFIS	Garmin	G500H System (Duel Panel)
Nav/Comm, 1ea.	Garmin	SL-40
Audio Panel	NAT	AMS-42
Transponder	Garmin	GTX-345R
Radar Altimeter	King	KRA-405B
GPS Navigation	Garmin	GTN-650 WAAS
AHRS	Garmin	GRS-77
Synthetic Vision System	Garmin	G500H SVY
TAS	Avidyne	TAS-600
Weather Detection	Garmin	GDL-69A
Standby Instruments	L-3 Avionics	ESI-2000
Fuel Flow Computer	Shaden	Digiflow
Digital Clock	Davtron	N811B
ELT	Artex	

Equipment:

Wire Strike Kit
High Skid Gear
Duel Flight Controls
Lead Acid Battery Upgrade
Air Conditioning
Aero Dymanix NVIS
Whelen LED Exterior Lighting
Aerofilter Engine Induction Barrier Air Filter System

This aircraft has been maintained under FAA Part 91 and Eurocopter's recommended inspection program. There are current aircraft logbooks dating back to aircraft factory new delivery. This aircraft was purchased new and has been owned and operated by the selling agency. This aircraft has a current Standard Airworthiness Certificate. There is no known major damage history and the paint is in very good condition and interior in good condition. The information provide in this summary is presumed to be accurate as of the date of this posting. It is highly recommended that a physical inspection of the aircraft and aircraft records be made before considering this aircraft. **This aircraft is offered as is with no warranties implied.**