Original CR

Metro Phoenix Auto Auction
2475 S. 59th Avenue
Phoenix, AZ 85043
602-279-9500
rernst@metroaa.com
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2006 FORD FUSION**
Bodystyle/Series:	**4 Door Sedan -**
Color:	**GRAY**
Mileage:	**93,402 (Verified, 6 digits)**
Turn-in Mileage:	**-**
VIN:	**3FAHP071X6R235548**
Work Order/ Stock Number:	**000467174**
Customer:	GSA Fleet Other Federal Agency 1800 F Street NW Room 3400 Washington, DC 20405 816-823-3358 linda.betlock@gsa.gov
Client Stock #:	**G09-35548**
Vehicle Grade	**Grade 2.0**
Remarks:	**-**
Announcements:	• AS IS:NO ARB ON FRM
Certification :	**Not Certified**
Req. Prev. Repair Order:	**-**

Drivable: Yes	Tire Rating: null	Incremental Recon: No

UniBody/Frame Damage: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**6-Cylinder Gas**	Cruise Control:	**Yes**
Engine Size:	**3 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**No**
Radio:	**AM/FM CD**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /Black**	Rear Defroster:	**No**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	**Power**	Drive Type:	**Front Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Additional Equipment:

Air Conditioning	Power Driver Seat	CD in Dash
Front Wheel Drive	Power Windows	Tilt Wheel

Power Steering	Cruise Control	

Non Chargeable Damages

Photo	Item	Damage	Comments	Parts	Labor	Labor Hours	Paint Hours	Estimate	Action	Severity
	Photo - Rear	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
[no photo]	Photo - Wheel	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Interior	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Right	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Rear	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Extra Photo 1	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Right	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
[no photo]	Photo - Interior	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Left	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
				$0.00 (total)	**$0.00 (total)**	**0 (total)**	**0 (total)**	**$0.00 (total)**		

Chargeable Damages

Photo	Item	Damage	Comments	Parts	Labor	Labor Hours	Paint Hours	Estimate	Action	Severity

	Front Bumper	Light Scratch	-	$0.00	$300.00	0	0	$300.00	Report	0
	Left Front Door	Light Scratch	-	$0.00	$300.00	0	0	$300.00	Report	0
	Left Rear Door	Light Scratch	-	$0.00	$300.00	0	0	$300.00	Report	0
	Rear Bumper	Light Scratch	-	$0.00	$300.00	0	0	$300.00	Report	0
	Deck Lid	Heavy Scratch	-	$0.00	$350.00	0	0	$350.00	Report	0
[no photo]	Right Rear Door	Ding	-	$0.00	$55.00	0	0	$55.00	Report	0
				$0.00 (total)	**$1,605.00 (total)**	**0 (total)**	**0 (total)**	**$1,605.00 (total)**		

File Insurance Claim? No

Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.