Original CR

Metro Phoenix Auto Auction
2475 S. 59th Avenue
Phoenix, AZ 85043
602-279-9500
remst@metroaa.com
WHOLESALE ASSESSMENT ONLY

Make/Model:	**2010 FORD FUSION BAS**
Bodystyle/Series:	**4 Door Sedan BAS**
Color:	**WHITE**
Mileage:	**74,340 (Verified, 6 digits)**
Turn-in Mileage:	**-**
VIN:	**3FADP0L3XAR396674**
Work Order/ Stock Number:	**000484099**
Customer:	GSA Fleet Vehicle Sales 1800 F Street NW Room 3400 Washington, DC 20405 816-823-3358 linda.betlock@gsa.gov
Client Stock #:	**G106987K**
Vehicle Grade	**Grade 3.0**
Remarks:	**-**
Announcements:	**-**
Certification :	**Not Certified**
Req. Prev. Repair Order:	**-**

Drivable: Yes	Tire Rating: null	Incremental Recon: No

UniBody/Frame Damage: NO

Equipment

Transmission:	**Automatic Transmission**	A/C:	**Yes**
Engine:	**4-Cylinder Hybrid**	Cruise Control:	**Yes**
Engine Size:	**2.5 L**	Pwr Steering:	**Yes**
Roof:	**Hard Top**	Pwr Locks:	**Yes**
Radio:	**AM/FM CD**	Pwr Windows	**Yes**
Interior - Type/Color:	**Cloth Interior /Gray**	Rear Defroster:	**Yes**
Airbag:	**Dual Air Bags**	Tilt Steering:	**Yes**
Seats:	**Power**	Drive Type:	**Front Wheel Drive**
Seat Count:	**0**	Brakes:	**Power Brakes**

Additional Equipment:

Air Conditioning	LF Tires - 6/32 inch	RF Tires - 6/32 inch
LR Tires - 6/32 inch	RR Tires - 6/32 inch	Car Tire Size - LR SIDE TIRE SIZE 17

Car Tire Size - RR SIDE TIRE SIZE 17	Car Tire Size - LF SIDE TIRE SIZE 17	Car Tire Size - RF SIDE TIRE SIZE 17
Power Driver Seat	Tire Brand - Front Left - LF SIDE TIRE MFG Falken Falken	Tire Brand - Front Right - RF SIDE TIRE MFG Falken Falken
Tire Brand - Rear Left - LR SIDE TIRE MFG Falken Falken	Tire Brand - Rear Right - RR SIDE TIRE MFG Falken Falken	Power Mirrors
CD in Dash	Front Wheel Drive	Power Windows
Power Lock	Tilt Wheel	Power Steering
Cruise Control		

Non Chargeable Damages

Photo	Item	Damage	Comments	Parts	Labor	Labor Hours	Paint Hours	Estimate	Action	Severity
	Photo - Rear	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Wheel	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Interior	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Overall Picture - Odometer	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Right	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Rear	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Extra Photo 1	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Right	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown

	Photo - Interior	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
	Photo - Left	Photo Only	-	$0.00	$0.00	0	0	$0.00	Estimate Only	Unknown
				$0.00 (total)	**$0.00 (total)**	**0 (total)**	**0 (total)**	**$0.00 (total)**		

Chargeable Damages

Photo	Item	Damage	Comments	Parts	Labor	Labor Hours	Paint Hours	Estimate	Action	Severity
[no photo]	Front Bumper	Chipped	PAINT	$0.00	$175.00	0	0	$175.00	Report	0
[no photo]	Hood	Chipped	TOUCHUP	$0.00	$65.00	0	0	$65.00	Report	0
[no photo]	Left Front Door	Dents W/No Pt. Dmg.	-	$0.00	$135.00	0	0	$135.00	Report	0
[no photo]	Left Rear Door	Dents W/No Pt. Dmg.	-	$0.00	$65.00	0	0	$65.00	Report	0
[no photo]	Rear Bumper	Chipped	PAINT	$0.00	$175.00	0	0	$175.00	Report	0
				$0.00 (total)	**$615.00 (total)**	**0 (total)**	**0 (total)**	**$615.00 (total)**		

File Insurance Claim? No

Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.