



Metro Phoenix Auto Auction  
2475 S. 59th Avenue  
Phoenix, AZ 85043  
602-279-9500  
remst@metroaa.com  
WHOLESALE ASSESSMENT ONLY

Make/Model: **2007 FORD F150 XLT**  
Bodystyle/Series: **4 Door Vehicle XLT**  
Color: **WHITE**  
Mileage: **70,833 (Verified, 6 digits)**  
Turn-in Mileage: **-**  
VIN: **1FTPW12V97KC70189**  
Work Order/ Stock Number: **000634151**



Customer: GSA Fleet Vehicle Sales  
1800 F Street NW  
Room 3400  
Washington, DC 20405  
417-276-3475  
linda.betlock@gsa.gov

Client Stock #: **421213F**  
Vehicle Grade : **Grade 3.0**  
Remarks: **-**  
Announcements: **-**  
Certification : **Not Certified**  
Req. Prev. **-**  
Repair Order: **-**

Drivable: Yes	Tire Rating: null	Incremental Recon: No
---------------	-------------------	-----------------------

UniBody/Frame Damage: NO

### Equipment

Transmission:	<b>Automatic Transmission</b>	A/C:	<b>Yes</b>
Engine:	<b>8-Cylinder Flex Fuel</b>	Cruise Control:	<b>Yes</b>
Engine Size:	<b>5.4 L</b>	Pwr Steering:	<b>Yes</b>
Roof:	<b>Hard Top</b>	Pwr Locks:	<b>No</b>
Radio:	<b>AM/FM CD</b>	Pwr Windows	<b>Yes</b>
Interior - Type/Color:	<b>Cloth Interior /Gray</b>	Rear Defroster:	<b>No</b>
Airbag:	<b>Dual Air Bags</b>	Tilt Steering:	<b>Yes</b>
Seats:	<b>-</b>	Drive Type:	<b>Rear Wheel Drive</b>
Seat Count:	<b>0</b>	Brakes:	<b>Power Brakes</b>

### Additional Equipment:

Air Conditioning	LF Tires - 8/32 inch	RF Tires - 8/32 inch
LR Tires - 8/32 inch	RR Tires - 8/32 inch	Car Tire Size - LF SIDE TIRE SIZE 17

Car Tire Size - LR SIDE TIRE SIZE 17	Car Tire Size - RR SIDE TIRE SIZE 17	Car Tire Size - RF SIDE TIRE SIZE 17
Tire Brand - Front Left - LF SIDE TIRE MFG Firestone	Tire Brand - Front Right - RF SIDE TIRE MFG Firestone	Tire Brand - Rear Left - LR SIDE TIRE MFG Firestone
Tire Brand - Rear Right - RR SIDE TIRE MFG Firestone	Two-Wheel Drive	CD in Dash
Power Windows	Tilt Wheel	Power Steering
Cruise Control		

### Non Chargeable Damages

Photo	Item	Damage	Comments	Parts	Labor	Labor Hours	Paint Hours	Estimate	Action	Severity
	Photo - Left	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Photo - Rear	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Photo - Rear	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Photo - Right	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Photo - Right	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
[no photo]	Photo - Wheel	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Photo - Interior	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
[no photo]	Photo - Interior	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Extra Photo 1	Photo Only	-	\$0.00	\$0.00	0	0	\$0.00	Estimate Only	Unknown
	Overall	Photo							Estimate	

	Picture - Odometer	Only	-	\$0.00	\$0.00	0	0	\$0.00	Only	Unknown
				\$0.00 (total)	\$0.00 (total)	0 (total)	0 (total)	\$0.00 (total)		

### Chargeable Damages

Photo	Item	Damage	Comments	Parts	Labor	Labor Hours	Paint Hours	Estimate	Action	Severity
	Windshield	Cracked	-	\$0.00	\$280.00	0	0	\$280.00	Report	Unknown
	Inside Bed	Heavy Scratch	NEEDS BEDLINER	\$0.00	\$140.50	0	0	\$140.50	Install	Unknown
				\$0.00 (total)	\$420.50 (total)	0 (total)	0 (total)	\$420.50 (total)		

File Insurance Claim? No

Additional Damages and Remarks: -

DISCLAIMER. THIS CONDITION REPORT IS FOR INFORMATIONAL PURPOSES ONLY AND IS BASED ON INFORMATION PROVIDED BY THE SELLER. THIS CONDITION REPORT IS NEITHER INTENDED, NOR SHOULD IT BE CONSTRUED TO CONSTITUTE, ANY TYPE OF WARRANTY, WHETHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OF MERCHANTABILITY, AND ANY SUCH WARRANTY, WHETHER ARISING BY OPERATION OF LAW OR OTHERWISE, IS HEREBY DISCLAIMED. ANY REPUBLISHING OF THIS CONDITION REPORT SHALL CONTAIN THIS DISCLAIMER.