Stock #: 81053
Unit #: G61-0708G
Customer:
Location:

CONDITION REPORT

Dealers AUTO AUCTION Of Alaska

Date: 06/29/2015 11:51 am
Seller: General Services Administr #G020
Phone/Fax: (907) 271-4007/(907) 271-3971

Year	Make	Model	Body Type	Doors	VIN
2008	FORD	RANGER	PICKUP	2	1FTYR11U88PA95023

Drive	Ext Color	Int Color	Int Material	EOT	Lic. Plate	State	# of	Expires
4x4	Gray	Black	Cloth		G61-0708G		0	

Odometer			Engine		Transmission	Sound	Roof	Airbags
23785	6 digit		**6** Cyl. 3.0L	Gas	Auto	w/CD	Hard	Dual

Equipment: Power Steering, Power Brakes, Air Conditioner.

Electronics: Cd Player.

Notification:

Arrival: 06/29/2015

Visual: 06/29/2015, Jeremy

Body: 06/29/2015, Jeremy

Mechanical: 06/29/2015, Jeremy

CR Writer: Jeremy

CR Completed: 06/29/2015, Jeremy

Driveable: Yes

Visual Frame Damage: No

General Condition: Average

Tires:	Left	Right
Front		
Rear		
Spare		

Announcements:

Notes:

Inspection Date	Condition Description	Approved	Repaired	Material Estimate	Labor Hours	Labor Estimate	Paint Hours	Paint Estimate	Sublet Estimate
06/29/2015	Lr Side Panel Dents	/ /	/ /	0.00	0.00	0.00	0.00	0.00	0.00
06/29/2015	Rear Truck Bed Photo Only	/ /	/ /	0.00	0.00	0.00	0.00	0.00	0.00
06/29/2015	Rear Tailgate Dents	/ /	/ /	0.00	0.00	0.00	0.00	0.00	0.00
06/29/2015	Rr Side Panel Dents	/ /	/ /	0.00	0.00	0.00	0.00	0.00	0.00
06/29/2015	Int Front Seat - Lf Hole	/ /	/ /	0.00	0.00	0.00	0.00	0.00	0.00
			Total Estimate:	$0.00	Hr: 0.00	$0.00	Hr: 0.00	$0.00	$0.00
			Grand Total:						$0.00

Charge Date	Description	Amount
	Total Charges:	$ 0.00

Pictures Left Side

Pictures Right Side

Pictures Rear

Pictures Odometer



Pictures Interior

Rear Truck Bed Photo Only

Rear Tailgate Dents

Int Front Seat - Lf Hole

Rr Side Panel Dents



Lr Side Panel Dents