Stock #: 80188
Unit #: G63-2311H
Customer:
Location:

CONDITION REPORT

Dealers AUTO AUCTION Of Alaska

Date: 06/26/2015 01:24 pm
Seller: General Services Administr #G020
Phone/Fax: (907) 271-4007/(907) 271-3971

Year	Make	Model	Body Type	Doors	VIN
2009	CHEVRO	K2500	WAGON 4 DOOR	4	1GNGK46K09R263856

Drive	Ext Color	Int Color	Int Material	EOT	Lic. Plate	State	# of	Expires
4x4	Silver	Gray	Cloth		G63-2311H		0	

Odometer			Engine		Transmission	Sound	Roof	Airbags
66654	6 digit		**8** Cyl. 6.0L	Gas	Auto	w/CD	Hard	Dual

Option: Power Locks, 3rd Seat, Power Mirrors.
Interior: Power Windows, Power Seats, Cruise Control, Tilt Wheel.
Equipment: Air Conditioner, Power Steering, Power Brakes.
Electronics: Cd Player.

Notification:
Arrival: 06/26/2015
Visual: 06/26/2015, Rod
Body: 06/26/2015, Rod
Mechanical: 06/26/2015, Rod
CR Writer: Rod
CR Completed: 06/26/2015, Rod

Driveable: Yes
Visual Frame Damage: No
General Condition: Average

Tires:	Left	Right
Front		
Rear		
Spare		

Announcements:

Notes:

Inspection Date	Condition Description	Approved	Repaired	Material Estimate	Labor Hours	Labor Estimate	Paint Hours	Paint Estimate	Sublet Estimate
06/26/2015	Front Bumper Light Scratch	/ /	/ /	0.00	0.00	0.00	0.00	0.00	0.00
06/26/2015	Rr Side Panel Dent	/ /	/ /	0.00	0.00	0.00	0.00	0.00	0.00
			Total Estimate:	$0.00	Hr: 0.00	$0.00	Hr: 0.00	$0.00	$0.00
			Grand Total:						$0.00

Charge Date	Description	Amount
	Total Charges:	$ 0.00

Pictures Left Side

Pictures Right Side

Pictures Rear

Pictures Odometer

Pictures Interior

Front Bumper Light Scratch

Rr Side Panel Dent