**Stock #:** 81224
**Unit #:** G63-2314H
**Customer:**
**Location:**

# *CONDITION REPORT*

Dealers AUTO AUCTION Of Alaska

**Date:** 07/30/2015 04:36 pm
**Seller:** General Services Administr #G020
**Phone/Fax:** (907) 271-4007/(907) 271-3971

| Year | Make | Model | Body Type | Doors | VIN |
|---|---|---|---|---|---|
| 2009 | CHEVRO | SILVERADO K2500HD | PICKUP | 2 | 1GBHK44659E153867 |

| Drive | Ext Color | Int Color | Int Material | EOT | Lic. Plate | State | # of | Expires |
|---|---|---|---|---|---|---|---|---|
| 4x4 | Blue | Gray | Vinyl | | G63-2314H | | 0 | |

| Odometer | | | Engine | | Transmission | Sound | Roof | Airbags |
|---|---|---|---|---|---|---|---|---|
| 33532 | 6 digit | | **8** Cyl. 6.6L | Diesel | Auto | w/CD | Hard | Dual |

**Equipment:** Air Conditioner, Power Steering, Power Brakes.
**Electronics:** Cd Player.

**Interior:** Tilt Wheel.

**Notification:**
**Arrival:** 07/30/2015
**Visual:** 07/30/2015, Rod
**Body:** 07/30/2015, Rod
**Mechanical:** 07/30/2015, Rod
**CR Writer:** Rod
**CR Completed:** 07/30/2015, Rod

**Driveable:** Yes
**Visual Frame Damage:** No
**General Condition:** Average

| Tires: | Left | Right |
|---|---|---|
| Front | | |
| Rear | | |
| Spare | | |

**Announcements:**

**Notes:**

| Inspection Date | Condition Description | Approved | Repaired | Material Estimate | Labor Hours | Labor Estimate | Paint Hours | Paint Estimate | Sublet Estimate |
|---|---|---|---|---|---|---|---|---|---|
| | | | Total Estimate: | $0.00 | Hr: 0.00 | $0.00 | Hr: 0.00 | $0.00 | $0.00 |
| | | | Grand Total: | | | | | | $0.00 |

| Charge Date | Description | Amount |
|---|---|---|
| | Total Charges: | $ 0.00 |

Pictures Left Side

Pictures Right Side

Pictures Rear

Pictures Odometer

Pictures Interior