Stock #: 83901
Unit #: G11-0734L
Customer:
Location:

CONDITION REPORT

Dealers AUTOAUCTION Of Alaska

Date: 12/01/2015 02:48 pm
Seller: General Services Administr #G020
Phone/Fax: (907) 271-4007/(907) 271-3971

Year	Make	Model	Body Type	Doors	VIN
2012	CHEVRO	IMPALA	SEDAN 4 DOOR	4	2G1WD5E30C1157110

Drive	Ext Color	Int Color	Int Material	EOT	Lic. Plate	State	# of	Expires
Front	White	Green	Cloth		G11-0734L		0	

Odometer			Engine		Transmission	Sound	Roof	Airbags
68510	Digital		**6** Cyl. 3.6L	Gas	Auto	w/CD	Hard	Dual

Option: Power Locks.
Interior: Power Windows, Power Seats, Cruise Control, Tilt Wheel.
Equipment: Air Conditioner, Power Steering, Power Brakes.
Electronics: Cd Player.

Notification:
Arrival: 12/01/2015
Visual: 12/01/2015, Justin
Body: 12/01/2015, Justin
Mechanical: 12/01/2015, Justin
CR Writer: Justin
CR Completed: 12/01/2015, Justin

Driveable: Yes
Visual Frame Damage: No
General Condition: Average

Tires:	Left	Right
Front		
Rear		
Spare		

Announcements:

Notes:

Inspection Date	Condition Description	Approved	Repaired	Material Estimate	Labor Hours	Labor Estimate	Paint Hours	Paint Estimate	Sublet Estimate
12/01/2015	Front Bumper Damaged	/ /	/ /	0.00	0.00	0.00	0.00	0.00	0.00
12/01/2015	Front Grille Broken	/ /	/ /	0.00	0.00	0.00	0.00	0.00	0.00
12/01/2015	Lf Side Mirror Cracked	/ /	/ /	0.00	0.00	0.00	0.00	0.00	0.00
12/01/2015	Top Roof Hole FILLED	/ /	/ /	0.00	0.00	0.00	0.00	0.00	0.00
12/01/2015	Int Front Seat - Lf Torn	/ /	/ /	0.00	0.00	0.00	0.00	0.00	0.00
			Total Estimate:	$0.00	Hr: 0.00	$0.00	Hr: 0.00	$0.00	$0.00
			Grand Total:						$0.00

Charge Date	Description	Amount
	Total Charges:	$ 0.00

Pictures Left Side

Pictures Right Side

Pictures Rr Qtr Panel

Pictures Rear

Pictures Lr Qtr Panel



Pictures Odometer



Pictures Interior



Pictures Rear Interior



Top Roof Hole



Front Bumper Damaged

Lf Side Mirror Cracked

Int Front Seat - Lf Torn

Front Grille Broken