

2008 Ford F250SD No Trim Badge

VIN: 1FTSW21578ED91028

Inv#: 6524

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
 4	Seats	Broken	Multiple Instances						--
Comment: Plastic Cover Broken For Driver Seat									
 5	Seats	Torn	Multiple Instances						--

Interior Subtotal

--	--	--	--	--	--
		--	--	--	--

Left

 6	Left Bed Side	Dents W/ Paint Dmg	Multiple Instances						--
 7	Left Front Door	Dents W/ Paint Dmg	Multiple Instances						--

Left Subtotal

--	--	--	--	--	--
		--	--	--	--

Mechanical

8	Emissions	Unknown Replace	Visible On Close Inspection						--
Comment: Catalytic Converter, Inop. Estimate To Replace									
9	Engine	Checked - Ok	None						--
10	Transfer Case 4x4	Checked - Ok	None						--
11	Transmission	Checked - Ok	None						--

Mechanical Subtotal

--	--	--	--	--	--
		--	--	--	--

Rear

 12	Tailgate	Dents W/ Paint Dmg	Multiple Instances						--
---	----------	--------------------	--------------------	--	--	--	--	--	----

Rear Subtotal

--	--	--	--	--	--
		--	--	--	--

Right

 13	Right Bed Side	Dents W/ Paint Dmg	Multiple Instances						--
 14	Right Front Door	Dents W/ Paint Dmg	Multiple Instances						--

2008 Ford F250SD No Trim Badge

VIN: 1FTSW21578ED91028

Inv#: 6524

Right Subtotal

--	--	--	--	--	--
		--	--	--	--

Structural

15 Center Cross Member Dent

Other

--

--

Structural Subtotal

--	--	--	--	--	--
		--	--	--	--

Total

--	--	--	--	--	--
		--	--	--	--

Tires

Region	Brand	Size	Tread Depth
Left Front	MATCHED	/-	Average (Average)
Left Rear	MATCHED	/-	Average (Average)
Right Front	MATCHED	/-	Average (Average)
Right Rear	MATCHED	/-	Average (Average)

Miscellaneous

Interior odor

OK

Images



2008 Ford F250SD No Trim Badge

VIN: 1FTSW21578ED91028

Inv#: 6524



2008 Ford F250SD No Trim Badge

VIN: 1FTSW21578ED91028

Inv#: 6524

