

Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.
Wood Village, OR 97060
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

Vehicle Description

2007 Chevrolet Tahoe 4WD 4D SUV 4WD LS 5.3L

VIN	1GNFK13017R400961		
Ext. Color	Gray		
Int. Color	Gray	Interior	Cloth
Mileage	81,802 Actual Miles		
Engine	5.3L 8-Cylinder Gas		
Transmission	Auto w/Overdrive		



Auction Data

Sale Date	Mon - Feb 8 - Open to the Public		
Run #	W045	Inv #	9013
Consignor	GSA FLEET SERVICES		

Declarations

Warranty	GSA Regular Terms
Mileage	81,802 Actual Miles
Title	Clear Title
Announcements	TPMS LIGHT ON

Equipment

- 4 Wheel Drive
- Automatic w/ Overdrive
- 8 Cylinder Gas
- Air Conditioning
- No Third Row Seat
- Power Trunk
- Electronic Traction Control
- Power Windows
- Power Locks
- Trip Counter
- Cruise Control
- Dual Air Bag
- Dual Air Thermostats
- Anti Lock Brakes
- Tilt Steering Wheel
- Steel Wheels
- AM/FM CD
- Keyless Entry
- Running Boards
- Towing Package
- Hard Top
- Tinted Windows
- Rear Wiper
- Rear Defog
- Power Steering
- Power Brakes
- Electric Mirrors

Damage Descriptions (CR completed on 1/5/2016 by SKYLAR FICKLIN)

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
1	Front Bumper/Cover	Collision Damage	Multiple Instances	--	--	--	--	--	--
Subtotal				--	--	--	--	--	--

2007 Chevrolet Tahoe 4WD 4D SUV 4WD LS 5.3L

VIN: 1GNFK13017R400961

Inv#: 9013

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
Front									
2	Hood	Chips	Visible On Close Inspection						--
									--
			Front Subtotal	--	--	--	--	--	--
						--	--	--	--
Interior									
3	Carpets	Dirty	Multiple Instances						--
									--
4	Headlining	Stained	Multiple Instances						--
									--
			Interior Subtotal	--	--	--	--	--	--
						--	--	--	--
Left									
5	Exterior Left	Checked - Ok	None						--
									--
			Left Subtotal	--	--	--	--	--	--
						--	--	--	--
Mechanical									
6	Engine	Checked - Ok	None						--
									--
7	Engine	Light On							--
									--
Comment: Tpms Light On									
8	Transfer Case 4x4	Checked - Ok	None						--
									--
9	Transmission	Checked - Ok	None						--
									--
			Mechanical Subtotal	--	--	--	--	--	--
						--	--	--	--
Rear									
10	Rear Bumper/Cover	Scraped	Multiple Instances						--
									--
			Rear Subtotal	--	--	--	--	--	--
						--	--	--	--

2007 Chevrolet Tahoe 4WD 4D SUV 4WD LS 5.3L

VIN: 1GNFK13017R400961

Inv#: 9013

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
---	----------	---------------	----------	----------	----------	--------------	-------------	------------	-------

Right

11	Exterior Right	Checked - Ok	None						--
----	----------------	--------------	------	--	--	--	--	--	----

Right Subtotal

--	--	--	--	--	--
--	--	--	--	--	--

Structural

12	Frame	Checked - Ok	None						--
----	-------	--------------	------	--	--	--	--	--	----

Structural Subtotal

--	--	--	--	--	--
--	--	--	--	--	--

Total

--	--	--	--	--	--
--	--	--	--	--	--

Tires

Region	Brand	Size	Tread Depth
Left Front	MATCHED	/-	Average (Average)
Left Rear	MATCHED	/-	Average (Average)
Right Front	MATCHED	/-	Average (Average)
Right Rear	MATCHED	/-	Average (Average)
Spare	MATCHED	/-	Good (Good)

Miscellaneous

Coolant level	OK
Fuel level	1/4
Interior odor	OK
Oil level	OK
Transmission fluid level	OK

2007 Chevrolet Tahoe 4WD 4D SUV 4WD LS 5.3L

VIN: 1GNFK13017R400961

Inv#: 9013

Images

