

Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.
Wood Village, OR 97060
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

Vehicle Description

2009 Chevrolet Suburban 4WD Flex 4D SUV 4WD 1500 LS

VIN	1GNFK163X9R231290		
Ext. Color	Gray		
Int. Color	Black	Interior	Vinyl
Mileage	84,979 Actual Miles		
Engine	5.3L 8-Cylinder Gas		
Transmission	Automatic		



Auction Data

Sale Date	Mon - Feb 8 - Open to the Public		
Run #	W048	Inv #	7658
Consignor	GSA FLEET SERVICES		

Declarations

Warranty	GSA Regular Terms
Mileage	84,979 Actual Miles
Title	Clear Title
Announcements	CROSS MEMBER DMG

Equipment

- 4 Wheel Drive
- No Third Row Seat
- Trip Counter
- Anti Lock Brakes
- Hard Top
- Power Steering
- Automatic Transmission
- Electronic Traction Control
- Cruise Control
- Tilt Steering Wheel
- Rear Defog
- Power Brakes
- 8 Cylinder Gas
- Power Windows
- Dual Air Bag
- Steel Wheels
- Rear Wiper
- Electric Mirrors
- Air Conditioning
- Power Locks
- Dual Air Thermostats
- AM/FM CD
- Tinted Windows

Damage Descriptions (CR completed on 12/17/2015 by Ryan Heath)

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
Front									
1	Hood	Chipped	10 Or More						--
				Front Subtotal					
				--	--	--	--	--	--
Left									
2	Left Front Door	Multiple Scratches	10 Or More						--

2009 Chevrolet Suburban 4WD Flex 4D SUV 4WD 1500 LS 5.3L

VIN: 1GNFK163X9R231290

Inv#: 7658

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
3	Left Front Fender	Multiple Scratches	10 Or More						--

Left Subtotal

--	--	--	--	--
		--	--	--

Rear

4	Rear Bumper	Chips	Multiple Instances						--
---	-------------	-------	--------------------	--	--	--	--	--	----

Rear Subtotal

--	--	--	--	--
		--	--	--

Right



5	Right Front Door	Dents W/No Pt. Dmg.	> 12 Inches						--
---	------------------	---------------------	-------------	--	--	--	--	--	----



6	Right Qtr Panel	Dents W/No Pt. Dmg.	Multiple Instances						--
---	-----------------	---------------------	--------------------	--	--	--	--	--	----



7	Right Rear Door	Dents W/No Pt. Dmg.	> 12 Inches						--
---	-----------------	---------------------	-------------	--	--	--	--	--	----

Right Subtotal

--	--	--	--	--
		--	--	--

Structural

8	Rear Cross Member	Dent	Other						--
---	-------------------	------	-------	--	--	--	--	--	----

Structural Subtotal

--	--	--	--	--
		--	--	--

Total

--	--	--	--	--
		--	--	--

Tires

Region	Brand	Size	Tread Depth
Left Front	MATCHED	/-	Average (Average)
Left Rear	MATCHED	/-	Average (Average)
Right Front	MATCHED	/-	Average (Average)
Right Rear	MATCHED	/-	Average (Average)

Miscellaneous

Interior odor OK

2009 Chevrolet Suburban 4WD Flex 4D SUV 4WD 1500 LS 5.3L

VIN: 1GNFK163X9R231290

Inv#: 7658

Images

