

# Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.  
Wood Village, OR 97060  
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

## Vehicle Description

2009 Chevrolet Suburban 4WD Flex 4D SUV 4WD 1500 LS

VIN	1GNFK16309R231427		
Ext. Color	Gray		
Int. Color	Black	Interior	Vinyl
Mileage	75,203 Actual Miles		
Engine	5.3L 8-Cylinder Gas		
Transmission	Automatic		



## Auction Data

Sale Date	Mon - Feb 8 - <a href="#">Open to the Public</a>		
Run #	W049	Inv #	7659
Consignor	GSA FLEET SERVICES		

## Declarations

Warranty	<a href="#">GSA Regular Terms</a>
Mileage	75,203 Actual Miles
Title	Clear Title
Announcements	CROSS MEMBER DMG

## Equipment

- 4 Wheel Drive
- No Third Row Seat
- Trip Counter
- Dual Air Thermostats
- Trailer Hitch
- Tinted Windows
- Automatic Transmission
- Electronic Traction Control
- Cruise Control
- Tilt Steering Wheel
- Hard Top
- Power Steering
- 8 Cylinder Gas
- Power Windows
- Dual Air Bag
- Steel Wheels
- Rear Defog
- Power Brakes
- Air Conditioning
- Power Locks
- Anti Lock Brakes
- AM/FM CD
- Rear Wiper
- Electric Mirrors

## Damage Descriptions (CR completed on 12/17/2015 by Ryan Heath)

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
<b>Front</b>									
1	Front Bumper	Dents W/No Pt. Dmg.	> 12 Inches						--
2	Hood	Dents W/ Paint Dmg	1 To 2 Inches						--

Front Subtotal

--	--	--	--	--	--
----	----	----	----	----	----

# 2009 Chevrolet Suburban 4WD Flex 4D SUV 4WD 1500 LS 5.3L

VIN: 1GNFK16309R231427

Inv#: 7659

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
---	----------	---------------	----------	----------	----------	--------------	-------------	------------	-------

## Left

3	Left Front Fender	Dents W/No Pt. Dmg.	1 To 2 Inches						--
---	-------------------	---------------------	---------------	--	--	--	--	--	----

### Left Subtotal

--	--	--	--	--
--	--	--	--	--

## Rear



4	Rear Bumper	Cracked	> 12 Inches						--
---	-------------	---------	-------------	--	--	--	--	--	----

### Rear Subtotal

--	--	--	--	--
--	--	--	--	--

## Right



5	Right Qtr Panel	Dents W/ Paint Dmg	2 To 3 Inches						--
---	-----------------	--------------------	---------------	--	--	--	--	--	----

### Right Subtotal

--	--	--	--	--
--	--	--	--	--

## Structural

6	Rear Cross Member	Dent	Other						--
---	-------------------	------	-------	--	--	--	--	--	----

### Structural Subtotal

--	--	--	--	--
--	--	--	--	--

### Total

--	--	--	--	--
--	--	--	--	--

## Tires

Region	Brand	Size	Tread Depth
Left Front	MATCHED	/-	Average (Average)
Left Rear	MATCHED	/-	Average (Average)
Right Front	MATCHED	/-	Average (Average)
Right Rear	MATCHED	/-	Average (Average)

## Miscellaneous

Interior odor OK

# 2009 Chevrolet Suburban 4WD Flex 4D SUV 4WD 1500 LS 5.3L

VIN: 1GNFK16309R231427

Inv#: 7659

## Images

