

# Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.  
Wood Village, OR 97060  
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

## Vehicle Description

2008 Chevrolet Silverado 2500 No Trim Badge

|              |                     |          |         |
|--------------|---------------------|----------|---------|
| VIN          | 1GBHK23K28F223241   |          |         |
| Ext. Color   | Gray                |          |         |
| Int. Color   | Gray                | Interior | Leather |
| Mileage      | 91,868 Actual Miles |          |         |
| Engine       | 6.0L 8-Cylinder Gas |          |         |
| Transmission | Automatic           |          |         |



## Auction Data

|           |  |       |      |
|-----------|--|-------|------|
| Sale Date | Mon - Feb 8 - <a href="#">Open to the Public</a> |       |      |
| Run #     | W051   | Inv # | 9189 |
| Consignor | GSA FLEET SERVICES                               |       |      |

## Declarations

|          |                                   |
|----------|-----------------------------------|
| Warranty | <a href="#">GSA Regular Terms</a> |
| Mileage  | 91,868 Actual Miles               |
| Title    | Clear Title                       |

## Equipment

- 4 Wheel Drive
- 6 Passenger
- Alloy Wheels
- Hard Top
- Automatic Transmission
- Power Locks
- Tilt Steering Wheel
- Power Steering
- 8 Cylinder Gas
- Trip Counter
- AM/FM CD
- Power Brakes
- Air Conditioning
- Dual Air Bag
- Step Bumper

## Damage Descriptions (CR completed on 1/5/2016 by LUIS MEJIA)

| #                     | Location       | Damage Action | Severity           | Parts \$ | Other \$ | Repair hours | Paint hours | Part hours | Total |
|-----------------------|----------------|---------------|--------------------|----------|----------|--------------|-------------|------------|-------|
| <b>Front</b>          |                |               |                    |          |          |              |             |            |       |
| 1                     | Front Bumper   | Chipped       | Multiple Instances |          |          |              |             |            | --    |
| 2                     | Hood           | Chipped       | Multiple Instances |          |          |              |             |            | --    |
| <b>Front Subtotal</b> |                |               |                    | --       | --       | --           | --          | --         | --    |
| <b>Interior</b>       |                |               |                    |          |          |              |             |            |       |
| 3                     | Steering Wheel | Worn          | Acceptable         |          |          |              |             |            | --    |

# 2008 Chevrolet Silverado 2500 No Trim Badge

VIN: 1GBHK23K28F223241

Inv#: 9189

**Interior Subtotal**

|    |    |    |    |    |    |
|----|----|----|----|----|----|
| -- | -- | -- | -- | -- | -- |
|    |    | -- | -- | -- | -- |

**Left**

|   |                       |      |            |  |    |
|---|-----------------------|------|------------|--|----|
| 4 | Left Front Door Panel | Worn | Acceptable |  | -- |
|   |                       |      |            |  | -- |

**Left Subtotal**

|    |    |    |    |    |    |
|----|----|----|----|----|----|
| -- | -- | -- | -- | -- | -- |
|    |    | -- | -- | -- | -- |

**Rear**

|   |             |                     |                    |  |    |
|---|-------------|---------------------|--------------------|--|----|
| 5 | Rear Bumper | Dents W/No Pt. Dmg. | Multiple Instances |  | -- |
|   |             |                     |                    |  | -- |

|   |           |               |                    |  |    |
|---|-----------|---------------|--------------------|--|----|
| 6 | Rear Door | Light Scratch | Multiple Instances |  | -- |
|   |           |               |                    |  | -- |

**Rear Subtotal**

|    |    |    |    |    |    |
|----|----|----|----|----|----|
| -- | -- | -- | -- | -- | -- |
|    |    | -- | -- | -- | -- |

**Right**

|   |                |               |                    |  |    |
|---|----------------|---------------|--------------------|--|----|
| 7 | Right Bed Side | Light Scratch | Multiple Instances |  | -- |
|   |                |               |                    |  | -- |

|   |                   |               |                    |  |    |
|---|-------------------|---------------|--------------------|--|----|
| 8 | Right Pillar Post | Light Scratch | Multiple Instances |  | -- |
|   |                   |               |                    |  | -- |

**Right Subtotal**

|    |    |    |    |    |    |
|----|----|----|----|----|----|
| -- | -- | -- | -- | -- | -- |
|    |    | -- | -- | -- | -- |

**Total**

|    |    |    |    |    |    |
|----|----|----|----|----|----|
| -- | -- | -- | -- | -- | -- |
|    |    | -- | -- | -- | -- |

**Tires**

| Region      | Brand   | Size | Tread Depth       |
|-------------|---------|------|-------------------|
| Left Front  | MATCHED | /-   | Average (Average) |
| Left Rear   | MATCHED | /-   | Average (Average) |
| Right Front | MATCHED | /-   | Average (Average) |
| Right Rear  | MATCHED | /-   | Average (Average) |
| Spare       | FACTORY | /-   | Average (Average) |

**Miscellaneous**

|                                 |    |
|---------------------------------|----|
| <b>Coolant level</b>            | OK |
| <b>Interior odor</b>            | OK |
| <b>Oil level</b>                | OK |
| <b>Transmission fluid level</b> | OK |

# 2008 Chevrolet Silverado 2500 No Trim Badge

VIN: 1GBHK23K28F223241

Inv#: 9189

## Images

