

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

**Vehicle Description**

2009 Chevrolet Silverado 3500 No Trim Badge

VIN	1GBHK79K49E149042		
Ext. Color	White		
Int. Color	Gray	Interior	Leather
Mileage	72,079 Actual Miles		
Engine	6.0L 8-Cylinder Gas		
Transmission	Automatic		



**Auction Data**

Sale Date	Mon - Feb 8 - <a href="#">Open to the Public</a>		
Run #	W053	Inv #	8276
Consignor	GSA FLEET SERVICES		

**Declarations**

Warranty	<a href="#">GSA Regular Terms</a>
Mileage	72,079 Actual Miles
Title	Clear Title
Announcements	OIL/FLUID LEAK

**Equipment**

- 4 Wheel Drive
- 6 Passenger
- Dual Air Bag
- Hard Top
- Automatic Transmission
- Utility Bed
- Alloy Wheels
- Power Steering
- 8 Cylinder Gas
- Trip Counter
- Tilt Steering Wheel
- Power Brakes
- Air Conditioning
- Cruise Control
- AM/FM CD

**Damage Descriptions** (CR completed on 12/29/2015 by LUIS MEJIA)

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
<b>Front</b>									
1	Front Bumper	Chipped	Multiple Instances						--
2	Hood	Chipped	Multiple Instances						--
<b>Front Subtotal</b>				--	--	--	--	--	--

**Interior**

	3	Right Rear Seat	Torn	Multiple Instances					--
--	---	-----------------	------	--------------------	--	--	--	--	----

# 2009 Chevrolet Silverado 3500 No Trim Badge

VIN: 1GBHK79K49E149042

Inv#: 8276

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
4	Steering Wheel	Worn	Acceptable						--
<b>Interior Subtotal</b>				--	--	--	--	--	--
<b>Left Subtotal</b>				--	--	--	--	--	--
<b>Left</b>									
5	Left Bed Side	Light Scratch	Multiple Instances						--
6	Left Front Door	Light Scratch	Multiple Instances						--
7	Left Front Door Panel	Scratched	Multiple Instances						--
8	Left Front Fender	Light Scratch	Multiple Instances						--
<b>Left Subtotal</b>				--	--	--	--	--	--
<b>Mechanical</b>									
9	Engine	Leak Check and Advise	Unknown						--
<b>Mechanical Subtotal</b>				--	--	--	--	--	--
<b>Right</b>									
10	Right Bed Side	Light Scratch	Multiple Instances						--
11	Right Front Door	Light Scratch	Multiple Instances						--
12	Right Front Fender	Light Scratch	Multiple Instances						--
<b>Right Subtotal</b>				--	--	--	--	--	--
<b>Total</b>				--	--	--	--	--	--

<b>Tires</b>			
Region	Brand	Size	Tread Depth
Left Front	MATCHED	/-	Average (Average)
Left Rear	MATCHED	/-	Average (Average)

# 2009 Chevrolet Silverado 3500 No Trim Badge

VIN: 1GBHK79K49E149042

Inv#: 8276

Right Front	MATCHED	/-	Average (Average)
Right Rear	MATCHED	/-	Average (Average)
Spare	FACTORY	/-	Average (Average)

## Miscellaneous

Coolant level	OK
Interior odor	OK
Oil level	Low
Transmission fluid level	OK

## Images



## 2009 Chevrolet Silverado 3500 No Trim Badge

VIN: 1GBHK79K49E149042

Inv#: 8276

---

